

A

ABERDEEN CHEMICAL PLANT
ROUTINE CHEMICAL DOSIMETRY SUMMARY

MONTH OF: June, 1981

DATE OF REPORT: July 1, 1981

c: CLM, CRM, PEM, JRM, RDJ, TBD, SJV, RAF, RAM, AHS
T. G. Grumbles - Houston, O. D. Steffey - Ponca City


ALL SAMPLE RESULTS:

<u>Chemical</u>	<u>< PEL</u>		<u>≥ PEL OVEREXPOSURES</u>	
	<u>No.</u>	<u>%</u>	<u>No.</u>	<u>%</u>
VCM	75	95	4	5
Lead	12	100	0	0
Antimony	12	100	0	0
Total Particulates	3	100	0	0

OVEREXPOSURES:

<u>Job Class</u>	<u>Exposure</u>	<u>Source</u>
Reactor Operator	1.4 ppm VCM	Dump Sweco exhauster out of service.
Dryer Operator	2.0 ppm VCM	Specific cause not identified.
Reactor Operator	2.1 ppm VCM	Specific cause not identified.
General Mechanic	3.7 ppm VCM	Repaired caustic pump in old vinyl area. Specific cause not identified.

NONE OF THE FOUR PEOPLE WERE USING RESPIRATORY PROTECTION.


Jerald Uptain

VAB.0001073486

ABERDEEN CHEMICAL PLANT CHEMICAL DOSIMETRY TRENDS

% <
PEL

100

VCM

0

100

Lead

0

100

Antimony

0

100

Total
Particulates

0

Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	Oct.	Nov.	Dec.	Jan.	Feb.	Mar.	Apr.	May	June	July	Aug.	Sept.	Oct.	Nov.	Dec.
19 80												19 81												19 82											