



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 1
5 POST OFFICE SQUARE, SUITE 100
BOSTON, MA 02109-3912

VIA EMAIL

David Haddad
Blackstone Reserve
DJ Development, 107 Windham Road,
Derry, NH 03038
david@djlandscaping.com

Subject: September 8, 2021, EPA Inspection

Dear Mr. Haddad:

On September 8, 2021, the U.S. Environmental Protection Agency ("EPA") performed an inspection at Blackstone Reserve. A copy of the inspection report is included as an attachment to this letter.

Specific comments, informed by the inspection, are as follows:

- An erosion channel was forming leading down to the west side of the dirt road running north of the houses.
- Stockpiles near the northwest basins were not stabilized.
- Stockpiles along the south side of the site were overtopping the boundary silt fence.

Please provide a response to these comments, including photographs documenting that the issues have been addressed, to the following technical contact:

Andrew Spejewski
Mail Code: 04
5 Post Office Sq - Suite 100
Boston, MA 02109-3912
(617) 918-1014
Spejewski.andrew@epa.gov

Sincerely,

**ANDREW
SPEJEWSKI**

Andrew Spejewski
Enforcement Officer
Water Compliance Section
Enforcement and Compliance Assurance Division

Digitally signed by
ANDREW SPEJEWSKI
Date: 2021.11.22 14:11:53
-05'00'

Enclosures:

Inspection Report for September 8, 2021, EPA Inspection
Contact Sheets of photos

CCs (electronic only):

David Haddad
ATTORNEYNAME, US EPA
Andrew Spejewski, US EPA