

October 26, 1971

O. D. SHREVE
MARSHALL LAB.

HEAVY METAL ANALYSIS

Please give me an estimate of the cost of analyzing materials for trace amounts of mercury, lead, arsenic, chromium, cadmium and chlorinated biphenyls. All analyses should be sensitive to about 1 ppm. What would be the "per metal" cost to add additional metals to this list?

WILLIAM W. MILLER
TOXICITY & POLLUTION CONTROL COORDINATOR

WWM/ps

N38424