

10/7/82
(DATE)K2335
(LOT)3839* LBS.
(EST WT)

COMTYP JOB NAME: 01YE735DMK

BLENDED BACK: CG 01, PQ 98,

(CODE)

(LBT)

(POUNDS)

EQUIP MENT	NAME: MOLYBDATE ORANGE	USE LBS	N-CODE	ACCT LBS
PREP	1 OBTAIN FOR S-34	315	4-A	315
1	2 OBTAIN FOR S-23	42	108-A	42
	3 OBTAIN FOR S-38	105	3-A	105
	4 OBTAIN FOR S-40	58	32-D	58
	5 OBTAIN FOR S-43	47	3-A	47
	6 DISSOLVE IN 30 G WATER AT 100-120°F IN DRUM FOR S-47	17	765-A	17
	7 DISSOLVE IN 30 G WATER AT 100-120°F IN DRUM FOR S-51	60	994-A	60

351	8	WEIGH IN	OPTR _____, MK 236, 37.98 %	37.98	10-D	1407
2			OPTR _____, MK _____, _____ %			

359	9	WEIGH IN.	OPTR _____, MK 59, T-360, 33.85 %	7.44	423-D	252
3			OPTR _____, MK _____, T- _____, _____ %			

SV	10	FLUSH DISTRIBUTOR LINES UNTIL WATER COMES OUT ALL JETS RECORD: OK (OK)				
4	11	RUN IN 40" (1992 G) WATER				
	12	RUN IN FROM V-354. OPTR 126, MK Meter 110' *F 200 gal		41-D	3800	
		PH 2.1 (2.8-3.7) G/ML 1337 (1.270-1.328) 281 gal				
		3.358 #/GAL, SEE SUPV IF NOT IN RANGE.				
	13	ADJ TO 3294 GAL AT 67-69°F. RECORD: 68 *F 2640		57-A	2640	
		(67° IN V-240 & 246; 69° IN V-241, 242, 245)				
	14	STIR 5 MIN. & RECORD: PH 2.4 (2.8-3.6)				
	15	IF NECESSARY, ADJ. TO PH 3.8-3.9 ASSUME 32% & RECORD: PH 3.85 (3.8-3.9) ASSUME 50%		28-D		
		NOTE: DILUTE N-7-D 10:1 WITH WATER BEFORE ADDING		7-D		
	16	RECORD: 7.1218 G/ML (1.117-1.118)				
		NOTE: IF G/ML OUT OF LIMITS, FILL OUT CHECK LIST & ATTACH				
	17	STIR AT 67-69°F FOR S-28. TAKE 1 QT SAMPLE.				

358	18	RUN 2" (110 G) WATER INTO V-358				
5	19	RUN V-359 INTO V-351				
	20	PUMP V-351 INTO V-358				
	21	TURN ON AGITATOR				
	22	SIFT IN N-108-A FROM S-2				
	23	ADJUST TO 68' (3216 G) AT 67-69°F RECORD: 68 *F				
	24	STIR 3 MIN. & RECORD: PH 10.5 (9.0-9.5)				
	25	IF NECESSARY, ADJ. TO PH 9.0-9.5 ASSUME 32% & RECORD: PH 9.0 ASSUME 50%		28-D		
	26	RECORD: G/ML 1.059 (1.059-1.060)		7-D		
		NOTE: G/ML OUT OF LIMITS FILL OUT CHECK LIST & ATTACH				
	27	STIR AT 67-69°F FOR S-28. TAKE 1 QT SAMPLE.				

OCT 11 1982

E C

