

ABD00342712

CONOCO CHEMICALS – ABERDEEN PVC PLANT
DOSIMETRY CARD (A)

SAMPLE No 1179

A

Hazard: VCM (✓) Lead () Noise () () Date 10/18/80

Name Doug Sparr S. S. # 418/66/3073 Shift A

Department Vinyl Job Class Chief Lead

Instrument No. 472R		Start	Stop
Time 640	AM () PM (✓)	705	AM () PM ()
Noise Cell No.	Airflow		

Analyst: J. Grace Analysis Date: 10-30-80

Hazard		TWA Exposure
VCM	PEL: 1 PPM	0.1 PPM
Noise	Over () Under () 115 dBA	% of PEL
Lead (Micrograms)	TOT: PEL: Per M ³	Per M ³

ABD00342713

CONOCO CHEMICALS - ABERDEEN PVC PLANT
DOSIMETRY DATA CARD (B)

SAMPLE No 1179

Hazard: VCM (✓) Lead () Noise () () Date 10/18/80 ^A

Time Clock (Lead Sampling Only) : IN: 640 AM () PM (✓) OUT: 0700 AM (X) PM ()

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

Area	Time	Area	Time
Rx's			
Dryers			

List most likely causes of possible overexposure to the hazard.

1. Recovery Systems
- 2.
- 3.

Check respiratory protection you used:

(X) None () Dust Mask (X) Air-line Respirator () Scott Air-pak

Signature

Douglas Sparr

Please complete and return to guard