

**PLAINTIFF'S
EXHIBIT**

GPR-50

October 3, 1961

Geo. P. Reintjes Co., Inc.
2513-19 Jefferson St.
Kansas City 41, Mo.

Attention: Mr. J. B. Stanley

Subject: No. 4 Open Hearth Rebuild
Suspended Uptakes
Wheeling Steel Order No. 115896

(File 9-A-45)

Gentlemen:

This letter confirms our receiving your letter dated September 28, 1961 and marked prints showing necessary alterations required to refractory supporting steel in the uptakes.

Your marked prints give location horizontally for refractory supporting steel marks L7, L8, L11, H5, H6 and H11. We have noted that marks L7, L8 and H5 have been relocated vertically with no dimensions given. It appears as though L7, L8 and H5 have been moved downward 3". We also note that arrangement of L7 and H5 has been changed.

Your forwarding to us as soon as possible detailed information on alterations for refractory supporting steel, will be appreciated. More detailed information is necessary for us to revise our drawings accordingly for field alterations, fabrication and installation.

Yours very truly,

STEAMERVILLE WORKS

H. R. Ford
H. R. Ford
Chief Plant Engineer

JB: pr

cc: L-M
GFW
EAC
DES
RKH

02131.008