

GIST MEETING

FEB. 27, 2003

Update: Monthly Reports
Model Report
Summary Report

* Satisfy Mvco? - Today's Objective

Risk/Exposure: What is the maximum air/dw concentration - daily dose. Screen data against it?

Overall Recommendations:

- Letart
- Permit Monitoring

Comments on Report:

- Man Site gw flow - needs to be qualified with "DuPont & GE Pumping"
- Offsite gw migration - there will be some if DuPont West well field is turned off.
- No comment on upstream PWS sources for C-8 (i.e. BelPre)
- No comment/observation Re. Letart as being source for C-8 in downstream PWS.

► FMG Background Studies:

- Background Ohio Samples: Send shuttle to OEPA - 2 samples at 2 PWS - alluvial aquifer
- Air Deposition
 - Need LHA Invest. to confirm air deposition conceptual model. Soil samples at Lubeck.

ASH027994

EID781274

EID781274

WV 2-Mile Radius

Make similar recommendations as OEPA in their section.

WV PWS

Recommend continued quarterly sampling at Lubeck, GE and DuPont.

Landfills

- Continue C-8 monitoring according to permit conditions. Surface water same.
- Continue SW points required by consent order (vs permits)

** Did Steve Williams get a copy of GW Modeling report? Check distribution.

Next report iteration

- 2-3 weeks