

No 001879

ABERDEEN CHEMICAL PLANT—DOSIMETRY RECORD

Name L. E. Frye Shift B^(D) Date 3-18-96Social Security No. 416-74-1049 Job Code Gen Mach

Instrument No. <u>2540</u>	Start Time <u>0700</u> AM(X) PM()	Stop Time <u>1530</u> AM() PM()
Airflow _____		

	HAZARD	SAMPLE CONCENTRATION (Time Weighted Average)	Sample Time _____
☒	VCM	<u>0.1</u> - PPM	
☐	Lead	-Micrograms/M ³	PEL: -Micrograms/M ³
☐	Total Dust	-Milligrams/M ³	
☐			
☐			

Analyst [Signature]
Analysis Date 3/19/96

Hazard: VCM () Lead () Dust () _____ ()

1. I came to work at 0700 AM () PM ()2. I left work at 1520 AM () PM ()

Firewatch Work?
Yes / No (Circle One)

3. I did the regular work of a (enter Job Class) Maintenance A


4. I used a respirator during the following jobs (check one)

	None ⁰	Dust Mask	Air-Line Resp.	Scott Air-Pak	3 M Air Hat
_____	☒	☐	☐	☐	☐
_____	☐	☐	☐	☐	☐
_____	☐	☐	☐	☐	☐

5. The following unusual events may have caused me to be overexposed:

6. Other comments and information (Use reverse side of card)

Signature



Please complete and return to Guard