

FILE NAME: Superior Combustion Industries (SCI)

DATE: 1972 Feb 23

DOC#: SCI012

DOCUMENT DESCRIPTION: Field Activity Report

200-227 *File*

REGION II - Erie  
PROD. MFG. OR SERVICE \_\_\_\_\_  
Boller  
DATE OF ACTIVITY 2/23/78

FIELD ACTIVITY REPORT  
(Occupational Health)

|                                                |                                         |                               |                                                                            |
|------------------------------------------------|-----------------------------------------|-------------------------------|----------------------------------------------------------------------------|
| PLANT<br><u>Superior Combustion Industries</u> |                                         |                               |                                                                            |
| ADDRESS<br><u>Frederick &amp; Blackman</u>     |                                         | ZIP CODE<br><u>16701</u>      | TELEPHONE<br><u>717 871-0127</u>                                           |
| PERSON INTERVIEWED<br><u>Bill Sieden</u>       |                                         | TITLE<br><u>Plant Manager</u> |                                                                            |
| EMPLOYEES                                      | MALE                                    | FEMALE                        | TOTAL                                                                      |
|                                                |                                         |                               | <u>100</u>                                                                 |
|                                                |                                         |                               | IND. CODE<br><u>34</u>                                                     |
|                                                |                                         |                               | COUNTY<br><u>LD</u>                                                        |
| PUNCH CARD                                     | YES <input checked="" type="checkbox"/> | NO <input type="checkbox"/>   | FOLDER YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> |
|                                                |                                         |                               | N.S.N. YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> |

PURPOSE: INVEST, SURVEY, INSPEL, PRELIM, FOL, CONF, VISIT, OTHER \_\_\_\_\_

REASON: SELF INIT, P.D. REF, COMPL, REQUEST, SOURCE \_\_\_\_\_

SAMPLES COLLECTED \_\_\_\_\_ TOTAL \_\_\_\_\_

(NO. & KIND)

DETERM. MADE \_\_\_\_\_ TOTAL \_\_\_\_\_

(NO. & KIND)

MEDICAL - O.C. REPORTED, NO. & KIND \_\_\_\_\_

RECOMMENDATIONS AND REMARKS

| SPECIFIC HAZARD OR CONDITION | WORKERS EXPOSED | RECOMMENDATIONS |        | ACCOMPLISHED |    |          |
|------------------------------|-----------------|-----------------|--------|--------------|----|----------|
|                              |                 | WRITTEN         | VERBAL | YES          | NO | IN PROG. |

Weld Fumes (Inert) 10 Local Exhaust Ventilation I

Have installed fan and most duct work. Have to install a few more elbows and purchase some flexible tubing. I consider this compliance.

Had Federal OSHA inspection within last two weeks. Had few citations and a small fine. Federal inspection says they are way ahead of average shop in compliance

PA STATE ARCHIVES

300 North Street, Harrisburg, PA 17120-0000  
By: Frederick & Mueser Consultants

BY Paul Gronka WINS 1.5

☐ OVER

RIN *[Signature]*

*File*  
 Superior Combustion Industries Corp.  
 801 Broad St.  
 Emmaus, Pa.

-2-

| <u>OPERATION</u>            | <u>HAZARD</u>                                                              | <u>CONTROL MEASURE</u>                                 |
|-----------------------------|----------------------------------------------------------------------------|--------------------------------------------------------|
| Main Assembly cont.         |                                                                            |                                                        |
| cement mixing(cont.)        | "Tarabrand cement<br>SS3915/1947" dust<br>(Made in Yugoslavia)             | general vent.                                          |
| arc welding                 | Fe, O <sub>2</sub> fumes, CO, heat,<br>Ozone, U. V. light, NO <sub>2</sub> | general vent, helmet,<br>some welding is<br>shielded   |
| acetylene burning           | Fe, O <sub>2</sub> fumes, CO <sub>2</sub> , heat,<br>infra-red, CO         | general vent.,<br>goggles                              |
| shear                       | Fe dust                                                                    | general vent.                                          |
| brake                       | Fe dust                                                                    | " "                                                    |
| fiberglass insulation       | fiberglass dust                                                            | " "                                                    |
| testing                     | heat, infra-red,<br>CO, CO <sub>2</sub>                                    | enclosed, exhausted<br>to the outside                  |
| specialty spray<br>painting | "Synthetic Thinner<br>S-81" vapor & mist<br>(Allentown Paint<br>Products)  | respirator B M2301,<br>occ. exposure,<br>general vent. |

Report of the Pennsylvania State  
 Health Department

PA STATE ARCHIVES

800 North Second Street, Harrisburg, PA 17120-4000

PA Historical & Library Commission