

LOT MAY -0-81- 1446

EST'D WGT 5632

TOTAL EST'D WGT= LBS (CRT ENTRY)

## MAKING NOTES

JOB NAME: 01YE698DPS

| INSTRUCTIONS                         |    |    |    |  |  | = | PRESSING       | =              | RECORD |     |     |     |  |
|--------------------------------------|----|----|----|--|--|---|----------------|----------------|--------|-----|-----|-----|--|
| VAT                                  |    |    |    |  |  |   | PRESSLOAD      | <del>1ST</del> | 2ND    | 3RD | 4TH | 5TH |  |
| DATE                                 |    |    |    |  |  |   | STARTED        |                |        |     |     |     |  |
| TIME                                 |    |    |    |  |  |   | CAKES USED     |                |        |     |     |     |  |
| RELEASED BY                          |    |    |    |  |  |   | WATER ON       |                |        |     |     |     |  |
| PRESS                                | 2  | 92 | 93 |  |  |   | HRS. WASHED    |                |        |     |     |     |  |
| NO.OF CAKES                          | 54 | 54 | 54 |  |  |   | OHMS           |                |        |     |     |     |  |
| PRESS WITH AGITATION                 |    |    |    |  |  |   | HRS. WASHED    |                |        |     |     |     |  |
| WASH TO 2000 OHMS WITH 35-75 F WATER |    |    |    |  |  |   | OHMS           |                |        |     |     |     |  |
| TEST AFTER 2 HOURS                   |    |    |    |  |  |   | HRS. WASHED    |                |        |     |     |     |  |
| LOAD ON 7 CARS                       |    |    |    |  |  |   | OHMS           |                |        |     |     |     |  |
|                                      |    |    |    |  |  |   | CAKE CONDITION |                |        |     |     |     |  |
|                                      |    |    |    |  |  |   | NO CARS LOADED |                |        |     |     |     |  |
|                                      |    |    |    |  |  |   | EXPLAIN LOSSES |                |        |     |     |     |  |

SAMPLES  
DELIVER TO

SAMPLED BY  
RELEASED BY

(EXTRUDED) DRY 10 HRS AT 240 DEG F | LUMP: - OK - WET - SALTS - CONTAMINATED  
(NOT EXTRUDED) DRY 10 HRS AT 240 F | \_\_\_\_\_

ADDITIONAL DRYING HOURS REQUIRED

SAMPLES 1 ENV  
DELIVER TO COLOR TEST LAB

NO CARS PULLED  
SAMPLED BY  
RELEASED BY *l-*

NO DRUMS 18  
LUMP WGT 5533

| MILL MIKROATOMIZE                |  | SCREEN |  | = GRINDING = |  | SCREEN     |  | RPM |  |
|----------------------------------|--|--------|--|--------------|--|------------|--|-----|--|
| MAX. TEMP                        |  | DEG F  |  |              |  | MAX. TEMP. |  | F   |  |
| SET ROOF BLAST - GATE AT "9" FOR |  |        |  |              |  |            |  |     |  |
| HIGH AIR FLOW                    |  |        |  |              |  |            |  |     |  |

## EXPLAIN LOSSES

SAMPLE WITHOUT MIXING  
SAMPLES  
DELIVER TO CTL

DATE MIXED  
SAMPLED BY  
RELEASED BY

1446  
41  
100

3.37 +  
0.12 -  
3.07 +  
0.12 -  
3.30 +  
0.12 -  
2.24 +  
0.12 -  
3.08 +  
0.12 -  
3.54 +  
0.12 -  
3.40 +  
0.12 -  
3.32 +  
0.12 -  
3.22 +  
0.12 -  
3.30 +  
0.12 -  
3.32 +  
0.12 -  
3.15 +  
0.12 -  
3.24 +  
0.12 -  
3.18 +  
0.12 -  
3.30 +  
0.12 -  
3.04 +  
0.12 -  
3.10 +  
0.12 -  
3.32 +  
0.12 -  
55.33 \*