

workmen should take daily showers to remove the material from their persons before they leave the plant. Even though the exposure does not necessitate showers, workers should be encouraged to wash thoroughly at the end of their shifts. Cleansing materials, shower stalls, and wash basins should be provided. Washable suits of tightly woven fabric,

preferably full-length coveralls, and washable caps should be worn. Suits, caps, socks and underwear should be laundered daily at the plant. Clothing should be laundered less frequently only at the express direction of the plant medical department.

Skin contact with liquid chemicals should be avoided. See Chapter 38 for details.

References

- American Petroleum Institute, 1271 Ave. of the Americas, New York, N Y 10020 *Cleaning Petroleum Storage Tanks*, RP 2015
- American Standards Institute, 1430 Broadway, New York, N Y 10018
Gray Finishes for Industrial Apparatus and Equipment, Z55.1
Safety Code for Fixed Ladders, A14.3
Safety Code for Powered Industrial Trucks, B56.1
Safety Color Code for Marking Physical Hazards and the Identification of Certain Equipment, Z53.1
Scheme for the Identification of Piping Systems, A13.1
- Association of American Railroads, Operating-Transportation Div., 1920 L St. NW, Washington, D C 20006 *Recommended Methods for Loading, Bracing and Blocking Carload Shipments of Machinery in Closed Cars*, Pamphlet No. 21
- E. I. du Pont de Nemours & Co. (Inc.), Explosives Dept., Wilmington, Del. 19898 *Blasters Handbook*, 15th ed., 1967
- Illuminating Engineering Society, 345 East 47th St. New York, N Y 10017 *IES Handbook*, 3rd ed.
- Manufacturing Chemists' Association, 1825 Connecticut Ave. NW, Washington, D C 20009 *Manual Sheets, TC Series (on unloading various hazardous liquids from tank cars) Guide to Precautionary Labeling of Hazardous Materials* Manual L-1
- National Fire Protection Association, 60 Batterymarch St. Boston, Mass. 02110
Cleaning and Safeguarding Small Tanks and Containers, No. 327
Code for Explosives and Blasting Agents, No. 495
Flammable and Combustible Liquids Code, No. 30
Fundamental Principles for the Prevention of Dust Explosions in Industrial Plants, No. 63
National Electrical Code, No. 70
National Fire Codes, Vol. 4, "Flammable Liquids and Gases"
Sprinkler System Installation, No. 13
- National Safety Council, 425 North Michigan Ave., Chicago, Ill. 60611
Industrial Data Sheets
Automotive Hoisting Equipment, 437
Baling Presses, 421
Bottles and Broken Glass, 355
Boxcars, Unloading Bulk Grain from, 521
Calender Rolls, Handling, 403
Chains (Alloy Steel) for Overhead Lifting, 478
Containers (Small), Flammable Liquids in, 532
Conveyors, Belt (for Bulk Material)—Equipment, 569
Conveyors, Belt (for Bulk Material)—Operation, 570
Conveyors, Roller, 528