




14 APR 80 3:48

K.B. TERMAAT

KBT
D. L.

Inter Office

Electrical and Electronics Division
Product Engineering Office

Mr. J. W. Durstin

April 10, 1980

cc Messrs. W. L. Bailey
J. R. Cherry
J. Gormley
B. P. Hooten

J. B. Huebner
R. S. Oswald
J. G. Rivard

Subject: Identification of Production Materials and Components Containing Asbestos

Reference: Mr. J. W. Durstine's letter March 14, 1980 to Messrs. D. D. Baker, et al

The following EED PEO parts are released with asbestos containing materials:

<u>Specification Number</u>	<u>Component</u>	<u>Basic Part No.</u>
ESF-M3D76-A	A/C Motor Commutator	18B374
ESF-M3D76-A	Cooling Fan Motor Commutator	8K621
ESF-M3D76-A	W/S Washer Motor Commutator	17B616
ESF-M3D76-A	W/S Wiper Motor Commutator	18B374
ESF-M3D76-A	Heater Motor Commutator	18B374
ESF-M3D113-A	Starter Commutator	11015
ESA-M4D140-A	I/C Lamp Socket	13711
ESF-M8G55-A	Water Temp Sender Gasket	10914
ESF-M8G55-A	Seal - EEC	12A696
ESF-M8G96-A	Air Temp Sender Gasket	12A676
ESW-M8G109-B	W/S Wiper Gasket	17C430
ESF-M8G126-A	Window Regulator Yoke Gasket	14A427
F-104128108M3	Horn Gasket	13817

The following EED PEO released components are suspected to contain asbestos:

<u>Component</u>	<u>Supplier</u>	<u>Basic Part No.</u>
Fuel Pump Motor	Bosch	9350
Antenna Motor	Tenna	18B801
Seat Motor Armature	G-I & Eaton	14547
Power Mirror Motor	Harmon	17D696
Sun Roof Motor	Am. Bosch	15B689
Power Wdo Motor	Am. Bosch, L-N & G-I	14553
Power Door Lock	Essex	218A42

We have also requested an evaluation of the entertainment components designed and released by the FACC subsidiary. An initial review by FACC Engineering indicates no known asbestos containing materials are released. The final results of this evaluation will be forwarded to your office by April 25, 1980.

For any further information contact J. B. Huebner, EED Materials Engineering (21495).

A. D. Krugler
A. D. Krugler

9001 1771

SCF-FORD-1847