

February 19, 1976

Mr. Glen Butler  
Area Director  
U.S. Department of Labor  
Occupational Safety and Health Administration  
Federal Office Building - Room 734  
234 Summit Street  
Toledo, Ohio 43604

Dear Mr. Butler:

Attached is our check No. 068686 for \$255.00 to cover the penalties charged Maremont Corporation on your Citation OSHA-1 #320 dated February 11, 1976.

Sincerely,

R. J. Treinen  
Manufacturing Manager

RJT:llw

Att.

cc: J. L. Cipolone  
R. A. Hemmelgarn  
R. C. Rogers  
A. P. Staszak

MAR 001706

# MAREMONT

C O R P O R A T I O N

## INTER-OFFICE CORRESPONDENCE

TO: R. A. Hemmelgarn

DATE: April 5, 1976

FROM: A. P. Staszak

COPIES TO:

LOCATION: Paulding

R. C. Rogers

J. Sherr

✓ R. J. Treinen

SUBJECT: OSHA FOLLOW-UP HYGIENE INSPECTION

On April 1, 1976, Bill Gribble from the Toledo OSHA office, was in to make a follow-up hygiene inspection. The purpose of this visit was to determine whether we had complied with earlier dust and noise citations.

First we met in my office to discuss the particular items in question: dust at Block presses, and noise and dust at the #2439 Block saw.

Gribble then met with Jane Miller of the UAW and Rick Mabis of the MESA.

We then proceeded to the Block Department. After looking over the area, Gribble decided to take six hour air samples on both operators at the #3 preform press. During the sampling period everything appeared satisfactory until the clean up at the end of the work shift. During clean up a malfunction of the vacuum sweeper occurred which reintroduced a considerable amount of dust into the air. Both operators were immediately instructed to cease using this piece of equipment and hopefully it will not greatly affect the results of the air samples taken.

The #3 preform press was the only machine sampled during this visit.

After reviewing our OSHA accident forms #100,101, and 102, during the closing conference, Gribble mentioned that he would be in this week to examine the #1, 5 and 6 Block presses for dust, the #2439 saw for dust and noise and to further investigate the progress we have made on reducing airborne asbestos dust in the entire plant.

*A. P. Staszak*

A. P. Staszak  
OSHA and EPA Compliance Director

APS:llw

MAR 001707



June 1, 1976

Mr. Glen Butler  
Area Director  
Occupational Safety and Health Administration  
Federal Office Building - Room 734  
234 Summit Street  
Toledo, Ohio 46304

Dear Mr. Butler:

REF: OSHA-1, No. 320

This is our fourth progress report for correction of alleged violations stemming from an inspection made on 2/4/76.

Item 1 of citation 3; item 1 of citation 2 and items 2 and 3 of citation 1 were reported corrected in previous reports.

The following is a report on the remaining item.

| <u>Citation</u> | <u>Item</u> | <u>Status</u>                                                                                                                                       |
|-----------------|-------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| 1               | 1           | A purchase order for correction of electrical wiring will be issued following approval from Corporate offices. This item will be abated by 8/16/76. |

Sincerely,

A handwritten signature in cursive script, reading "A. P. Staszak".

A. P. Staszak  
OSHA and EPA Compliance Director

APS:llw

cc: R. A. Hemmelgarn  
R. C. Rogers  
J. Sherr  
R. J. Treinen

MAR 001708