



TO E. D. Macias AT Assonet DATE May 20, 1974
 FROM R. A. Chartier AT Assonet COPY TO
 SUBJECT MEETING ON ENVIRONMENTAL HEALTH - MAY 14, 1974

A meeting was held on May 14, 1974, to discuss the implementation of the new plant breathing air system and the procedures for handling monitoring data that indicate over 50 ppm readings when they are obtained. The following points were agreed upon:

1. If any suspicion of reading over 50 foreman to call lab and technician will immediately proceed to building and take a reading.
2. Any readings over 50 on a routine basis foreman is to be notified.
3. Foreman will ask laboratory technician to stay or return depending on nature of excursion.
4. When MSA units arrive for each building additional monitoring capability will be available.
5. Foreman will notify lead operator and personnel in building.
6. Utility man should take a mask into any reactor with him starting now.
7. Any work on H₂S, filters, etc., maintenance men should wear breathing apparatus.
8. Try a 6 inch hose for in reactor.
9. Maintenance wants readings taken initially on various jobs. Lab to take readings.
10. Need eyeglass program for masks resolved and started right away.

OLI 5835

11. Need a list of all people who wear prescription glasses.
12. Need sanitizing material for laboratory. Need two masks.



R. A. Chartier

RC:jaa

Distribution:

L. A. Baker
R. H. Carte
D. L. Chaloux
E. T. Chesler
A. T. D'Ambra
D. C. Foster
E. J. Goettman
T. O. Hill
F. R. Klebacher
R. E. Martel
R. J. Paolantonio
R. H. Rawlings