

cc: Messrs. WEZieske - FHWhiting - DSOpfinger -
GRKatchur - MKaufman - ALHulsted -
LFDonnelly - FSFrederick (Engrg.-3W3)
RLBieber - EWReiss (Prod.Cont.-2N5)
JDIngerto - GSTrump (Hagerstown)
TGDickson - JLRathburn (Dana Corporation)

MACK TRUCKS, INC.
HIGHWAY VEHICLE ENGINEERING
ALLENTOWN, PENNA.

MARCH 20, 1973

TO: CONTRACT ENGINEERING

ATTENTION: MR. M. T. MOLL

SUBJECT: CLUTCH REQUIREMENT FOR ROADWAY
EXPRESS - G.S.O. R773ST-98239

For record purposes only, as well as for information to all concerned, below are listed the components for the clutch requirements for the subject order.

<u>Mack No.</u>	<u>Spicer No.</u>	<u>Description</u>
11HBA4152-P3	127400-1X	(CL695) AS-1402 Cover Assy. (3200#)
101HB455	127261-4X	Front Driven Disc Assy. (1488 Material) Dampened organic facing
101HB456	127262-4X	Rear Driven Disc Assy. (1488 Material) Dampened organic facing
597HB327	113C49	Intermediate Plate
11HB4219	107035-27	Clutch and Disc Assy. in- cludes (6) 274C-6 drive pins

BUS-0063


DANA-0317.040

MR. M. T. MOLL

-2-

MARCH 20, 1973

As indicated above, we have assigned CL695
unit symbol for proper identification of this clutch.


DALE H. CHRISTMAN

dmy

BUS-0064