

SUMMARY OF ACTION ITEMS
FROM
CCU S/D PLANNING MEETING

Participants

Mike Anderson (part-time)
Dave Atwood
S. S. Braun-1100 Milam
Mike Davis
Dave Davison
Dick Frutiger
H. C. Grant-OSP
Jerry Ransdell
Phil Snyder

Date: May 23, 1980

Action Items:

- 2) Sandblasting - The Complex policy of using an alternate material for silica sand will be followed on this shutdown.
- 3) Particulate Control - As a minimum, the contractor will be required to vacuum (or equivalent) particulates on the walls of equipment at least once per day, and twice per day during periods of heavy dust generation (gouging, blasting, etc.). Use of a super-vac or other means of controlling particulate generation will be investigated.
- 4) Asbestos - Investigate the use of a super sucker and equivalent to remove asbestos backed refractory to control asbestos exposure. If this is impractical, appropriate respiratory will be required.
- 7) Personal Hygiene Facilities - Contractor should be required to provide showers so that personnel can wash before leaving site.

ABS-007403

LAM 024223

Summary of Action Items from CCU S/D Planning Meeting

2

- 8) Monitoring - The industrial hygiene monitoring should cover the same materials monitored during the last shutdown plus the following: copper, cadmium, lead, and refractory silica.

Dist.: Attendees

DPMC
5/28/80
RPF:ikg

LAM 024224

ABS-007404