

FILE NAME: Asbestos Cement Pipe and Sheet (ACPS)

DATE: 1988 Apr 22

DOC#: ACPS129

DOCUMENT DESCRIPTION: Memo - Poor Housekeeping in A/C Operation Areas

RUSH

J-M Manufacturing Co., Inc.

Internal Correspondence

To : C. G. Stelchek- Denison

Date: April 22, 1988

From : E. E. Wang- HQ

Copies : T. E. Lohman- HQ; C. J. Chen- HQ; Homer Hsieh- HQ

Subject : POOR HOUSEKEEPING IN A/C OPERATION AREAS

I was told by the industrial hygiene survey people, who have just conducted an asbestos and silica sampling work at your plant, that the housekeeping in the A/C operation areas was very poor. For instance, the bags containing asbestos raw material were punctured and left unsealed; the A/C workers wore their street dresses (not the special clothing, such as coveralls or similar whole body work clothes) while working (this will carry the asbestos fibers to their homes and cause asbestos contamination); asbestos dust was found everywhere around the area; and even the survey person's equipments were contaminated by those asbestos fibers. Furthermore, the industrial hygienists have clearly expressed that they will not enter your facility for October's comprehensive survey if the areas involved have not been cleaned-up.

I would like to call your IMMEDIATE ATTENTION to this matter. Take your IMMEDIATE CORRECTIVE ACTION to greatly improve the housekeeping in the A/C operation areas. All external surfaces in areas involved shall be maintained free of accumulations of asbestos fibers if, with their dispersion, there would be an excessive concentration.

E. E. Wang

JM-GA-002

EXHIBIT

21

Jim Reichert
7/8/08
hg Litigation Services

JONES 0001448

EXHIBIT 23	
J. Reichert	
Deponent	
Date 9/4/11	Rptr. DW