

8/27/83
VCM release

At about 1425-051430 I came from Basing
Area by VIO Dryer and saw Fire pumps
were on I then went to Guard house and
called Bob to see what was going on in
unit he said VCM was coming up from
sewer after 744 was into charge
mode I then went to new unit at
this time I passed Doug about cooling
tower at 3-400 tower I went by 5600 tower
and saw VCM coming from sewer and
chem wash pumps seal water drains and
Relief valve by chem wash strainer was popping
off Alton and Willie were into Scott Air packs
at this time Willie checked VC valves on
744 Alton then cut off manual valve west
of chem wash pumps for chem wash main
return line VCM slowed down at this
time also MSA was flooding area with DTH 000105768
water the hold tank for chem wash was not
in contact with VCM, after checking chem wash
valve and sewer chem wash act is kicking as
bolts are loose on same and valve is not going
all the way close we'll go to check act and line
valve back up or change out also manifold will
be press checked before next charge

Stu Kilgus 8-27-83