

CONOCO CHEMICALS — ABERDEEN PVC PLANT
DOSIMETRY CARD (A)
SAMPLE **No** 0488Hazard: VCM (✓) Lead () Noise () () Date 2/9/80Name Douglas Spann S.S. # 418-66-3073 Shift PDepartment Vinyl Job Class Chief Operator

Instrument No. <u>299</u>	Start Time <u>6:33</u> AM () PM (X)	Stop Time <u>7:05</u> AM (X) PM ()
Noise Cell No. _____	Airflow _____	

Analyst: [Signature] Analysis Date: 2-12-80

Hazard	TWA Exposure		
VCM	PEL: 1 PPM	<u>40.1</u>	PPM
Noise	Over () Under () 115 dBA	% of PEL	
Lead (Micrograms)	TOT: PEL: Per M ³	Per M ³	

CONOCO CHEMICALS — ABERDEEN PVC PLANT
DOSIMETRY DATA CARD (B)
SAMPLE **No** 0488Hazard: VCM (✓) Lead () Noise () () Date 2/9/80Time Clock (Lead Sampling Only) : IN: 0700 AM (X) PM (X) OUT: 0700 AM (X) PM ()

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

Area	Time	Area	Time
<u>RX</u>	<u>2.0</u>		
<u>DRYER</u>	<u>2.0</u>		

List most likely causes of possible overexposure to the hazard.

- Rec systems
- Rx's
-

Check respiratory protection you used:

() None () Dust Mask () Air-line Respirator () Scott Air-pak

Signature Douglas Spann

Please complete and return to guard