



INTERNAL
CORRESPONDENCE



UNION CARBIDE CORPORATION

OLD SAW MILL RIVER ROAD, TARRYTOWN, NEW YORK 10591

To (Name) W.P. Fethke
Division Linde
Location Tarrytown
Area

Date March 3, 1986

Originating Dept.

Area

Copy to J. Cullen
A.J. Caglione
R. Langworth
J.E. Pikula
T.M. Reynolds

Subject Industrial Hygiene Survey
Room 77L - Mezzanine
Linde Building

Subject area was monitored for particulate matter on January 9, 1986 while General Services personnel were removing piping insulation. Ventilation in laboratory was off while work was performed.

Particulate was identified as amosite asbestos fibers.

<u>Area Sample</u>	<u>Concentration of Asbestos Fibers/cc. TWA</u>
1 - Southeast	<.04
2 - Middle of 1 & 3	<.01
3 - Southwest	<.03
4 - Northwest	<.01

Exposure to asbestos fibers is below the permissible level of 2 fibers/cc. TWA₈ (OSHA).

F.D. Lutz

am
860301

A04341

From: AJC1 --CAPS Date and time 02/21/86 14:01:58

To: AJC1 --CAPS

*** Resending note of 01/09/86 12:57

To: WPF1 --CAPS

Subject: Removal of Insulation in 77L

Wait, In my opinion the insulation removal was handled poorly and Allied should not do this work in the future.

STATUS:

The insulation has been removed and bagged.

MY OBSERVATIONS:

- . The only plastic covering in place was installed by MPT personnel. In fact, one cover was removed.
- . The door to the upper level of 75L was partially open.
- . There were no warning signs posted on the entrances to the lab.
- . It appears that MPT's vacuum was used (dry) to clean up. Allied disposed of the filter.
- . There is still particulate matter on the shelves that were not covered and on the floor.
- . The air samplers are turned off (unless they are on timers).

cc: RAR1 --CAPS

TMR1

--CAPS

AU4342