

=====

MATERIAL SAFETY DATA SHEET

Effective Date: March 29, 1993 Code: Allied Brake Shoe Drilled Page:3

=====

Section 7 - HANDLING AND STORAGE

=====

Special precautions are required when installing or removing asbestos friction materials. In replacing linings that contain asbestos fiber, we suggest the worker follow the RECOMMENDED PROCEDURES published by the "Friction Materials Institute" that are reproduced on page 5.

Storage: No special precautions

=====

Section 8 - EXPOSURE CONTROLS/PERSONAL PROTECTION

=====

-Protective Equipment

Eyes: Use proper protection - safety glasses, as a minimum

Skin: Washing on leaving work area and at end of shift

Inhalation: Respiratory protection is required for lining installation.

Dust/particulate respirator with OSHA approved high-efficiency filters must be worn.

=====

Section 9 - PHYSICAL AND CHEMICAL PROPERTIES

=====

Material state @ normal conditions: Solid

Boiling Point: N/A

Melting Point: N/A

Solubility in Water: None

Volatiles: None

Appearance and odor: Gray or dark solid part - mild odor

Specific Gravity(H2O - 1): 1.6 - 2.3

=====

Section 10 - STABILITY AND REACTIVITY

=====

Stability: Stable

Hazardous Polymerization: Will not occur.

Conditions to Avoid: None

Hazardous Decomposition Products: None

=====

Section 11 - TOXICOLOGICAL INFORMATION

=====

Information Not Available

=====

Section 12 - ECOLOGICAL INFORMATION

=====

Information Not Available

NOVO12056