

FILE NAME: General Electric (GE)

DATE: 1943 Jan

DOC#: GE202

DOCUMENT DESCRIPTION: Journal Article - Safety in Handling Aluminum Powders [Chemical Engineering]

CHEMICAL ENGINEERING

In this Issue

JANUARY, 1943

Volume 51

Number 1

S. D. KIRKPATRICK Editor
JAMES A. LEE Managing Editor
THEODORE E. OLIVE Associate Editor
HERBY M. BATTER Market Editor
JOHN R. CALLAHAN Assistant Editor
ROBERT G. FERGUSON Assistant Editor
LESTER H. POPE Assistant Editor

EDITORIAL REPRESENTATIVES

E. S. STETSON Chicago
R. S. MCHUGH Washington
EARLE WARDMAN Atlanta

PUBLISHER

DIRECTOR MANAGER

E. H. DEUEL New York
R. G. FREDERICK New York
FRED GRANT Cleveland
L. A. GUNNINGHAM Chicago
W. D. BOYD Boston
J. E. VAN ARSDALE Philadelphia

Published monthly. Price 95 cents per copy.
Address communications about subscriptions to Director of Circulation, Chem. & Met. Eng., 330 West 42 St., New York, N. Y.
Subscription rates: United States, Mexico, Canada and South American countries, \$3 a year, \$4 for two years, \$5 for three years. Canada, \$3.50 a year, \$5 for two years, \$6 for three years (payable in Canadian funds). Great Britain and British Possessions, 50 shillings a year, 60 shillings for three years. All other countries, \$5 a year, \$10 for three years. Entered as second class matter, September 2, 1918, at Post Office at Albany, N. Y., U. S. A. under act of March 3, 1879. Contents copyrighted, 1943, by McGraw-Hill Publishing Company, Inc. Second class: 535 North Michigan Avenue, Chicago; 65 Post Street, San Francisco; Aldwych House, Aldwych, London, W. C. 2; Washington; Philadelphia: Cleveland; Detroit; St. Louis; Boston; Los Angeles; Atlanta.

McGraw-Hill Publishing Co., Inc.

JAMES H. McGRAW
Founder and Secretary Chairman

PUBLICATION OFFICE

33-128 North Broadway, Albany, N. Y.
Editorial and Executive Offices
330 West 42 Street, New York, N. Y.
JAMES H. McGRAW, Jr. President
HOWARD E. LITCH Executive Vice-President
MASON BRITTON Vice-President
S. R. FURMAN Treasurer
J. A. GERARDI Secretary
I. H. BLACKBURN, Jr. Director of Circulation
Member A.S.P. Member A.S.E.
Cable address McGRAWHILL, New York

Our Year II of World War II	75
EDITORIAL FOREWORD	
Waste Disposal Problems in Wartime	78
By F. W. MOHLEN	
Safety in Handling Aluminum Powders	82
By G. M. SABCOCK and F. R. BETHWISCH	
Progress Report of the Rubber Director	85
Selection of Pumps for Oleum and Strong Sulphuric Acid	86
By WARD E. PRATT	
Effect of the Kinetic Energy Term in Gas Flow Calculations	90
By BENJAMIN MILLER	
Nylon Research Wins Its War Wings	92
EDITORIAL STAFF REPORT	
Manufacture of Butadiene From Ethyl Alcohol—II	94
By J. A. GUNN and T. BROUKE	
Labor Relations and Collective Bargaining in Chemical Industry	99
A CHEM. & MET. REPORT	
Chrome Tanning Leather	112
A CHEM. & MET. PICTURED FLOWSHEET	
Chem. & Met. Plant Notebook	107
Process Equipment News	107
Chemical Engineering News	110
News From Washington	121
Interpreting Washington	124
New Products and Materials	128
From the Log of Experience	134
Personalities	137
Meetings and Conventions	143
News From Abroad	155
Chem. & Met. Bookshelf	167
Chemical Economics and Markets	175
Current Prices	197
New Construction	199

An Index to advertisers will be found on page 146



A McGraw-Hill Publication

McGraw-Hill Publishing Company

330 West 42nd Street, New York, N. Y.

Director of Circulation
Please change my address as Chemical & Metallurgical Engineering

From
To

I

Safety in Handling Aluminum Powders

G. M. BABCOCK and F. B. RETHWISCH *Reynolds Metals Co., Louisville, Ky.*

Chem. & Met. INTERPRETATION

Except for those people who work constantly with aluminum powders, sufficient respect for the explosibility of this material does not appear to exist. With the present widespread use of aluminum powders for the manufacture of military pyrotechnics, need has developed for the more widespread dissemination of information on safe practices in their handling and in manufacturing pyrotechnics. The article which follows is based on the experience gained by the Reynolds Metals Co. in many years of producing and handling metallic powders and is offered as a starting point in the development of safety programs for concerns engaged in or beginning operations in pyrotechnic work. Certain fundamental precautions are discussed by the authors as a service to the industry, but neither they nor their company assume liability of any kind in presenting this information.—Editors.

FLAKE ALUMINUM POWDER, somewhat similar to the material commonly used in aluminum paint under the rather misleading name of "aluminum-bronze powder," is a valuable component of pyrotechnic mixtures used for flares and signals. The high surface area of a given weight of aluminum flake powder makes it easily ignitable when in the presence of oxygen or air. Burning, it evolves a tremendous amount of heat and light. Owing to its low apparent density, fine particles of the material tend to float in air with the attendant danger of violent explosion upon ignition, when a proper ratio of aluminum to oxygen is reached.

A somewhat different aluminum powder, the grained variety, consists of spheres, sausage shapes or irregular grains of aluminum, which are relatively hard to ignite. When mixed with oxygen-producing compounds, the grained powder will burn with the evolution of much heat and light. This material, however, has a high apparent density and low surface area which tends to keep it from suspension in air so that the danger of explosion or fire from aluminum "fog" is almost nil.

Both flake and grained aluminum are shipped in sealed drums with fully removable heads. These drums

should be stored unopened in a separate area wherever possible, since if they are stored along with such chemicals as sulphur, nitrates and others of similar character, a fire from any cause would present a most serious problem. Whenever a drum of aluminum powder is opened for loading or inspection, it should be closed and re-sealed as soon as possible. This not only insures greater safety against fire from external causes but also limits the likelihood of tramp material getting into the powder, or of the powder absorbing water from the air. In one instance a sealed drum of flake aluminum withstood an aluminum dust explosion and subsequent fire without ignition of the drum contents.

There are few practical means of extinguishing fires involving aluminum powder or mixtures containing this powder. Anything which tends to disturb the burning mass may throw the aluminum into the air and result in a violent explosion of tremendous destructive power. It is true that dry sand, carefully placed over a pile of burning aluminum, will smother the flame, but in the excitement attending such a fire, there is danger that the sand will be thrown or shoveled on to the mass, and that the powder will be thrown into the air. There have been

several cases where relatively harmless fires have been changed to serious and fatal explosions from this cause.

Consequently, the safer and more prudent rule is to instruct employees to walk out of the building in the case of an aluminum fire, shutting the door securely but as gently as possible to avoid disturbing the burning mass.

All employees should be instructed in procedures to avoid. They should understand thoroughly that water, carbon tetrachloride, fire foam, carbon dioxide and similar extinguishing agents should not be used on aluminum fires. Use of such materials will cause explosions. Night watchmen should be instructed to convey this information to any regular or volunteer group which attempts to extinguish an aluminum fire. Furthermore, the use of a fine spray of water from a slurrup pump, such as is used by civilian defense workers on incendiary bombs, should never be used on aluminum powder fires.

It is of utmost importance that local fire departments be informed of these precautions. The department should be provided with complete information and charts regarding these warehouses which contain aluminum, as well as those containing other chemicals. These charts should also be readily available to the watchmen and to the plant's own protection division at all times.

AVOIDING HAZARDS

A source of great danger in the handling of aluminum powder is the presence of foreign substances, particularly hard or metallic materials. Care should be taken to see that closing bolts, nails and similar bits of metal cannot contaminate aluminum powder or pyrotechnic mixtures.

Good plant housekeeping is one of the most effective methods in achieving plant safety and care must be taken particularly in the weighing, mixing and pressing rooms. As little material as is practical should be kept in one place at one time. Scoops for handling powders should be of non-sparking material and the handling should be slow and deli-

beries to reduce during to a minimum. Rooms in which powder is handled should be cleared at frequent intervals, but never during weighing, mixing or pressing operations. All material should be kept in closed containers while cleaning is in progress. If oil is used in the pyrotechnic mixture, special care must be taken to insure that all oily rags or waste are deposited in closed safety cans away from the storage or loading area. These rags must be disposed of daily. In cleaning, cars must be taken particularly to keep all corners, window ledgers, beams, building steel and other resting places free from dust.

BUILDING PROTECTION

The buildings used for weighing, mixing and loading operations should, wherever possible, be so spaced and protected that fires or explosions in one unit cannot be communicated to other units. Construction should be adapted to the resisting of explosions, using either a "soft" wall or roof, or a blow-out panel. All equipment should be located so that the operator has a free path to an outside door, without a mixing bench, press or mixer between him and the door.

All metal in the buildings should be grounded. This not only includes the equipment itself, but also metal window and door frames and other building elements. Clips connected to ferribe grounded leads should be placed on all metal drums or other movable equipment. Only explosion-proof motors should be permitted, and for these the controls should be fully insulated and non-arcing, located outside the workroom so that no worker need be in the mixing or pressing room from the time of starting these operations until they are completed.

All lights should be of a type approved for explosive operations and conditions. Particular care must be taken when atmospheric or manual tools are to be used in buildings for repairs or changes. When such work is to be carried out, the rooms must first be emptied of all ignitable material and thoroughly cleaned. Fatal explosions have been caused in dust-filled rooms by an arc from the switch of an ordinary flashlight. Therefore, only flash

lights, electric lighting and power equipment carrying Underwriters' approval for use in explosive areas and where explosive vapors are encountered should be used.

Whenever possible, built the shoes of workers and the floor should be of a conductive but non-sparking type. Electrical discharges produced by static or lightning are the most difficult safety hazards to control. The danger from static charges produced by friction is greatest in cold, dry weather. Even walking on concrete or composition flooring in unconducting shoes may produce sparks capable of leading pyrotechnic mixtures or fine aluminum particles suspended in the air. Even the friction caused by aluminum powder poured from a scoop to a container can create high static charges on the aluminum particles.

Particularly in the case of black aluminum powder, considerable time is required to dissipate this charge.

Several types of non-sparking, conductive shoes have been employed successfully. Three types may be described briefly here, including (1) Magnetic flooring installed over a wood or concrete base, with conductive metal grids placed beneath the surface of the floor and properly grounded; (2) embossed asphalt composition flooring with a conductive aggregate which also is laid over grounded metal grids; and (3) insulating graphite tile made of a conductive mass, the edges of the tile being melted together with a hot iron in installation to provide a continuous surface. With this last mentioned type no metal grid is necessary, the tile itself being grounded at various points.

These views, from photos by the U. S. Army Signal Corps, show a thermal bomb demonstration at the Army War College, Washington, D. C. The upper view shows the bomb beginning to explode, while the lower shows the object of the explosion where the bomb having reached a temperature of about 4,000 deg. F. is walking through the slab of steel on which it rests.



These photographs were obtained from the U. S. Army Signal Corps, Washington, D. C. The upper view shows the bomb beginning to explode, while the lower view shows the object of the explosion where the bomb having reached a temperature of about 4,000 deg. F. is walking through the slab of steel on which it rests.

The causes of static should be explained to employees, using simple illustrations such as the rubbing of silk in wool clothes, or the combing of hair. Bolt drives should not be used on machines in the mixing, pressing or loading rooms. Special care should be taken in screen rooms, since the friction of the particles passing over the screens and their temporary suspension and separation in air can build up high static charges. All metal in processing and storage rooms should be grounded and every possibility of a spark from machinery, from broken electric light bulbs, or from the dropping of steel tools should be guarded against. Property provided metal containers or spark-proof conductive flooring will permit more rapid dissipation of static charges than wooden containers. Mirrors should be allowed to remain at rest for a short time before the pictures are removed, thus permitting any static charge induced in the metal parts

in the wax to be conducted to ground. Simple electroscopes can be made to determine when a mixture is free of static charge.

Adequate lightning protection is an important requirement for the plant handling aluminum powders. The grounding of all metal windows and floor frames and approved lightning protection of all wiring will largely eliminate the possibility of high charges collecting before or during a thunderstorm and perhaps discharging to the ground with an accompanying flash or spark. Protection against static lightning strikes is best left to municipalities on this subject. Many concerns that town all mixing and loading operations during severe, stormy lightning storms, the employees leaving the processing rooms during that period. Radio sets are good indicators of approaching electrical storms, but if they are used, they should not be disabled in the loading area owing to the hazard they introduce.

Highlights in Avoiding Aluminum Powder Explosions

1. All machinery and all wind door and window frames should be well grounded.
2. All mixing and conveying equipment should be constructed so as to minimize the escape of dust into rooms.
3. Spillages, scrap, conveyors and the like should be of non-sparking materials.
4. Mirrors, or for as possible, should be kept in separate rooms, outside the work rooms. When it is necessary to have them in the workrooms, they should be of the explosion-proof, dust-proof, spark-proof type of scratch-resistant construction.
5. Dust should not be permitted to collect in workrooms; they should be cleaned several times a day. If necessary, although not while operations are going on.
6. Dust in the air should be kept at a minimum. Men people who do not work continuously with aluminum powder do not fully appreciate the explosibility of this material. Tread and forest' state that the lower explosive limit for aluminum powder suspended in air varies with the method of ignition. With an electrically heated glowing wire, or with an open flame, the lower explosive limit was found to be at a concentration of 7.0 mg. Al. per liter of air, and at a concentration of 33.7 mg. with an induction spark.
7. Lighting of rooms should be provided by dust-proof, explosion-proof bulbs.
8. If necessary to use flashlight, they should always be of an Underwriters' approved type, for use in explosive atmospheres.
9. All bearings and gears should be kept well lubricated and protected from dust.
10. All employees should wear approved type clothing, without pockets or cuffs, if feasible.
11. Operations engaged in mixing should wear protection on a level protection.
12. Safety shoes of a type which are both conductive and non-sparking should be worn by operators.
13. Conductive leather should be employed if possible.
14. Operators should be instructed that in case of fire they should work out and close the doors of the room until someone has effectively arrested the static charge.
15. Aluminum powders should be stored only in sealed drums and kept from other materials, especially oxidizing agents or easily oxidizable substances.
16. Only dry wood or Underwriters' approved extinguishers should be used on aluminum powder fires.
17. Care should be taken to prevent foreign substances from getting into aluminum powder.
18. Building construction should follow the recommendations of the National Fire Protection Association.
19. In general, it is advisable to follow most of the precautions usually observed in the handling of explosives.

MIXERS AND PRESSES

Machinery used in mixing and pressing operations should be equipped with unproved dust-proof bearings, which should be kept well lubricated. Excessive temperature in any part should call for an immediate shutdown. If a shaft or other part should become so hot as to burn the part of face, such as by a hammer blow on the shaft, as long as any flammable material is in the room, displaced things or heat vents should be protected from aluminum-powder-containing materials, thermal applications of a heavy growth extinguishing this danger.

The clothing worn by plant employees should be kept clean and free from aluminum dust by frequent washing. Many concerns supply shirts and slacks to both male and female employees; the backs being made without cuffs. There is a possibility of danger when employees wear their work clothes to their homes before changing. For example, a spark from a cigarette may easily cause fatal burns to a person whose clothing is filled with the dust of a pyroelectric machine. (Owing to the possibility of static charges, silk and synthetic materials should not be worn at work by employees.)

The ideal arrangement in locker rooms for employees is to use a double locker system with an intervening shower or washroom. With this method, a locker is provided for each employee at each side of the shower or washroom. The employee removes his work clothes and places them in the work clothes locker, then takes his shower and sometimes to his second locker on the other side of the shower room where he removes his street clothing. Thus his work clothes locker is always available for inspection by company officials or for the removal of soiled clothing for replacement with clean clothing. As previously mentioned, spark-proof and conductive shoes should always be worn by employees in the handling and mixing areas.

REFERENCES

1. "Fugate and Flyover," The Lower Limits of Concentration of Aluminum Dust in Air, by J. H. Jan, 1934, p. 216.
2. "National Fire Code for the Protection of Plant Industries," 2504, National Fire Protection Association, Boston, Mass.
3. "Code for Protection Against Lightning," Section 122, U. S. Bureau of Standards, Department of Commerce, Washington, D. C., 1934.
4. "Extinguishing and Safety," "Fighting with Lightning," Random House, New York, N. Y.

Advertisers In This Issue

Page	Page	Page	Page
Abbe Inc., Paul O. 127	Bow Chem. Co. 193	Lawrence Mach. & Pump Corp. 274	Richardson Scale Co. 710
Acme Copper Mining & Mach. Co. 40	Dorring Iron Works. 42	Layne & Bowler, Inc. 169	Robert Filter Mfg. Co. 31
Allis-Chalmers Mfg. Co. 15	Dreese Corp. 279	Lebanon Steel Pkwy. 231	Robinson Conveying Bldg. Co. 51
Allis Corp., Wash. 224	Drakefield & Co., Inc., B. F. 273	Lee Metal Prods. Co., Inc. 244	Robinson Mfg. Co. 156
Aluminum Co. of America. 87	Drexler Co. 271	Leeds & Northrup Co. 72	Roche-Conoverville Mower Corp. 174
Aluminum Ore Co. 214	Duramelloy Corp. 142	Little All Products Co. 19	Rosen Controller Co. 265
American Chain & Cable Co. 174, 244	Durham Co., Inc. 21	Loeb Equip. Supply Co. 380	R-S Product Corp. 130
American District Steam Co. 143	Eagle-McRae Lead Co. 251	Lubricants Div., Fisher Bros., Re- ... 8	Ryan & Son, Inc., J. T. 341
American Flange & Mfg. Co. 41	Edgar Mear Iron Works, Inc. 285	Lubrizol Co. 247	Sarco Co., Inc. 274
American Locomotive Co. 235	Electrical Engineers Equip. Co. 70	Lubrizol Steel Co. 287-288	Searchlight Section 278-281
American Mach. & Metal, Inc. 254	Elliot Co. 204	Lynn Co. 287-288	Shapiro, Mfg. Crane & Hoist ... 245
American Motor Co., Inc. 14	Emaco Equip. Co. 303	Machinery & Equip. Corp. 204	Shaw & Co., Inc. 244
American Pipe & Found. Co. 111	Eppenhach, Inc. 164	Mathews Mfg. & Bldg. Co. 11	Solway Sales Corp. 250
American Pulverizer Co. 140	Egypt Laboratory, Inc. 204	Marley Co., Inc. 225	Sperry & Co., D. R. 244
American Smelting & Refining Co. 194	Emaco-Horrell Sales Co. 203	Master Electric Co. 3rd Cover	Spratt-Waldron Mfg. Co. 275
American Tool & Machine Co. 34	Everlasting Valve Co. 184	McGraw-Hill Book Co. 270	Standard Conveyor Co. 276
American Wingco Co., Inc. 172	Fairbanks Co. 200	Mercer Eng'g Works, Inc. 150	Standard Oil Co. (Indiana) 65-66
Armstrong Mach. Works. 128	Fairbanks, Morse & Co. 186	Metric Metal Works. 14	Stebbins Eng'g. & Mfg. Co. 104
Atlas Mineral Products of Penna. 231	Fawcett Inc. 230	Michigan Steel Casting Co. 132	Sole Equip. Corp. 242
Atlas Powder Co. 202	Fiber Paper Co. 274	Midvale Co. 49	Sturtevant Mfg. Co. 143
Babcock & Wilcox Co. 16, 58, 154-155	Fish Mfg. Corp. 200, 202, 203, 204	Midwest Piping & Supply Co. 45	Sutton Steel & Stone, Inc. 274
Babcock, Inc. 212	Fletcher Works 527	Inc. 45	Separation Eng'g. Corp. 152
Bader & Sons Co., E. S. 228	Foster Wheeler Corp. 219	Mittler, Inc. 278	Tabor Pump Co. 270
Baker & Co., Inc. 44	Floor Corp., Ltd. 237	Mining Equip. Co., Inc. 125	Taylor Forge & Pipe Works 271
Baldwin-Hill Co. 150	Foots Bros. Gear & Mach. Corp. 217	Monarch Mfg. Works, Inc. 145	Taylor Int'l. Co. 10
Barton Co., Inc. 202	Forbush Co. 45	Massachusetts Chemical Co. 121	Texas Co. 14
Bates Co., W. 169	Frederick Iron & Steel Co. 158	Mattis Mach. Works. 142	Thermal Systems, Ltd. 274
Bausch & Lomb Optical Co. 247	Fuller Co. 147	Memo Chain Co. 48	Thiessen Equip. & Mach. Corp. 271
Bear Ste. Eng. Co. 203	Garrett Packing Co. 10	Mpant Vanner Woodbury Mills, Inc. 118	Timken Roller Bearing Co. 217
Bird Mach. Co. 51	Guth & Son, E. 280	Murray Mfg. Co., D. J. 245	Roller Bearing Div. 217
Black-Knox Co. 31	General Controls 178	Nath Eng'g Co. 251	Union Roller Bearing Co. 25
Blackman, Inc. 105	General Electric Co. 21-22, 41	National Box & Lumber Co. 252	Steel & Tube Div. 25
Bols Co. 240	General Elec. Co., All Config. 22	National Radiator Co. 261	Thompson Alloy Mfg. Co. 232
Bosnyk Forge & Tool Works. 152	General Elec. Co., All Config. 22	National Technical Labs. 174	Tollman Castings Div. 137
Bradley Machinery Co. 374	General Elec. Co., All Config. 22	Neville Co. 245	American Mach. & Metals, Inc. 47
Brighton Copper Works. 243	Global Steel Tubing Co. 267	Niagara All-Alloy Co. 241-242	Troyer Eng'g. & Mfg. Co. 129
Brill Equip. Corp. 201	Gladding, McBean & Co. 250	Niagara Filter Corp. 237	Tuba-Tubes, Inc. 4
Brill Co. 152	Goodrich Pump, Inc. 244	North American Mfg. Corp. 47	Turner Mfg. Co. 146
Buell Eng'g. Co. 235	Greiner Tank & Mfg. Co., Inc. 242	Nutram Iron Corp. 61	Union Bag & Paper Co. 44
Buffalo Forge Co. 201	Grover, Tweed & Co. 180	Oliver United Filtration Inc. 213	Union Bay State Co. 26
Buffalo Fdry. & Mach. Co. 207	Gunnell Co., Inc. 21	Pasadena Corporation 164	Union Carbide & Carbon Corp. 13, 191
Butter Pump Co. 128	Grove Radiator Co. 211	Parkbridge, Arthur S. 201	Union Standard Equip. Co. 200
Carbide & Carbon Chemicals Corp. 191	Hardinge Co. Inc. 52	Pearlman Pump Div., Food Mach. Corp. 165	U. S. Ind. Alcohol Co. 19-20
Carpanter Steel Co. 234	Harvey Bros. 230	Pennsylvania Crusher Co. 273	U. S. Stoneware Co. 37-38
Cash Co., A. W. 111	Harvey Mfg. Co. 114	Pennsylvania Salt Mfg. Co. 57	Viking Pump Co. 248
Celotex Co. 274	Hatherton & Hunter, Inc. 253	Perry, Marlyn 280	Vogel-Garcia Chemical Corp. 205
Century Electric Co. 76	Hick Eng'g. Co., Inc., S. D. 243	Petrol-Elmer Corp. 218	Vogel Mach. Co., Inc. 240
Chicago Valve Co. 247	Hidomama Rubber Co. 141	Perry Equip. & Supply Co. 282	Wolf-Gulmeyer Corp. 240
Chicago Bag Co. 227	Homerhead Valve Mfg. Co. 207	Petro-Chem Development Co., Inc. 177	Watson-Stilwell Co. 261
Chemical Commission Corp. 214	Hooker Electrochemical Co. 254	Plauder Co. Back Cover	Warren Steam Pump Co. 151
Chicago Bridge & Iron Co. 248	Howell Machine Mfg. Co. 53	Philadelphia Gear Works. 222	Western Pipefitters Corp. 125
Chicago Metal Mfg. Corp. 149	Hudson Water Treatment Co. 146	Phonograph Inc. 63	Washington Elec. & Mfg. Co. 39
Clapp Corp. 273	Ingersoll-Rand 10	Pittsburgh Lachrydryer Corp. 197	Western Elec. Int'l. Co. 274
Corbano Corp. 240	Ingersoll-Rand & Disc Div., Borg-Warner Corp. 49	Pittsburgh Piping & Equip. Co. 221	Whelan to Eng. 274
Cohan & Co., E. 248	International Mixture & Chem. Corp. 14	Porter Co., Inc., H. K. 144	Whitlock Mfg. Co. 282
Cole Mfg. Co., R. D. 250	International Nickel Co., Inc. 52, 114	Powell Co., Wm. 172-173	Wickwire Speaker Steel Co. 254
Commercial Solvents Corp. 104-105	Iron & Steel Prods. Inc. 100	Powers Regulator Co. 176	Wilkey & Sons, Inc., A. 45
Consolidated Prods. Co., Inc. 279	Island Equip. & Supply Co., Inc. 283	Powder Mill Corp. 285	Williams Tool, Crank & Pulv. Co. 171
Continental Oil Co. 143	Jacobvitz Co., G. S. 282	Pratt-Hunt Corp. 283	Williams Products Int'l. 124
Copper Alloy Fdy. Co. 148	Junior Mfg. Co., D. O. 41	Patton & Co., J. F. 217	Worthington Pump & Mach. Corp. 195
Copper Eng'g. Corp. 31	Julius Mfg. Co. 215	Pawel & Schwartz, Inc. 314	Wright Mfg. Div. American Chain & Cable Co., Inc. 244
Coring Glass Works. 247	Junkins Bros. 239	Professional Services 274	Wyckoff & Sons, A. 274
C-O-Two Fire Equipment Co. 89	John-Manville 146	Pulverizing Mach. Co. 214	
Cresco Co. 177	Jones Fdry. & Mach. Co. 246	Quaker Oak Co. 157	
Danaher Ventilating Equip-ment Div., American Mach. & Metal, Inc. 244	Kaiser Mach. Corp. 204	Raymond Pulverizer Div., Com-bustion Equip. Co., Inc. 12	
De Laval Separator Co. 218	Kelley & Co., O. S. 248	Reading Chain & Block Corp. 140	
De Laval Steam Turbine Co. 263	Kerr Mfg. Co., C. M. 182	Reading-Patt & Cady (Div.) American Chain & Cable Co. 176, 244	
Dawson Oven Co. 151	Kentucky Valve Mfg. Co. 234	Reeves Pulley Co. 102	
Diamond Alkali Co. 27	Kerr-McCormick Co. 287	Rohlfeld Chemicals, Inc. 32	
Dicella Co. 186	Kellogg, Maurice A. 181	Rolly Tar & Chem. Corp. 235	
Dings Magnatic Separator Co. 181	Kold-Hold Mfg. Co. 254	Republic Ventilator Equip. Co., Inc. 204	
Dodge Mfg. Corp. 25	La Mella Chem. Prod. Co. 275	Rhodes & Sons, J. 240	
Dorr Co., Inc. 24	Lapp Insulator Co., Inc. 156		
Dougherty, James 204			

SEARCHLIGHT SECTION CLASSIFIED ADVERTISING

Business Opportunities 278
Engineering Services 278
Patents 278
Patents Vested 278
Patents Wanted 278
Selling Opportunities 278
Wanted to Purchase 278
Used Equipment 278-281