

FILE NAME: Allied Signal Bendix (ASB)

DATE: 1976 Feb 9

DOC#: ASB057

DOCUMENT DESCRIPTION: Letter from Bendix to Chrysler



**Hydraulics
Division**

St. Joseph, Michigan 490
Telephone 429-0221

The Bendix Corporation

February 9, 1976

Daniel Glazier
Industrial Hygienist
Chrysler Corporation
P.O. Box 1919
Detroit, Michigan 48231


Dear Mr. Glazier:

Confirming our meeting and conversation of Wednesday, February 4, 1976, pertaining to asbestos dust on the shoe and lining assemblies supplied to the Chrysler Toledo Machining Plant by the Bendix Corporation, Hydraulics Division.

The box of shoe and lining assemblies contaminated with excessive asbestos dust represents an abnormal condition. I have never seen assemblies in our Plant covered with that amount of loose asbestos dust.

Corrective actions are being taken that should help to prevent recurrence of this condition.

Sincerely,


Willie J. Proctor
Supervisor, Industrial Health,
Safety and Security

WJP:tag

cc: Tom DuRoss
Stan Christian

CHRYSLER 002400