

5
Delco says: 38-27E has changed
years ago - Carl used to add
graphite to rear brakes
upon assembly.

Cedilloe being pushed to
go with cup release.

and EEB
May of 82 this bar will be gone
anyway 9 1/2 x 2 Duo Servo.

Answer to problem is not a
development program involving
new formulators. Need a
desultory change to 38-27E.

EEB thinks it to late now.
maybe 30 days.

No Pb has ^{not} been discussed of Cedilloe