

0700 → 1900

"C" Kallan

6/10/84

1. S. Kilgus - V.C. - B. Stone Covered.
C. Morris - Dr. Case - W. Jackson Covered.
B. King - V.C. - B. Major Covered.
2. Old Module Dump Juvaco vibrated loose grain,
had shift mech. repair
3. Had shift mech. Connect fuel hoses to East
Incinerator burner, stem, not go; V.C.M.,
4. We going to try to site East incinerator but
had a bad stem leak - Isolated - Safety.
5. Changed filter - mostly twabby.
6. Working on housekeeping.
7. Old Module - Still doubling up on Newgood and Kill
for cold.
- 8.

1900-0700 A-SHIFT 6-10-84 BTH

1. A.C. PETTUS ON VAL., R.C. TOWERY COVERED.
L. KEATON OUT ON SICK LEAVE, D. PERRY COVERED.

2. GAVE WORD TO KEEP DOUBLE KILLING 5385 IN
THE OLD MODULE.

3. FLUSHING THE FLUID BED SLURRY. (Twice)

D.J. 4. HAVE SOMEONE ON DAYS CHECK THE UNDER GROUND
WATER LEAK BETWEEN #3 & #4 COOLING TOWERS.

5. #8 BIRD PLUGGED & KILTED OFF.

6. MAKING ADJ. ON FLUID BED AIR FLOWS.

7. WORKING ON HOUSEKEEPING.

8. WILL HOLD 741 RE DOWN @ A.M.

9. POWDER LITE AIR BLOWER WON'T STAY ON LINE, W.O. IN.

10. ADDED 5 GAL. PVA TO THE 5425 FORMULA.

11. HOLDING 700 RE. DOWN FOR MAIN CHARGE VALVE
CHANGE OUT.

12.

(DWH)