

July 30, 1972

U.S. DEPARTMENT OF LABOR

WORKPLACE STANDARDS ADMINISTRATION

Bureau of Labor Standards

Form No. OSHA-2
May, 1971

MATERIAL SAFETY DATA SHEET

SECTION I	
MANUFACTURER'S NAME MONSANTO COMPANY	EMERGENCY TELEPHONE NO. (314) 694-1000
ADDRESS (Number, Street, City, State, and ZIP Code) 800 North Lindbergh Boulevard, St. Louis, Missouri 63166	
CHEMICAL NAME AND SYNONYMS Mixture	TRADE NAME AND SYNONYMS Pyranol A13B3B-2
CHEMICAL FAMILY Chlorinated aromatic	FORMULA Mixture

SECTION II HAZARDOUS INGREDIENTS					
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES				%	TLV (Units)

SECTION III PHYSICAL DATA			
BOILING POINT (°F.)	760 mm	210 - 400°C	SPECIFIC GRAVITY (H ₂ O=1) 25/15 C 1.515-1.525
VAPOR PRESSURE (mm Hg.)	Not Avail		PERCENT VOLATILE BY VOLUME (%) N.A.
VAPOR DENSITY (AIR=1)	Not Avail		EVAPORATION RATE (_____ = 1) <1
SOLUBILITY IN WATER	20°C negligible		
APPEARANCE AND ODOR	Colorless oil aromatic odor		

SECTION IV FIRE AND EXPLOSION HAZARD DATA							
FLASH POINT (Method used)	None to Boiling	FLAMMABLE LIMITS	<table border="1"> <tr> <td>LeI</td> <td>UoI</td> </tr> <tr> <td>N.A.</td> <td>N.A.</td> </tr> </table>	LeI	UoI	N.A.	N.A.
LeI	UoI						
N.A.	N.A.						
EXTINGUISHING MEDIA	Self						
SPECIAL FIRE FIGHTING PROCEDURES Respiratory protection when fighting fires where exposure to vapors or gases is possible.							
UNUSUAL FIRE AND EXPLOSION HAZARDS Highly toxic gases (hydrogen chloride) can be evolved.							

DSW 267261

SECTION V HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE	Not available.
EFFECTS OF OVEREXPOSURE	Skin irritation in the form of chloracne, systematic intoxication leads to nausea, vomiting, loss of weight, edema and abdominal pain.
EMERGENCY AND FIRST AID PROCEDURES	Remove from exposure. Remove contaminated clothing. Wash contacted area with large amounts of water and soap.
	Refer to physician.

SECTION VI REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	
INCOMPATIBILITY (Materials to avoid)			
HAZARDOUS DECOMPOSITION PRODUCTS CO, CO ₂ , smoke, soot, hydrogen chloride			
HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	

SECTION VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED	
Absorb on clay, sawdust or other absorbant material. Place in drums. Bury in approved chemical landfill in accordance with local and state regulations.	
WASTE DISPOSAL METHOD	
Burn in approved incinerator in accordance with local and state regulations.	

SECTION VIII SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify type)		
Bureau of Mines approved respirator for organic vapors.		
VENTILATION	LOCAL EXHAUST Yes - for vapors.	SPECIAL
	MECHANICAL (General)	OTHER
PROTECTIVE GLOVES	rubber	EYE PROTECTION
		chemical goggles
OTHER PROTECTIVE EQUIPMENT		

SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING	
Avoid skin and eye contact, avoid inhalation of vapors.	
OTHER PRECAUTIONS	
DSW 267262	

While the information and recommendations set forth herein are believed to be accurate as of the date hereof, MONSANTO COMPANY MAKES NO WARRANTY WITH RESPECT THERETO AND DISCLAIMS ALL LIABILITY FROM RELIANCE THEREON.

HYDRAULICS &
LUBRICANTS

DSW 267263