

CHEMICALS

INDUSTRIES

REC'D JUL 15 1976

INTEROFFICE / LAKE CHARLES

TO O. L. Cromeans

DATE July 14, 1976

FROM G. K. Jordan

SUBJECT VCM and Related Outages

A meeting was held July 13 to run through the sequence of events for the shutdown. Attending were: Joe Morgan; Ralph Darnell; Cliff Stacy; L. Calcote; Mancy Breaux; Bill Davis; Bob Lynch; Shayde Paulk; Jimmy Wade; E. J. Tullier; Ron Kaspar; G. C. Fuller; Lew Hazlewood; John Morgan; Bill McClendon; Lamar Oliver; Bill McClendon and myself.

In addition to the detailed planning in each area, Lamar Oliver will be responsible for coordinating power switching, isolating, etc., and Ralph Darnell will coordinate the isolation of the steam system for tie-in work.

The attached memo and chart show individual unit downtimes with the chart updating the memo.

GKJ/jb

Attachment

cc: J. R. Farst
T. G. Taylor
R. E. Baker
A. J. Beatrice
J. H. Morgan
Bill Phillips
Bill Davis
Mancy Breaux
R. Kaspar
E. J. Tullier
G. C. Fuller
E. L. Cook
R. W. Darnell
R. P. Lynch
J. B. Alleman
H. J. Hoene
J. M. Davis

James Peck
Bill Smith
Bill McClendon
Jim Lafleur
Cliff Stacy
Lamar Oliver
Leo Krause
R. F. Dieter
Shift Superintendent

SL 085279

7-14-76

	July 14 Wed.	15 Thur.	16 Fri.	17 Sat.	18 Sun.	19 Mon.	20 Tue.	21 Wed.	22 Thur.	23 Fri.	24 Sat.	25 Sun.	26 Mon.	27 Tue.	28 Wed.	29 Thur.	30 Fri.
EDC						XXXXXX	XXXXXX	XXXXXX									
OHC	#3	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX
				*1 & *2	XXXXXX	XXXXXX	XXXXXX	XXXXXX									
Tri-Eth.		XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX									
VDC		XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXX								
VCM						XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX
EC						XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXX									
P/T	Reactor Shutdown/Loading					XXXXXX	XXXXXX	XXXXXX	XXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	Reactor Start-up	
HCl						XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX
Tetra		XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXX
Inc.						XXXXXX	XXXXXX	XXXXXX									
Hg C.r.						XXXXXX											
Dia. Cl ₂						HI CRT											

SL 085280