

CONOCO ABER

JUNE 26, 1974

ATTENTION: J D BURNS - SADDLE BROOK

CC: C H KLONICK - HOUSTON

D V PORCHEY - PONCA CITY

RE: OSHA INSPECTION

MR. CARL MCCOY, JR. - JACKSON, MS OFFICE

MR. MCCOY ARRIVED AT 10 AM AND LEFT ABOUT 2 PM. HE REVIEWED VCM DOSIMETER PROGRAM AND DATA AS WELL AS CENTURY MONITORING RESULTS. ALSO REVIEWED OSHA INJURY LOG. THERE WERE NO APPARENT PROBLEMS WITH OUR RECORD KEEPING.

MR. MCCOY, JERALD UPTAIN, AND CHARLES DAVIS (UNION PRESIDENT) TOURED THE PLANT REQUIRING ABOUT 1 HOUR 50 MINUTES IN THE PLANT.

ON THE EXIT INTERVIEW HE INDICATED:

- 1) AN INDUSTRIAL HYGIENIST WILL VISIT LATER TO TAKE DOSIMETER SAMPLES AND CHECK NOISE LEVELS. THIS WOULD PROBABLY BE TWO MONTHS DUE TO BACKLOG AND LACK OF URGENCY BASED ON OUR MONITORING PROGRAM.
- 2) THREE ITEMS WERE DISCUSSED THAT WILL BE REPORTED BY MR. MCCOY AND MAY RESULT IN CITATIONS PENDING REVIEW BY HIS AREA SUPERVISOR.

A. OVERHEAD CRANE IN MAINTENANCE SHOP.

1. NEED MONTHLY INSPECTION AND RECORD OF THE CHAIN.

2. ANNUAL MAGNETIC TEST OF THE HOOK TO LOOK FOR CRACKS.

STANDARD 1910.17J2 AND J3 PAGE 22262

B. STORAGE AREA OVER THE PURCHASING OFFICE NEED TO POST A LOAD LIMIT SIGN

STANDARD 1910.22D1 PAGE 22108

C. 10 INCH RADIAL ARM POWER SAW NEED A LOWER BLADE GUARD

STANDARD 1910.213H1 PAGE 22275.

E MARCUS SMITH
CONOCO ABER
END/TT