

UNION CARBIDE CORPORATION • MINING & METALS DIVISION • P.O. BOX 579 • NIAGARA FALLS

August 2, 1973

Mr. Doug Jones
Georgia-Pacific Company
1466 White Circle
Marietta, GA 30060


Dear Mr. Jones:

At the request of J. E. Walsh, enclosed is a copy of the recognized procedure for obtaining airborne asbestos fiber counts. Along with that is a list of equipment needed to perform these counts. If you intend only to obtain these counts and have them analyzed elsewhere, you only need the equipment marked with a red line. A substitution that can be easily made is the soap film flowmeter. One can cut the bottom of a graduate and rig a flowmeter without spending \$40.00.

Please let us know if we can be of any further assistance. Simply contact Mr. Walsh at Union Carbide's Atlanta Sales Office.

We look forward to serving you.

Very truly yours,


Edward J. Kleber
Customer Service Representative

Enclosure

cc: J. E. Walsh

/ds

