

by General Motors Corporation have contained warnings relative to asbestos exposure. Since model year 1977 (i.e., 1976) all service manuals prepared by General Motors Corporation which contain sections dealing with brakes have contained warnings related to asbestos exposure. See answer to Interrogatory No. 10(e), supra.

- (b) See answer to Interrogatory No. 32(a), supra.
- (c) See answer to Interrogatory No. 32(a), supra.
- (d) See answer to Interrogatory No. 32(a), supra.
- (e) See answer to Interrogatory No. 32(a), supra.

8002 0539