

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



(31)

C39

10720
10260
460

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-88

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 2242	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		6191		A. State Manifest Document Number 00-1145-14		
4. Generator's Phone (409) 945-7411		US EPA ID Number TXD 000 461 533		B. State Generator's ID 30689		
5. Transporter 1 Company Name UNION CARBIDE CORPORATION		102		C. State Transporter's ID 30689		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (409) 945-7411		
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 249		E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID 39036		
				H. Facility's Phone (409) 935-4787		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a.	WASTE ASBESTOS, ORM-E, NA9189	21	BAGS	.28	T	17075
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
CLASS INH		WASTE-SHIPMENT				
15. Special Handling Instructions and Additional Information		NO USEPA Hazardous Waste Present				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.		Date				
Printed/Typed Name S RODRIGUEZ		Signature S Rodriguez			Month Day Year 10 2 85	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date				
Printed/Typed Name Jerry DAVIL		Signature Jerry Davil			Month Day Year 10 2 85	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date				
Printed/Typed Name		Signature			Month Day Year	
19. Discrepancy Indication Space		UCTC 01568				
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.		Date				
Printed/Typed Name		Signature			Month Day Year 10 2 85	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711 953



Form approved. OMB No. 2000-0404. Expires 7-31-86

Please print or type. (Form designed for use on elite (12-pitch) typewriter)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533		Manifest Document No. 2461		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.							
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590						A. State Manifest Document Number 00114515									
4. Generator's Phone (409) 945-7411						B. State Generator's ID 30689									
5. Transporter 1 Company Name UNION CARBIDE CORPORATION						C. State Transporter's ID 30689									
6. Transporter 1 US EPA ID Number TXD 000 461 533						D. Transporter's Phone (409) 945-7411									
7. Transporter 2 Company Name						E. State Transporter's ID									
8. Transporter 2 US EPA ID Number						F. Transporter's Phone									
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOCP 127 SOUTH, TEXAS CITY, TX						G. State Facility's ID 39036									
10. Facility US EPA ID Number TXD 000 835 249						H. Facility's Phone (409) 935-4781									
11A. HM		11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.			
		WASTE ASBESTOS, ORM-E, NA9189				59 BAGS		69 T				17075			
		CLASS INH													
		WASTE SHIPMENT													
		NO USEPA Hazardous													
J. Additional Descriptions for Materials Present						K. Handling Codes for Wastes Listed Above									
15. Special Handling Instructions and Additional Information															
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.															
Printed/Typed Name SKODRIGUEZ						Signature SKODRIGUEZ						Date 10/4/55			
17. Transporter 1 Acknowledgement of Receipt of Materials						Printed/Typed Name BJ LLOYD						Signature BJ LLOYD		Date 10/4/55	
18. Transporter 2 Acknowledgement of Receipt of Materials						Printed/Typed Name						Signature		Date	
19. Discrepancy Indication Space															
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.															
Printed/Typed Name						Signature						Date 10/4/55			

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved. OMB No. 2000-0404. Expires 7-31-86

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 12424	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00-114816		
4. Generator's Phone 409 945-7411				B. State Generator's ID 30689		
5. Transporter 1 Company Name UNION CARBIDE CORPORATION				C. State Transporter's ID 30689		
6. US EPA ID Number TXD 000 461 533				D. Transporter's Phone 409 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX				G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 935 249				H. Facility's Phone 409 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	WASTE ASBESTOS, ORM-E, NA9182	45 BAGS	58	7	#1207	
CLASS INH						
WASTE SHIPMENT						
NO USEPA Hazardous Waste Present						
J. Additional Descriptions for Materials Listed Above						
K. Handling Codes for Wastes Listed Above						
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name S RODRIGUEZ				Signature S Rodriguez		
Date 10/8/93				Month Day Year		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name Terry Davlin				Signature Terry Davlin		
Date 10/8/93				Month Day Year		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name				Signature		
Date				Month Day Year		
19. Discrepancy Indication Space						
UCTC 01570						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name				Signature		
Date 10/8/93				Month Day Year		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		TXD 000 461 533	1550	A. State Manifest Document Number 00114317	
4. Generator's Phone (409) 945-7411				B. State Generator's ID 30689	
5. Transporter 1 Company Name UNION CARBIDE CORPORATION		6. US EPA ID Number TXD 000 461 533		C. State Transporter's ID 30689	
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (9) 945-7411	
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 035 249		E. State Transporter's ID	
				F. Transporter's Phone	
				G. State Facility's ID 39036	
				H. Facility's Phone (409) 935-278	
11A. HM	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. WASTE ASBESTOS, ORM-E, NA9189-W	49	61	T	1707
	b. CLASS INH				
	c. WASTE SHIPMENT				
	d. NO USEPA Hazardous Waste Present				
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above			
16. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.					
Printed/Typed Name S RODRIGUEZ		Signature S Rodriguez		Date 10/3/85	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature Jerry Daulton		Date 10/3/85	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date	
19. Discrepancy Indication Space		UCTC 01571			
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.					
Printed/Typed Name		Signature		Date 10/3/85	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		4. Generator's Phone (409) 945-7411	5. US EPA ID Number TXD 000 461 533	A. State Manifest Document Number 00 114516		
5. Transporter 1 Company Name UNION CARBIDE CORPORATION		6. US EPA ID Number TXD 000 461 533	B. State Generator's ID 30689			
7. Transporter 2 Company Name		8. US EPA ID Number	C. State Transporter's ID 30689			
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 107 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TKD 000 835 249	D. Transporter's Phone (409) 945-7411			
			E. State Transporter's ID			
			F. Transporter's Phone			
			G. State Facility's ID 39036			
			H. Facility's Phone (409) 935-478			
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a.	WASTE ASBESTOS, ORM-E, NA9189		1	66	T	1707
b.	CLASS INH					
c.	WASTE SHIPMENT					
d.	NO USEPA Hazardous Waste Present					
J. Additional Descriptions for Materials Listed Above			K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name SKODKIGUEZ			Signature A. Skodkiguez		Date 10/8/82	
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature J. Davila		Date 10/8/82	
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date	
19. Discrepancy Indication Space			UCTC 01572			
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name			Signature		Date	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711 951



Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		TXD 000 461 533	12405		A. State Manifest Document Number 00114315
4. Generator's Phone (409) 945-7411					B. State Generator's ID 30689
5. Transporter 1 Company Name UNION CARBIDE CORPORATION		TXD 000 461 533			C. State Transporter's ID 30689
7. Transporter 2 Company Name					D. Transporter's Phone (409) 945-7411
					E. State Transporter's ID
					F. Transporter's Phone
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 107 SOUTH, TEXAS CITY, TX		TXD 000 461 533			G. State Facility's ID 39036
					H. Facility's Phone (409) 935-4783
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. WASTE ASBESTOS, ORM-E, NA9189	32	39	T	17075
	b. CLASS INH				
	c. WASTE SHIPMENT				
	d. NO USEPA Hazardous Waste Present				
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.		Date			
Printed/Typed Name S RODRIGUEZ		Signature S Rodriguez		Month Day Year 12 9 85	
17. Transporter 1 Acknowledgement of Receipt of Materials		Date			
Printed/Typed Name C. C. CALLIS		Signature C. C. Callis		Month Day Year 12 9 85	
18. Transporter 2 Acknowledgement of Receipt of Materials		Date			
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space		UCTC 01573			
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.		Date			
Printed/Typed Name		Signature		Month Day Year	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address		TXD 000 461 533		A. State Manifest Document Number		00 165218	
UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		BLDG. 24		B. State Generator's ID		30689	
4. Generator's Phone (409) 945-7411		5. Transporter 1 Company Name		C. State Transporter's ID		30689	
UNION CARBIDE CORPORATION		TXD 000 461 533		D. Transporter's Phone (409) 945-7411			
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Transporter's ID			
9. Designated Facility Name and Site Address		10. US EPA ID Number		G. State Facility ID		39036	
GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX		TXD 000 835 249		H. Facility's Phone (409) 935-4783			
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.		
	a. Insulation/Asbestos	1	BA	47 T	170760		
	b.						
	c.						
	d.						
16. Additional Descriptions for this Shipment		17. Handling Codes for Wastes Listed Above					
CLASS INH WASTE SHIPMENT							
18. Special Handling Instructions and Additional Information							
NO USEPA Hazardous Waste Present							
19. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.							
Printed/Typed Name		Signature		Date			
Gloria Matlage		Gloria Matlage		10/11/85			
SCHLEATHA GRIFFIN							
20. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name		Signature		Date			
C. L. E. T. H. I. N.		C. L. E. T. H. I. N.		10/11/85			
21. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name		Signature		Date			
22. Discrepancy Indication Space							
UCTC 01574							
23. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.							
Printed/Typed Name		Signature		Date			
		MS		10/11/85			

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



37

11200
10360
840

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMS No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		4. Generator's Phone (409 945-7411		5. BLDG. 120		A. State Manifest Document Number 00785252		B. State Generator's ID 30689	
5. Transporter 1 Company Name UNION CARBIDE CORPORATION #102		6. US EPA ID Number TXD 000 461 533		7. Transporter 1 Phone (409 945-7411		C. State Transporter's ID 30689		D. Transporter's Phone (409 945-7411	
7. Transporter 2 Company Name		8. US EPA ID Number		9. Transporter 2 Phone		E. State Transporter's ID		F. Transporter's Phone	
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 249		11. State Facility's ID 39036		12. Facility's Phone (409 935-4783			
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	a. Insulation / Asbestos			1	BA	418	T	170750	
	b.								
	c.								
	d.								
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above					
CLASS INH WASTE SHIPMENT									
15. Special Handling Instructions and/or EPA Hazardous Waste Present				NO USEPA Hazardous Waste Present					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.									
Printed/Typed Name SCULINATHA GRIFFIN								Signature Gloria Matloga	
Date 10/16/85								Month Day Year	
17. Transporter 1 Acknowledgement of Receipt of Materials									
Printed/Typed Name B J LLOYD								Signature B J Lloyd	
Date 10/16/85								Month Day Year	
18. Transporter 2 Acknowledgement of Receipt of Materials									
Printed/Typed Name								Signature	
Date								Month Day Year	
19. Discrepancy Indication Space									
UCTC 01575									
20. Facility Owner or Operator, Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.									
Printed/Typed Name								Signature	
Date 10/16/85								Month Day Year	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. DMB No. 2000-0404. Expires 7-31-88

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. - TXD 000 461 533		2. Page 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		6. US EPA ID Number TXD 000 461 533		A. State Manifest Document Number 00114320		B. State Generator's ID 30689	
4. Generator's Phone (409 945-7411		7. Transporter 2 Company Name		C. State Transporter's ID 30689		D. Transporter's Phone (409 945-7411	
5. Transporter 1 Company Name UNION CARBIDE CORPORATION		8. US EPA ID Number		E. State Transporter's ID		F. Transporter's Phone	
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 749		G. State Facility's ID 39036		H. Facility's Phone (409 935-4788	
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No. 40	Type BAGS	13. Total Quantity 48	14. Unit T	15. Waste No. 17075	
a.	WASTE ASBESTOS, ORM-E, NA9189						
b.							
c.							
d.							
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.							
Printed/Typed Name XX S RODRIGUEZ						Date 11/4/85	
Signature S Rodriguez							
17. Transporter 1 Acknowledgement of Receipt of Materials						Date 11/4/85	
Printed/Typed Name E WILLIAMS						Signature E Williams	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date	
Printed/Typed Name						Signature	
19. Discrepancy Indication Space							
UCTC 01576							
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.							
Printed/Typed Name						Date 11/4/85	
Signature [Signature]							

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved. OMB No. 2000-0404. Expires 7-31-86

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		TXD 000 461 533	12461	A. State Manifest Document Number 00 114341		
4. Generator's Phone (409 945-7411		5. Transporter 1 Company Name UNION CARBIDE CORPORATION		B. State Generator's ID 30689		
6. US EPA ID Number TXD 000 461 533		7. Transporter 2 Company Name		C. State Transporter's ID 30689		
8. US EPA ID Number		9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LCOP 197 SOUTH, TEXAS CITY, TX		D. Transporter's Phone (409) 945-7411		
10. US EPA ID Number TXD 000 835 249		11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) WASTE ASBESTOS, ORM-E, NA9189		E. State Transporter's ID		
12. Containers No. Type 52 BAGS		13. Total Quantity 71		F. Transporter's Phone		
14. Unit T		15. Waste No. 17075		G. State Facility's ID 39036		
16. CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present		17. Additional Descriptions for Materials Listed Above		H. Facility's Phone (409) 935-4783		
18. Special Handling Instructions and Additional Information		19. Generator's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.		I. Handling Codes for Wastes Listed Above		
20. Printed/Typed Name SKODRIGUEZ		21. Signature [Signature]		Date 11/5/85		
22. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name E. WILLIAMS		23. Signature [Signature]		Date 11/5/85		
24. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		25. Signature		Date		
26. Discrepancy Indication Space		27. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.		Date		
28. Printed/Typed Name AMY REID		29. Signature [Signature]		Date 11/5/85		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved. OMB No. 2000-0404. Expires 7-31-86

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address		TXD 000 461 533		A. State Manifest Document Number 00114323		
UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		B164		B. State Generator's ID 30689		
4. Generator's Phone (409) 945-7411		5. Transporter 1 Company Name		C. State Transporter's ID 30689		
UNION CARBIDE CORPORATION		TXD 000 461 533		D. Transporter's Phone (409) 945-7411		
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Transporter's ID		
9. Designated Facility Name and Site Address		10. US EPA ID Number		F. Transporter's Phone		
GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX		TXD 000 835 240		G. State Facility's ID 39036		
H. Facility's Phone (409) 935-4787		11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type		
WASTE ASBESTOS, ORM-E, NA9189		36		BACS		
CLASS INH						
WASTE SHIPMENT						
NO USEPA Hazardous Waste Present						
13. Additional Descriptions for Materials Listed Above		14. Handling Codes for Wastes Listed Above				
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.		Printed/Typed Name SKODRIQUEZ		Signature Rodriguez		
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name E. Williams		Signature E. Williams		
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature		
19. Discrepancy Indication Space				UCTC 01578		
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.		Printed/Typed Name		Signature		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 2-100	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00 114324		
4. Generator's Phone (409) 945-7411				B. State Generator's ID 30689		
5. Transporter 1 Company Name UNION CARBIDE CORPORATION				C. State Transporter's ID 30689		
6. Transporter 1 US EPA ID Number TXD 000 461 533				D. Transporter's Phone (409) 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. Transporter 2 US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX				10. US EPA ID Number TXD 000 835 249		
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers No. Type	13. Total Quantity Unit	14. Waste No.
a. WASTE ASBESTOS, ORM-E, NA9189				52 BAGS	43 T	1907
b. CLASS INH						
c. WASTE SHIPMENT						
d. NO USEPA Hazardous Waste Present						
J. Additional Descriptions for Materials Listed Above				K. Additional Descriptions for Materials Listed Above		
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name SKODRIGUEZ				Signature A. Rodriguez		Date 11/6/85
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name E. WILLIAMS		Date 11/6/85
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Date
19. Discrepancy Indication Space				UCTC 01579		
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as follows				Printed/Typed Name		Date

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



(27)

11400
10340
19603
1267060

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-040. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		BLDG. 144		A. State Manifest Document Number 00165331		
4. Generator's Phone (409 945-7411)		6. US EPA ID Number TXD 000 461 533		B. State Generator's ID 30689		
5. Transporter 1 Company Name UNION CARBIDE CORPORATION #1021		8. US EPA ID Number		C. State Transporter's ID 30689		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (945-7411)		
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 240		E. State Transporter's ID 39036		
11A. HM		11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) Insulation / Asbestos		12. Containers No. Type 1 BA		13. Total Quantity 58
b.				14. Unit T		15. Waste No. 170750
c.						
d.						
J. Additional Descriptions for Materials Listed Above		K. Hazardous Codes for Wastes Listed Above				
CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name Gloria Matlage		Signature Gloria Matlage		Date 11/13/85		
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature E. Williams		Date 11/13/85		
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date		
19. Discrepancy Indication Space		Signature		Date		
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Signature		Date		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



10580
10240
340

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0464. Expires 7-31-85

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590			A. State Manifest Document Number 00-114324		
4. Generator's Phone (409 945-7411			B. State Generator's ID 30689		
5. Transporter 1 Company Name UNION CARBIDE CORPORATION			C. State Transporter's ID 30689		
6. US EPA ID Number TXD 000 461 533			D. Transporter's Phone (409) 945-7411		
7. Transporter 2 Company Name			E. State Transporter's ID		
8. US EPA ID Number			F. Transporter's Phone		
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, 'LA MARQUE', TX 77568 LOCT 197 SOUTH, TEXAS CITY, TX			G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 835 249			H. Facility's Phone (409) 935-478		
11A. HM	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a.	WASTE ASBESTOS, ORN-E, NA9189	10 BAGS	21	7	1707
b.	CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present				
c.					
d.					
J. Additional Descriptions for Materials Listed Above			K. Handling Codes for Wastes Listed Above		
15. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.					
Printed/Typed Name RODRIGUEZ			Signature [Signature]		Date 11/15/85
17. Transporter 1 Acknowledgement of Receipt of Materials			Date		
Printed/Typed Name [Signature]			Signature [Signature]		Month Day Year 11/15/85
18. Transporter 2 Acknowledgement of Receipt of Materials			Date		
Printed/Typed Name			Signature		Month Day Year
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted below.					
Printed/Typed Name			Signature [Signature]		Date 11/15/85

UCTC 01581

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved: OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533		Manifest Document No. 2471		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.			
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590						A. State Manifest Document Number 00-114825					
4. Generator's Phone (409) 945-7411						B. State Generator's ID 30689					
5. Transporter 1 Company Name UNION CARBIDE CORPORATION						C. State Transporter's ID 30689					
6. Transporter 1 US EPA ID Number TXD 000 461 533						D. Transporter's Phone (409) 945-7411					
7. Transporter 2 Company Name						E. State Transporter's ID					
8. Transporter 2 US EPA ID Number						F. Transporter's Phone					
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX						G. State Facility's ID 39036					
10. Facility US EPA ID Number TXD 000 835 249						H. Facility's Phone (409) 935-478					
11A. HM		11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.	
		a. WASTE ASBESTOS, ORM-E, NA9189		59 BARS		102		T		1707	
		b. CLASS INH									
		c. WASTE SHIPMENT									
		d. NO USEPA Hazardous Waste Present									
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above					
15. Special Handling Instructions and Additional Information											
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.											
Printed/Typed Name: RODRIGUEZ						Signature: [Signature] Date: 11/19/85					
17. Transporter 1 Acknowledgement of Receipt of Materials											
Printed/Typed Name: E. WILLIAMS						Signature: [Signature] Date: 11/19/85					
18. Transporter 2 Acknowledgement of Receipt of Materials											
Printed/Typed Name:						Signature: [Signature] Date:					
19. Discrepancy Indication Space											
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 18.											
Printed/Typed Name:						Signature: [Signature] Date: 11/19/85					

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved. OMB No. 2000-0404 Expires 7-31-88

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 242	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00-114526		
4. Generator's Phone (409 945-7411)				B. State Generator's ID 30689		
5. Transporter 1 Company Name UNION CARBIDE CORPORATION				C. State Transporter's ID 30689		
6. US EPA ID Number TXD 000 461 533				D. Transporter's Phone (409) 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX				G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 835 249				H. Facility's Phone (409) 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
a.	WASTE ASBESTOS, ORM-E, NA9189	44	BAGS .54	7	17075	
b.	CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present					
c.						
d.						
J. Additional Descriptions for Materials Listed Above						
K. Handling Codes for Wastes Listed Above						
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name S RODRIGUEZ				Signature S Rodriguez		
17. Transporter 1 Acknowledgement of Receipt of Materials				Date 11/21/85		
Printed/Typed Name E WILLIAMS				Signature E Williams		
18. Transporter 2 Acknowledgement of Receipt of Materials				Date		
Printed/Typed Name				Signature		
19. Discrepancy Indication Space				UCTC 01583		
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name				Signature		
Date				Month Day Year 11/21/85		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved, OMB No. 2000-0404, Expires 7-31-88

Please print or type. (Form designed for use on elite (12-pitch) typewriter)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590 4. Generator's Phone (409) 945-7411						A. State Manifest Document Number 00114321			
5. Transporter 1 Company Name UNION CARBIDE CORPORATION 6. Transporter 1 US EPA ID Number TXD 000 461 533						B. State Generator's ID 30689			
7. Transporter 2 Company Name 8. Transporter 2 US EPA ID Number						C. State Transporter's ID 30689			
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOCP 107 SOUTH, TEXAS CITY, TX 77568						D. Transporter's Phone (409) 945-7411			
10. US EPA ID Number						E. State Transporter's ID			
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)						F. Transporter's Phone			
12. Containers						G. State Facility's ID			
13. Total Quantity						H. Facility's Phone			
14. Unit						I. Waste No.			
15. WASTE ASBESTOS, ORM-E, NA9189						J. Handling Codes for Wastes Listed Above			
16. CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present						K. Handling Codes for Wastes Listed Above			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.									
Printed/Typed Name K. RODRIGUEZ						Signature K. Rodriguez		Date 12/9/85	
17. Transporter 1 Acknowledgement of Receipt of Materials						Signature K. Rodriguez		Date 12/9/85	
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature K. Rodriguez		Date 12/9/85	
19. Discrepancy Indication Space						UCTC 01584			
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						Date 12/9/85			

Form approved. OMB No. 2000-0404. Expires 7-31-86

GENERATION

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved. OMB No. 2000-0404. Expires 7-31-86

Please print or type. (Form designed for use on elks (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. B-24	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590		6. US EPA ID Number TXD 000 461 533		A. State Manifest Document Number 00114340	
4. Generator's Phone (409) 945-7411		8. US EPA ID Number		B. State Generator's ID Number 30689	
5. Transporter 1 Company Name UNION CARBIDE CORPORATION		10. US EPA ID Number		C. State Transporter's ID 30689	
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (409) 945-7411	
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 249		E. State Transporter's ID 30689 F. Transporter's Phone 39036 H. Facility's Phone (409) 935-478	
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Type	14. Total Quantity	15. Unit Wt/Vol
	WASTE ASBESTOS, ORM-E, NA9189	65	BAGS	777	1207
CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present					
J. Additional Descriptions for Waste Present					
K. Handling Codes for Wastes Listed Above					
15. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.					
Printed/Typed Name XX RODRIGUEZ		Signature Rodriguez		Date 12/10/85	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature TUCKER		Date 12/10/85	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date	
19. Discrepancy Indication Space		Signature		Date	
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.		Signature		Date	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533		Manifest Document No. 11460 10220 10220 240		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590				4. Generator's Phone (409) 945-7411		A. State Manifest Document Number 000114825		B. State Generator's ID 30689	
5. Transporter 1 Company Name UNION CARBIDE CORPORATION				6. US EPA ID Number TXD 000 461 533		C. State Transporter's ID 30689		D. Transporter's Phone (909) 945-7411	
7. Transporter 2 Company Name				8. US EPA ID Number		E. State Transporter's ID		F. Transporter's Phone	
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOCAL 107 SOUTH, TEXAS CITY, TX 77568				10. US EPA ID Number		G. State Facility's ID 39036		H. Facility's Phone (409) 935-478	
11A. HM		11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers No. Type		13. Total Quantity	
		a. WASTE ASBESTOS, ORM-E, NA9189				61 BAGS		1.62 T	
		b.							
		c.							
		d.							
		CLASS INH WASTE SHIPMENT NO USEPA Hazardous							
J. Additional Descriptions for Materials Waste Present						K. Handler Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						Date			
Printed/Typed Name RODRIGUEZ						Signature Rodriguez		Month Day Year 12/19/85	
17. Transporter 1 Acknowledgement of Receipt of Materials						Date			
Printed/Typed Name STEVE SANDRA						Signature		Month Day Year 12/19/85	
18. Transporter 2 Acknowledgement of Receipt of Materials						Date			
Printed/Typed Name						Signature		Month Day Year	
19. Discrepancy Indication Space						UCTC 01587			
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 18.						Date			
Printed/Typed Name						Signature B. M. Stults		Month Day Year 12/19/85	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



370 12320
10320
2000

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-8

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 03024	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address ION CARBIDE CORPORATION O. BOX 471, TEXAS CITY, TX 77590		4. Generator's Phone (99) 945-7411		A. State Manifest Document Number TXD 000 16 54 94		
5. Transporter 1 Company Name ION CARBIDE CORPORATION #102		6. US EPA ID Number TXD 000 461 533		B. State Generator's ID TXD 000 461 533		
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID TXD 000 461 533		
9. Designated Facility Name and Site Address LF COAST WASTE DISPOSAL AUTHORITY O. BOX 1026, LA MARQUE, TX 77568 OP 197 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 249		D. State Facility's ID TXD 000 835 249		
				E. Facility's Phone (409) 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	a. Waste Asbestos, OR M-E, NA9189	73	BA 1.04	T	170756	
	b.					
	c.					
	d.					
CLASS INH WASTE SHIPMENT						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name NINEATHA RODRIGUEZ		Signature Gloria Matlage		Date 12/1/88		
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature Lock Johnson		Date 12/1/88		
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date		
19. Discrepancy Indication Space		UCTC 01588				
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.		Signature		Date		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0804. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 12360 10320 2040	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590			A. State Manifest Document Number 00165488			
4. Generator's Phone (409) 945-7411			B. State Generator's ID 30689			
5. Transporter 1 Company Name UNION CARBIDE CORPORATION			C. State Transporter's ID 30689			
6. US EPA ID Number TXD 000 461 533			D. Transporter's (Phone) 945-7411			
7. Transporter 2 Company Name			E. State Transporter's ID			
8. US EPA ID Number			F. Transporter's Phone			
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 PO BOX 197 SOUTH, TEXAS CITY, TX			10. US EPA ID Number TXD 000 835 249		G. State Facility's ID 39036 H. Facility's Phone (409) 935-4783	
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Type	14. Total Quantity	15. Unit Wt/Vol	16. Waste No.
a.	WASTE ASBESTOS, ORM-E NA9189	71	EA	1.08	T	170750
b.						
c.						
d.						
17. Special Handling Instructions and Additional Information 18. Additional Description for Materials Listed Above 19. Additional Handling Instructions for Waste Listed Above 20. Special Handling Instructions and Additional Information 21. Special Handling Instructions and Additional Information 22. Special Handling Instructions and Additional Information 23. Special Handling Instructions and Additional Information 24. Special Handling Instructions and Additional Information 25. Special Handling Instructions and Additional Information 26. Special Handling Instructions and Additional Information 27. Special Handling Instructions and Additional Information 28. Special Handling Instructions and Additional Information 29. Special Handling Instructions and Additional Information 30. Special Handling Instructions and Additional Information 31. Special Handling Instructions and Additional Information 32. Special Handling Instructions and Additional Information 33. Special Handling Instructions and Additional Information 34. Special Handling Instructions and Additional Information 35. Special Handling Instructions and Additional Information 36. Special Handling Instructions and Additional Information 37. Special Handling Instructions and Additional Information 38. Special Handling Instructions and Additional Information 39. Special Handling Instructions and Additional Information 40. Special Handling Instructions and Additional Information 41. Special Handling Instructions and Additional Information 42. Special Handling Instructions and Additional Information 43. Special Handling Instructions and Additional Information 44. Special Handling Instructions and Additional Information 45. Special Handling Instructions and Additional Information 46. Special Handling Instructions and Additional Information 47. Special Handling Instructions and Additional Information 48. Special Handling Instructions and Additional Information 49. Special Handling Instructions and Additional Information 50. Special Handling Instructions and Additional Information 51. Special Handling Instructions and Additional Information 52. Special Handling Instructions and Additional Information 53. Special Handling Instructions and Additional Information 54. Special Handling Instructions and Additional Information 55. Special Handling Instructions and Additional Information 56. Special Handling Instructions and Additional Information 57. Special Handling Instructions and Additional Information 58. Special Handling Instructions and Additional Information 59. Special Handling Instructions and Additional Information 60. Special Handling Instructions and Additional Information 61. Special Handling Instructions and Additional Information 62. Special Handling Instructions and Additional Information 63. Special Handling Instructions and Additional Information 64. Special Handling Instructions and Additional Information 65. Special Handling Instructions and Additional Information 66. Special Handling Instructions and Additional Information 67. Special Handling Instructions and Additional Information 68. Special Handling Instructions and Additional Information 69. Special Handling Instructions and Additional Information 70. Special Handling Instructions and Additional Information 71. Special Handling Instructions and Additional Information 72. Special Handling Instructions and Additional Information 73. Special Handling Instructions and Additional Information 74. Special Handling Instructions and Additional Information 75. Special Handling Instructions and Additional Information 76. Special Handling Instructions and Additional Information 77. Special Handling Instructions and Additional Information 78. Special Handling Instructions and Additional Information 79. Special Handling Instructions and Additional Information 80. Special Handling Instructions and Additional Information 81. Special Handling Instructions and Additional Information 82. Special Handling Instructions and Additional Information 83. Special Handling Instructions and Additional Information 84. Special Handling Instructions and Additional Information 85. Special Handling Instructions and Additional Information 86. Special Handling Instructions and Additional Information 87. Special Handling Instructions and Additional Information 88. Special Handling Instructions and Additional Information 89. Special Handling Instructions and Additional Information 90. Special Handling Instructions and Additional Information 91. Special Handling Instructions and Additional Information 92. Special Handling Instructions and Additional Information 93. Special Handling Instructions and Additional Information 94. Special Handling Instructions and Additional Information 95. Special Handling Instructions and Additional Information 96. Special Handling Instructions and Additional Information 97. Special Handling Instructions and Additional Information 98. Special Handling Instructions and Additional Information 99. Special Handling Instructions and Additional Information 100. Special Handling Instructions and Additional Information						
15. Special Handling Instructions and Additional Information 16. Special Handling Instructions and Additional Information 17. Special Handling Instructions and Additional Information 18. Special Handling Instructions and Additional Information 19. Special Handling Instructions and Additional Information 20. Special Handling Instructions and Additional Information 21. Special Handling Instructions and Additional Information 22. Special Handling Instructions and Additional Information 23. Special Handling Instructions and Additional Information 24. Special Handling Instructions and Additional Information 25. Special Handling Instructions and Additional Information 26. Special Handling Instructions and Additional Information 27. Special Handling Instructions and Additional Information 28. Special Handling Instructions and Additional Information 29. Special Handling Instructions and Additional Information 30. Special Handling Instructions and Additional Information 31. Special Handling Instructions and Additional Information 32. Special Handling Instructions and Additional Information 33. Special Handling Instructions and Additional Information 34. Special Handling Instructions and Additional Information 35. Special Handling Instructions and Additional Information 36. Special Handling Instructions and Additional Information 37. Special Handling Instructions and Additional Information 38. Special Handling Instructions and Additional Information 39. Special Handling Instructions and Additional Information 40. Special Handling Instructions and Additional Information 41. Special Handling Instructions and Additional Information 42. Special Handling Instructions and Additional Information 43. Special Handling Instructions and Additional Information 44. Special Handling Instructions and Additional Information 45. Special Handling Instructions and Additional Information 46. Special Handling Instructions and Additional Information 47. Special Handling Instructions and Additional Information 48. Special Handling Instructions and Additional Information 49. Special Handling Instructions and Additional Information 50. Special Handling Instructions and Additional Information 51. Special Handling Instructions and Additional Information 52. Special Handling Instructions and Additional Information 53. Special Handling Instructions and Additional Information 54. Special Handling Instructions and Additional Information 55. Special Handling Instructions and Additional Information 56. Special Handling Instructions and Additional Information 57. Special Handling Instructions and Additional Information 58. Special Handling Instructions and Additional Information 59. Special Handling Instructions and Additional Information 60. Special Handling Instructions and Additional Information 61. Special Handling Instructions and Additional Information 62. Special Handling Instructions and Additional Information 63. Special Handling Instructions and Additional Information 64. Special Handling Instructions and Additional Information 65. Special Handling Instructions and Additional Information 66. Special Handling Instructions and Additional Information 67. Special Handling Instructions and Additional Information 68. Special Handling Instructions and Additional Information 69. Special Handling Instructions and Additional Information 70. Special Handling Instructions and Additional Information 71. Special Handling Instructions and Additional Information 72. Special Handling Instructions and Additional Information 73. Special Handling Instructions and Additional Information 74. Special Handling Instructions and Additional Information 75. Special Handling Instructions and Additional Information 76. Special Handling Instructions and Additional Information 77. Special Handling Instructions and Additional Information 78. Special Handling Instructions and Additional Information 79. Special Handling Instructions and Additional Information 80. Special Handling Instructions and Additional Information 81. Special Handling Instructions and Additional Information 82. Special Handling Instructions and Additional Information 83. Special Handling Instructions and Additional Information 84. Special Handling Instructions and Additional Information 85. Special Handling Instructions and Additional Information 86. Special Handling Instructions and Additional Information 87. Special Handling Instructions and Additional Information 88. Special Handling Instructions and Additional Information 89. Special Handling Instructions and Additional Information 90. Special Handling Instructions and Additional Information 91. Special Handling Instructions and Additional Information 92. Special Handling Instructions and Additional Information 93. Special Handling Instructions and Additional Information 94. Special Handling Instructions and Additional Information 95. Special Handling Instructions and Additional Information 96. Special Handling Instructions and Additional Information 97. Special Handling Instructions and Additional Information 98. Special Handling Instructions and Additional Information 99. Special Handling Instructions and Additional Information 100. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name QUINTANA RODRIGUEZ			Signature [Signature]		Date 12/1/85	
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature [Signature]		Date 12/1/85	
Printed/Typed Name [Name]			Signature [Signature]		Date 12/1/85	
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature [Signature]		Date 12/1/85	
Printed/Typed Name [Name]			Signature [Signature]		Date 12/1/85	
19. Discrepancy Indication Space 20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name [Name]			Signature [Signature]		Date 12/1/85	

Form approved. OMB No. 2980-0404. Expires 7-31-86

EPA Form 8700-22 (3-84) White -original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy
TOWR-0311

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved, OMB No. 2000-0404, Expires 7-31-86

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Declaration No. 020271	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address ION CARBIDE CORPORATION O. BOX 471, TEXAS CITY, TX 77590		4. Generator's Phone 945-7411		A. State Manifest Document Number 00165496	
5. Transporter 1 Company Name ION CARBIDE CORPORATION #102		6. US EPA ID Number TXD 000 461 533		B. State Generator's ID 330689	
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID 330689	
9. Designated Facility Name and Site Address LF COAST WASTE DISPOSAL AUTHORITY O. BOX 1026, LA. MARQUE, TX 77568 PO BOX 197 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 249		D. Transporter's Phone 945-7411	
				E. State Transporter's ID	
				F. Transporter's Phone	
				G. State Facility AID 339036	
				H. Facility's Phone 409-335-4783	
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. Waste (colustor), ORM-E, NA9189	77	99	T	170750
	b.				
	c.				
	d.				
CLASS INH WASTE SHIPMENT NO USEPA Hazardous					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.					
17. Transporter 1 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name Gloria Matlage				Signature Gloria Matlage	
18. Transporter 2 Acknowledgement of Receipt of Materials				Date	
Printed/Typed Name				Signature	
19. Discrepancy Indication Space				Date	
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.				Date	
Printed/Typed Name				Signature	

Form approved: OMB No. 2000-0404. Expires 7-31-86

CREATION

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



(37) 12420
10280
1056
10280
2140

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533		Manifest Document No. 1624		2. Page 1 of 2		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address ION CARBIDE CORPORATION O. BOX 471, TEXAS CITY, TX 77590						A. State Manifest Document Number 00 165514			
4. Generator's Phone 909 945-7411						B. State Generator's ID 30689			
5. Transporter 1 Company Name ION CARBIDE CORPORATION						C. State Transporter's ID 30689			
6. US EPA ID Number TXD 000 461 533						D. Transporter's Phone 909 945-7411			
7. Transporter 2 Company Name						E. State Transporter's ID			
8. US EPA ID Number						F. Transporter's Phone			
9. Designated Facility Name and Site Address OFF COAST WASTE DISPOSAL AUTHORITY O. BOX 1026, LA MARQUE, TX 77568 PO BOX 197 SOUTH, TEXAS CITY, TX						G. State Facility's ID 10036			
10. US EPA ID Number TXD 000 835 249						H. Facility's Phone (409) 935-4783			
11A. HM		11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol	
		WASTE ASBESTOS, ORM-E, N/A 60 BA		1.11		7		170756	
b.									
c.									
d.									
CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present									
J. Additional Descriptions for Materials Listed Above									
K. Handling Codes for Wastes Listed Above									
L. Special Handling Instructions and Additional Information Pertinent to the Degree I Have Determined to be Practically Possible and I Have Selected the Method of Processing, Storage, and Disposal Currently Available to Me, Which Minimizes the Present and Future Threat to Human Health and the Environment.									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.									
Printed/Typed Name INEATHA RODRIGUEZ						Signature A. Rodriguez		Date 12/17/83	
Transporter 1 Acknowledgement of Receipt of Materials						Signature B. Rodriguez		Date 12/17/83	
Printed/Typed Name B. Rodriguez						Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials						Signature		Date	
Printed/Typed Name						Signature		Date	
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.									
Printed/Typed Name						Signature		Date 12/17/83	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



37

15620
12120
3500

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 03036	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address O. BOX 471, TEXAS CITY, TX 77590 409 945-7411			A. State Manifest Document Number 00165506		
4. Generator's Phone ()			B. State Generator's ID 30689		
5. Transporter 1 Company Name EOTRANSIDE CORPORATION			C. State Transporter's ID 0689		
6. Transporter 1 US EPA ID Number TXD 000 461 533			D. Transporter's Phone 409 945-7411		
7. Transporter 2 Company Name			E. State Transporter's ID		
8. Transporter 2 US EPA ID Number			F. Transporter's Phone		
9. Disposal Facility Name and Site Address O. BOX 1026, LA MARQUE, TX 77568 OP 197 SOUTH, TEXAS CITY, TX			G. State Facility's ID 09036		
10. Disposal Facility US EPA ID Number TXD 000 835 249			H. Facility's Phone 409 945-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	WASTE ABESIDS, ORNLS NA989	150BA	2.17	T	19075
		CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.					
Printed/Typed Name INEXTER RODRIGUEZ			Signature <i>Inexter Rodriguez</i>		Date Month Day Year 12/18/85
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature <i>LLoto R Oass</i>		Date Month Day Year 12/18/85
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature <i>William Stullken</i>		Date Month Day Year 12/18/85
19. Discrepancy Indication Space UCTC 01594					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.					
Printed/Typed Name WILLIAM STULLKEN			Signature <i>William Stullken</i>		Date Month Day Year 12/18/85

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved. OMB No. 2000-0404 Expires 7-31-8

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533		Manifest Document No. 103049		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address ION CARBIDE CORPORATION O. BOX 471, TEXAS CITY, TX 77590		4. Generator's Phone 945-7411		5. State Manifest Document Number 00165519		6. State Generator's ID No. 30689		7. State Generator's Phone 945-7411	
8. Transporter 1 Company Name ION CARBIDE CORPORATION #102		9. US EPA ID Number TXD 000 461 533		10. State Transporter's ID No. 30689		11. Transporter's Phone 945-7411		12. State Transporter's ID No. 30689	
13. Transporter 2 Company Name (None)		14. US EPA ID Number (None)		15. State Transporter's ID No. (None)		16. Transporter's Phone (None)		17. State Transporter's ID No. (None)	
18. Designated Facility Name and Site Address LF COAST WASTE DISPOSAL AUTHORITY O. BOX 1026, LA MARQUE, TX 77568 OP 197 SOUTH, TEXAS CITY, TX		19. US EPA ID Number TXD 000 835 249		20. State Facility ID No. 39086		21. Facility's Phone 935-4783		22. State Facility ID No. 39086	
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) Waste Asbestos, ORM-E, NA9189			12. Containers No.	13. Type BA	14. Total Quantity 0.19	15. Unit T	16. Waste No. 17095C	
CLASS INH WASTE SHIPMENT									
17. Additional Descriptions This waste is classified as Class I, Hazardous, and is subject to the requirements of the Resource Conservation and Recovery Act (RCRA) and the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). It is also subject to the requirements of the Texas Department of Water Resources (TDWR) and the Texas Department of Transportation (TxDOT). The waste is generated by the Ion Carbide Corporation and is being transported to the LF Coast Waste Disposal Authority for disposal. The waste is classified as Class I, Hazardous, and is subject to the requirements of the Resource Conservation and Recovery Act (RCRA) and the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). It is also subject to the requirements of the Texas Department of Water Resources (TDWR) and the Texas Department of Transportation (TxDOT).									
18. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.									
Printed/Typed Name Gloria Matlage		Signature Gloria Matlage		Date 12/26/85					
19. Transporter 1 Acknowledgement of Receipt of Materials		Signature E. Williams		Date 12/26/85					
19. Transporter 2 Acknowledgement of Receipt of Materials		Signature (None)		Date (None)					
19. Discrepancy Indication Space None									
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 18.									
Printed/Typed Name WILLIAM STULLKEN		Signature B. O. Stullken		Date 12/26/85					

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2005-0404. Expires 7-31.

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded area is not required by Federal law	
3. Generator's Name and Mailing Address ION CARBIDE CORPORATION O. BOX 471, TEXAS CITY, TX 77590		TXD 000 461 533	3185 811	A. State Manifest Document Number 00065655		
4. Generator's Phone (99) 945-7411				B. State Generator's ID No. 30689		
5. Transporter 1 Company Name ION CARBIDE CORPORATION #102		6. US EPA ID Number TXD 000 461 533		C. State Transporter's ID No. 30689		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (99) 945-7411		
9. Designated Facility Name and Site Address LF COAST WASTE DISPOSAL AUTHORITY O. BOX 1026, LA MARQUE, TX 77568 OP 197 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 249		E. State Transporter's ID No. 30689		
				F. Transporter's Phone		
				G. State Facility's ID No. 39036		
				H. Facility's Phone (99) 945-4711		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	a. Waste Asbestos, ORM-E, NA 9189	1. BA	84	T	17078C	
	b.					
	c.					
	d.					
CLASS INH						
WASTE						
I hereby certify that the contents of this manifest are true and accurate and that the materials described herein are properly classified, packaged, marked, and labeled, and are in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name Gloria Matlage		Signature Gloria Matlage		Date 12/26/18		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name E. Williams		Signature E. Williams		Date 12/26/18		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Date		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name WILLIAM STULLKEN		Signature Bill Stullken		Date 12/26/18		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2001-0007. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533		Manifest Document No. 10029	2. Page 12 of 12		Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address ION CARBIDE CORPORATION O. BOX 471, TEXAS CITY, TX 77590				4. Generator's Phone 99-945-7411		A. State Manifest Document Number 00065509		B. State Generator's ID 30689	
5. Transporter 1 Company Name ION CARBIDE CORPORATION #100				6. US EPA ID Number TXD 000 461 533		C. State Transporter's ID 30689		D. Transporter's Phone 945-7411	
7. Transporter 2 Company Name				8. US EPA ID Number		E. State Transporter's ID		F. Transporter's Phone	
9. Designated Facility Name and Site Address LF COAST WASTE DISPOSAL AUTHORITY O. BOX 1026, LA MARQUE, TX 77568 OP 197 SOUTH, TEXAS CITY, TX				10. US EPA ID Number TXD 000 835 249		G. State Facility's ID 30689		H. Facility's Phone 935-4783	
11A. HM	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	a. Waste Asbestos			1	BI	32	T	19023	
	b.								
	c.								
	d.								
CLASS IN WASTE SHIPMENT 16. Special Handling Instructions: I have determined that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations. 17. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations. 18. TRANSPORTER'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations. 19. Facility Owner or Operator, Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.									
Printed/Typed Name GLORIA MATLAGE				Signature Gloria Matlage		Date 1-21-18			
Printed/Typed Name E. WILLIAMS				Signature E. Williams		Date 1-21-18			
Printed/Typed Name				Signature		Date			
19. Discrepancy Indication Space				UCTC 01597					
Printed/Typed Name				Signature Bill Stillman		Date 1-21-18			



C3 40980
Pg 612 OF 1268 7680

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address FOX CARRIDE CORPORATION C. BOX 471, TEXAS CITY, TX 77590		TXD 000 431 500		A. State Manifest Document Number 00165599		
4. Generator's Phone (945-7411)		B144		B. State Generator's ID 20688		
5. Transporter 1 Company Name FOX CARRIDE CORPORATION #10		6. US EPA ID Number TXD 000 431 500	C. State Transporter's ID 0480		D. Transporter's Phone 945-7411	
7. Transporter 2 Company Name		8. US EPA ID Number	E. State Transporter's ID		F. Transporter's Phone	
9. Designated Facility Name and Site Address LE COAST WASTE DISPOSAL AUTHORITY C. BOX 1026, LA MARQUE, TX 77568 107 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 000		G. State Facility's ID 39036		H. Facility's Phone (409) 935-4783
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	1. Waste No.	
	WASTE ASBESTOS, ORM-E, NA9189	225	BA		170756	
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above			K. Handling Codes for Wastes Listed Above			
LESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE TO THE DEGREE I HAVE DETERMINED TO BE TECHNICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE RISK TO HUMAN HEALTH AND THE ENVIRONMENT. 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name		Signature		Date		
Gloria Matlage		Gloria Matlage		12/30/94		
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature		Date		
Printed/Typed Name		Signature		Month Day Year		
F. A. DUEZ, F. A. S. M. A.		F. A. DUEZ, F. A. S. M. A.		12/30/94		
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date		
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Signature		Date		
Printed/Typed Name		Signature		Month Day Year		
				12/30/94		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711 848



1d U2U C3 12300
0050Pg 613 10340
1970 of 1267 91,0

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 13128 B45	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address ECLIPSE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590		4. Generator's Phone (702) 945-7411		A. State Manifest Document Number 00165598		
5. Transporter 1 Company Name ECLIPSE CORPORATION #102		6. US EPA ID Number TXD 000 461 533		B. State Generator's ID 30689		
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID 30689		
9. Designated Facility Name and Site Address ECLIPSE WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 107 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 249		D. Transporter's Phone 945-7411		
				E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID 39036		
				H. Facility's Phone (409) 935-4783		
11A HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) HAZARDOUS ACETONES, CMT-L, N99189	12. Containers No. 70	Type HA	13. Total Quantity .98	14. Unit Wt/Vol T	1. Waste No. 170750
	b.					
	c.					
	d.					
CLASS IN: WASTE SHIPMENT J. Additional Descriptions of Materials Listed Above K. Handling Codes for Wastes Listed Above LESS I AM A SMALL QUANTITY HAZARDOUS WASTE, I HAVE BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO OBTAIN A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE THE AMOUNT AND TOXICITY OF WASTES GENERATED TO THE DEGREE I HAVE DETERMINED TO BE PRACTICALLY FEASIBLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE RISK TO HUMAN HEALTH AND THE ENVIRONMENT. 15. Special Handling Instructions and Additional Information 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name Gloria Mallage		Signature Gloria Mallage		Date 02/20/86		
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature B J Lloyd		Date 02/20/86		
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date		
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 18.						
Printed/Typed Name		Signature		Date 02/20/86		

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 753 333	Manifest Document No. 11410	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address HIGH CARBIDE CORPORATION P.O. BOX 171, TEXAS CITY, TX 77590 409 245-7411				A. State Manifest Document Number 112 00 241071	
4. Generator's Phone () 409 245-7411				B. State Generator's ID 30680	
5. Transporter 1 Company Name HIGH CARBIDE CORPORATION #102				C. State Transporter's ID 30008	
6. US EPA ID Number TXD 000 491 533				D. Transporter's Phone () 409 245-7411	
7. Transporter 2 Company Name				E. State Transporter's ID	
8. US EPA ID Number				F. Transporter's Phone	
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX				G. State Facility's ID 39036	
10. US EPA ID Number TXD 000 835 242				H. Facility's Phone (409) 935-4783	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol
a. Waste Asbestos, ORM-E, NA 9189			70 BG		170750
b.					
c.					
d.					
J. Additional Descriptions for Materials Listed Above			K. Handling Codes for Wastes Listed Above		
CLASS INH WASTE SHIPMENT					
15. Special Handling Instructions and Additional Information NO USEPA Hazardous Waste Present					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of processing, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.					
Printed/Typed Name Cloria Matlage		Signature Cloria Matlage		Month Day Year 02/26/86	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name B. T. L. L. L.		Signature B. T. L. L. L.		Month Day Year 02/26/86	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space UCTC 01291					
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19. Printed/Typed Name Signature Month Day Year 02/26/86					

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087



(37) C3 / 45680
Pg 615 / 0820
of 1265 / 4860

46200
41020
3113

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590		4. Generator's Phone () 409 945-7411	5. US EPA ID Number TXD 000 451 533	A. State Manifest Document Number N2 00 243997	
6. Transporter 1 Company Name UNION CARBIDE CORPORATION #10		7. US EPA ID Number TXD 000 451 533	B. State Generator's ID 30689		
8. Transporter 2 Company Name		9. US EPA ID Number	C. State Transporter's ID 30689		
10. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 POOP 197 SOUTH, TEXAS CITY, TX TXD 000 835 240		11. US EPA ID Number	D. Transporter's Phone (409) 945-7411		
12. Containers		13. Total Quantity	14. Unit Wt/Vol	E. State Transporter's ID	
15. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		F. Transporter's Phone			
a. Waste (Chemical), ORM-E, NA9187		No.	Type	G. State Facility's ID 39036	
b.		30086	2.15 T	H. Facility's Phone (409) 935-4783	
c.					
d.					
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above			
CLASS INH					
WASTE SHIPMENT					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of processing, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.					
Printed/Typed Name Gloria Matlone		Signature Gloria Matlone		Month Day Year 02 27 86	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature		Month Day Year	
Printed/Typed Name ERASMO F. NARICHO		Signature		02 27 86	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Month Day Year	
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space UCTC 01292					
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.					
Printed/Typed Name		Signature		Month Day Year	
		C. N. S.		02 27 86	

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)



37

Form Approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 1120001	2. Page of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address PIONEER WASTE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590 409 945-7411				A. State Manifest Document Number 112 00 243991	
4. Generator's Phone ()				B. State Generator's ID 30680	
5. Transporter 1 Company Name PIONEER WASTE CORPORATION 102				C. State Transporter's ID 30680	
6. US EPA ID Number TXD 000 461 533				D. Transporter's Phone (409) 945-7411	
7. Transporter 2 Company Name				E. State Transporter's ID	
8. US EPA ID Number				F. Transporter's Phone	
9. Designated Facility Name and Site Address WILCOAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 1007 157 SOUTH, TEXAS CITY, TX TXD 000 835 249				G. State Facility's ID 39036	
10. US EPA ID Number				H. Facility's Phone (409) 935-4783	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol
a. WASTE ASBESTOS, ORM-E, NA9189			100 BA	1.11 T	17075L
b.					
c.					
d.					
J. Additional Descriptions for Materials Listed Above					
K. Additional Descriptions for Wastes Listed Above					
15. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of processing, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.					
Printed/Typed Name			Signature K. Rodriguez	Month Day Year 12/3/86	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name			Signature Howard W. Bell	Month Day Year 10/2/86	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name			Signature	Month Day Year	
19. Discrepancy Indication Space					
UCTC 01293					
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.					
Printed/Typed Name			Signature W. M. Y.	Month Day Year 12/3/86	

U.S. ENVIRONMENTAL PROTECTION AGENCY
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 161 533	Manifest Document No. B17	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590 4. Generator's Phone (409) 945-7411				A. State Manifest Document Number 1200243950	
5. Transporter 1 Company Name UNION CARBIDE CORPORATION 6. US EPA ID Number TXD 000 161 533				B. State Generator's ID 30689	
7. Transporter 2 Company Name 8. US EPA ID Number				C. State Transporter's ID 30085	
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 10. US EPA ID Number TXD 000 635 242				D. Transporter's Phone (409) 945-7411	
				E. State Transporter's ID	
				F. Transporter's Phone	
				G. State Facility's ID 39036	
				H. Facility's Phone (409) 935-4783	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers		13. Total Quantity	14. Unit Wt/Vol
a. WASTE ASBESTOS, ORM-E, NA9184		No. Type			
		100 BA		1.3BT	170750
b.					
c.					
d.					
J. Additional Descriptions for Materials Listed Above					
CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present					
15. Special Handling Instructions and Additional Information					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of processing, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment. Printed/Typed Name: DRIGUES Signature: [Signature] Month Day Year: 12 23 84					
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name: [Signature] Signature: [Signature] Month Day Year: 12 23 84					
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name: [Signature] Signature: [Signature] Month Day Year: [Signature]					
19. Discrepancy Indication Space UCTC 01294					
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name: [Signature] Signature: [Signature] Month Day Year: 12 23 84					

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087



12460 0050 C3 - 124600
Pg 6/8 of 12460360

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 733	Manifest Document No. B17	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address WILSON CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590 4. Generator's Phone (409) 945-7411				A. State Manifest Document Number NO 00 243988		
5. Transporter 1 Company Name WILSON CARBIDE CORPORATION 102 6. US EPA ID Number TXD 000 461 733				B. State Generator's ID 30689		
7. Transporter 2 Company Name 8. US EPA ID Number				C. State Transporter's ID 30689		
9. Designated Facility Name and Site Address WILSON COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 10. US EPA ID Number TXD 000 835 242				D. Transporter's Phone (409) 945-7411		
				E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID 39036		
				H. Facility's Phone (409) 935-4783		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers	13. Total Quantity	14. Unit Wt/Vol	Waste No.
a. WASTE ASBESTOS, ORM-E, NA9189			No. Type			
			100 BA	1.21 T		170750
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above			K. Handling Codes for Wastes Listed Above			
CLASS INH			WASTE SHIPMENT			
15. Special Handling Instructions and Additional Information			NO USEPA Hazardous Waste Present			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of processing, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment. Printed/Typed Name: DRISCOLL Signature: [Signature] Month Day Year: 12/31/85						
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name: Howard W. Bell Signature: [Signature] Month Day Year: 12/31/85						
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name: Signature: Month Day Year:						
19. Discrepancy Indication Space UCTC 01295						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name: Signature: Month Day Year:						

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest of 1268 2820	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address UNION CARBIDE CORPORATION P. O. BOX 471, TEXAS CITY, TX 77590 4. Generator's Phone (409) 945-7411				A. State Manifest Document Number 12 00 243987	
5. Transporter 1 Company Name UNION CARBIDE CORPORATION 100 6. US EPA ID Number TXD 000 461 533				B. State Generator's ID 30689	
7. Transporter 2 Company Name 8. US EPA ID Number				C. State Transporter's ID 30689	
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P. O. BOX 1026, LA MARQUE, TX 77568 LOOP 197 SOUTH, TEXAS CITY, TX TXD 000 835 219				D. Transporter's Phone (409) 945-7411	
10. US EPA ID Number				E. State Transporter's ID	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				F. Transporter's Phone	
a. WASTE ASBESTOS, ORN-E, NA9189				G. State Facility's ID 39036	
b.				H. Facility's Phone (409) 935-4783	
c.				12. Containers No. Type	
d.				13. Total Quantity	
e.				14. Unit Wt/Vol	
f.				Waste No. (3)	
g.				15. Special Handling Instructions and Additional Information	
h.				16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of processing, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.	
i.				17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Year	
j.				18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Year	
k.				19. Discrepancy Indication Space	
l.				20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19. Printed/Typed Name Signature Month Day Year	

CLASS INH
WASTE SHIPMENT
NO USEPA Hazardous
Waste Present

UCTC 01296

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



C3
Pg 620
of 1268
23120
4140

Please print or type. (Form designed for use on site (12-pitch) typewriter)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. B139	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address OFFSHORE WASTE DISPOSAL AUTHORITY P.O. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00165402		
4. Generator's Phone 945-7411				B. State Generator's ID 30689		
5. Transporter 1 Company Name MICHAEL STEEL				C. State Transporter's ID 00009		
6. US EPA ID Number TXD 000 461 533				D. Transporter's Phone 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address OFFSHORE WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568				G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 835 240				H. Facility's Phone (409) 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	1. Waste No.
	a. Insulation Ashes	1	BA	2.18	T	170750
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above		
LESS I AM A SMALL QUANTITY GENERATOR, I HAVE BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE OFFSHORE WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA. I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE WASTE. 15. Special Handling Instructions and Additional Information: I HAVE DETERMINED TO DISPOSE OF THE WASTE BY THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY IN USE. THIS METHOD MINIMIZES THE PRESENT AND FUTURE HAZARD TO HUMAN HEALTH AND THE ENVIRONMENT. 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name Gloria Matlage				Signature Gloria Matlage		Date 01/03/88
17. Transporter 1 Acknowledgement of Receipt of Materials				Date		
Printed/Typed Name Brooks Matlage				Signature Brooks Matlage		Date 01/03/88
18. Transporter 2 Acknowledgement of Receipt of Materials				Date		
Printed/Typed Name				Signature		Date Month Day Year
19. Discrepancy Indication Space						
UCTC 01297						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name				Signature		Date Month Day Year

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



3
Pg 6260
of 1268

15860
22120
3740

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533		Manifest Document No. B139182		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address HIGH CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590						A. State Manifest Document Number 00165652				
4. Generator's Phone (09) 945-7411						B. State Generator's ID 30689				
5. Transporter 1 Company Name HIGH CARBIDE CORPORATION						6. US EPA ID Number TXD 000 461 533		C. State Transporter's ID 30689		
7. Transporter 2 Company Name						8. US EPA ID Number		D. Transporter's Phone (09) 945-7411		
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 BOX 197 SOUTH, TEXAS CITY, TX						10. US EPA ID Number TXD 000 835 249		E. State Transporter's ID		
								F. Transporter's Phone		
								G. State Facility's ID 39036		
								H. Facility's Phone (409) 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)					12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	a. Insulation / Asbestos					1 BH	1.52	T	170750	
	b.									
	c.									
	d.									
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above				
PLEASE I AM A STATE QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO OBTAIN A HAZARDOUS WASTE IDENTIFICATION CERTIFICATION UNDER SECTION 3002(B) OF THE FEDERAL HAZARDOUS WASTE MANAGEMENT ACT. I HAVE A PROGRAM IN PLACE TO REDUCE THE AMOUNT OF HAZARDOUS WASTE GENERATED AND TO SELECT THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE RISK TO HUMAN HEALTH AND THE ENVIRONMENT.										
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.										
Printed/Typed Name Gloria Matlage								Signature Gloria Matlage		Date 01/13/86
17. Transporter 1 Acknowledgement of Receipt of Materials										
Printed/Typed Name BROOKS MARCUS								Signature MARCUS BROOKS		Date 01/03/86
18. Transporter 2 Acknowledgement of Receipt of Materials										
Printed/Typed Name								Signature		Date
19. Discrepancy Indication Space										
UCTC 01298										
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.										
Printed/Typed Name								Signature		Date 1/3/86

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



C3
Pg 622 of 1365
27680
31300
5880

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 451 533	Manifest Document No. 3183 B139	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address ION CARRIER CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00165653		
4. Generator's Phone (09) 945-7411				B. State Generator's ID 30680		
5. Transporter 1 Company Name <i>Midwest</i> ION CARRIER CORPORATION				C. State Transporter's ID 30680		
7. Transporter 2 Company Name				D. Transporter's Phone 945-7411		
8. US EPA ID Number				E. State Transporter's ID		
9. Designated Facility Name and Site Address LA COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 OF 107 SOUTH, TEXAS CITY, TX				F. Transporter's Phone		
10. US EPA ID Number				G. State Facility's ID 39036		
H. Facility's Phone (409) 925-4783						
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	a. <i>Insulation/Asbestos</i>	1. DT	256 T		170750	
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above						
K. Handling Codes for Wastes Listed Above						
LESS I AM A SMALL QUANTITY GENERATOR, I HAVE BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(E) OF RCRA. I HAVE A PROGRAM IN PLACE TO FOLLOW SPECIAL HANDLING INSTRUCTIONS AND ADDITIONAL INFORMATION GENERATED TO THE DECREE I HAVE DETERMINED TO BE TECHNICALLY FEASIBLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE HAZARD TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name <i>Gloria Matlage</i>				Date 01/03/86		
Signature <i>Gloria Matlage</i>						
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <i>R. L. Davis</i>				Date 01/23/86		
Signature <i>R. L. Davis</i>						
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name				Date		
Signature						
19. Discrepancy Indication Space						
UCTC 01299						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 18.						
Printed/Typed Name				Date		
Signature <i>[Signature]</i>				Month Day Year 11/3/84		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



37 C3 12200
Pg 622 of 102 10620
1520

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 13132	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address ION MARINE CORPORATION C. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00 165602		
4. Generator's Phone (00) 945-7411				B. State Generator's ID 30689		
5. Transporter 1 Company Name ION MARINE CORPORATION				C. State Transporter's ID 30689		
6. US EPA ID Number TXD 000 461 533				D. Transporter's Phone 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address LF COAST WASTE DISPOSAL AUTHORITY C. BOX 1026, LA MARQUE, TX 77568				G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 835 749				H. Facility's Phone (409) 935-4783		
11A HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	1. Waste No.
	WASTE ASBESTOS, ORM-L, NA9189	75	BA	96	7	170750
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above						
K. Handling Codes for Wastes Listed Above						
EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MINIMIZE HAZARDOUS WASTE PRESENTATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA, I ALSO CERTIFY I HAVE A PROGRAM IN PLACE TO REDUCE THE PRESENT AND FUTURE THREAT TO HUMAN HEALTH AND THE ENVIRONMENT.						
15. Special Handling Instructions and Additional Information GENERATED TO THE DEGREE I HAVE DETERMINED TO BE ECONOMICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE OR DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE THREAT TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name MARTHA RODRIGUEZ				Signature [Signature]		Date 1/9/86
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name CLEO CALLIS				Signature [Signature]		Date 1/9/86
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name				Signature		Date
19. Discrepancy Indication Space UCTC 01300						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name MICHELEAN M. LOVE				Signature [Signature]		Date 1/11/86

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711 940



Form approved. OMB No. 2000-0404. Expires 7-31-86

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 523		Manifest Document No. 1213		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.																											
3. Generator's Name and Mailing Address ICE CARRIBE CORPORATION C. BOX 471, TEXAS CITY, TX 77590						A. State Manifest Document Number 00165001																													
4. Generator's Phone (945) 945-7411						B. State Generator's ID 30680																													
5. Transporter 1 Company Name BUROE STAFF ICE CARRIBE CORPORATION 102						US EPA ID Number TXD 000 461 523		C. State Transporter's ID 30680																											
7. Transporter 2 Company Name						8. US EPA ID Number		D. Transporter's Phone 945-7411																											
9. Designated Facility Name and Site Address ICE COAST WASTE DISPOSAL AUTHORITY C. BOX 1026, LA MARQUE, TX 77568 C. BOX 1027 SOUTH, TEXAS CITY, TX						10. US EPA ID Number TXD 000 225 241		E. State Transporter's ID																											
								F. Transporter's Phone																											
								G. State Facility's ID 39036																											
								H. Facility's Phone (409) 625-4783																											
11A. HM		11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.																							
		WASTE ASBESTOS, ORM-E, NA9189				45		T		T		170750																							
		b.																																	
		c.																																	
		d.																																	
CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present																																			
J. Additional Descriptions for Materials Listed Above												K. Handling Codes for Wastes Listed Above																							
LESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE TO THE DEGREE I HAVE DETERMINED TO BE ECONOMICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE HAZARD TO HUMAN HEALTH AND THE ENVIRONMENT.																																			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.																																			
Printed/Typed Name MURRAYA RODRIGUEZ												Signature M. Rodriguez												Date 1/1/86											
17. Transporter 1 Acknowledgement of Receipt of Materials												Signature D. P. Anderson												Date 1/1/86											
18. Transporter 2 Acknowledgement of Receipt of Materials												Signature												Date											
Printed/Typed Name												Signature												Month Day Year											
19. Discrepancy Indication Space																																			
UCTC 01301																																			
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.																																			
Printed/Typed Name												Signature												Date 1/1/86											

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved. OMB No. 2000-0404. Expires 7-31-86

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address ION CANBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590		TXD 000 461 533	3103 515PT	A. State Manifest Document Number 00165573	B. State Generator's ID 30689	
4. Generator's Phone 109 1945-7411		5. Transporter 1 Company Name ION CANBIDE CORPORATION	6. US EPA ID Number TXD 000 461 533	C. State Transporter's ID 30689	D. Transporter's Phone 945-7411	
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Transporter's ID	F. Transporter's Phone	
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 OFF SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD 000 835 248		G. State Facility's ID 39036	H. Facility's Phone (409) 835-4783	
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	a. WASTE ASBESTOS, ORM-E, HA9189	60 BA	1.08	T	170750	
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above			K. Handling Codes for Wastes Listed Above			
LESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 2002(D) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE TO THE DEGREE I HAVE DETERMINED TO BE TECHNICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE HAZARD TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name MENDIANA RODRIGUEZ		Signature <i>M Rodriguez</i>		Date 7/13/86		
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature <i>[Signature]</i>		Date 7/13/86		
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Date		
19. Discrepancy Indication Space		UCTC 01302				
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name		Signature <i>[Signature]</i>		Date 7/13/86		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



Form approved. OMB No. 2000-0404. Expires 7-31-86

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address ION CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590		4. Generator's Phone (00) 045-7411		A. State Manifest Document Number 00165575		B. State Generator's ID 30689	
5. Transporter 1 Company Name ION CARBIDE CORPORATION		6. US EPA ID Number TXD 000 001 522		C. State Transporter's ID 30689		D. Transporter's Phone 045-7411	
7. Transporter 2 Company Name		8. US EPA ID Number		E. State Transporter's ID		F. Transporter's Phone	
9. Designated Facility Name and Site Address THE COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 100 SOUTH, TEXAS CITY, TX		10. US EPA ID Number		G. State Facility's ID 39036		H. Facility's Phone (409) 035-4787	
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.	
	WASTE ASBESTOS, CRM-E, NA9189	50	BA	.69 T		170750	
CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present							
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above			
UNLESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER REGULATION 3002(B) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE THE AMOUNT OF WASTE GENERATED TO THE DEGREE I HAVE DETERMINED TO BE ECONOMICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, OR DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE HAZARD TO HUMAN HEALTH AND THE ENVIRONMENT.							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.							
Printed/Typed Name J. J. Rodriguez				Signature J. J. Rodriguez		Date 1/11/86	
17. Transporter 1 Acknowledgement of Receipt of Materials				Printed/Typed Name B. J. Hall		Date 1/11/86	
18. Transporter 2 Acknowledgement of Receipt of Materials				Printed/Typed Name		Date	
19. Discrepancy Indication Space				UCTC 01303			
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 18.							
Printed/Typed Name				Signature		Date 1/11/86	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711 10 93



C3
Pg 627 of 12560
10340
2068
2090

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 13104	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address HIGH CAPELIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77550 4. Generator's Phone (000) 945-7411				A. State Manifest Document Number 00165514		
5. Transporter 1 Company Name HIGH CAPELIDE CORPORATION 102				B. State Generator's ID 30689		
6. US EPA ID Number TXD 000 461 533				C. State Transporter's ID 30588		
7. Transporter 2 Company Name				D. Transporter's Phone (000) 945-7411		
8. US EPA ID Number				E. State Transporter's ID		
9. Designated Facility Name and Site Address ULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 10. US EPA ID Number TXD 000 835 249				F. Transporter's Phone		
				G. State Facility's ID 39036		
				H. Facility's Phone (409) 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	WASTE ASBESTOS, CRM-E, HA9189	70	1.16	T	170750	
	b.					
	c.					
	d.					
CLASS INH WASTE SHIPMENT NO USEPA Hazardous Waste Present						
J. Additional Descriptions for Materials Listed Above						
K. Handling Codes for Wastes Listed Above						
UNLESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE TO THE GREATEST EXTENT PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, OR DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE HAZARD TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name WILLIAM RODRIGUEZ				Signature [Signature] Date Month Day Year 7/14/86		
17. Transporter 1 Acknowledgement of Receipt of Materials				Date		
Printed/Typed Name R. J. LLOYD				Signature [Signature] Month Day Year 7/14/86		
18. Transporter 2 Acknowledgement of Receipt of Materials				Date		
Printed/Typed Name				Signature Month Day Year		
19. Discrepancy Indication Space						
UCTC 01304						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name				Signature [Signature] Date Month Day Year 7/14/86		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



32 C3 10540
Pg 628 of 10380
1068 140

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404 Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 3106	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address HIGH CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590 4. Generator's Phone (00) 945-7411				A. State Manifest Document Number 00 165516		
5. Transporter 1 Company Name HIGH CARBIDE CORPORATION				B. State Generator's ID 30689		
6. US EPA ID Number TXD 000 461 533				C. State Transporter's ID 30689		
7. Transporter 2 Company Name				D. Transporter's Phone 945-7411		
8. US EPA ID Number				E. State Transporter's ID		
9. Designated Facility Name and Site Address ULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 COR 107 SOUTH, TEXAS CITY, TX				F. Transporter's Phone		
10. US EPA ID Number TXD 000 825 249				G. State Facility's ID 39036		
H. Facility's Phone (409) 935-4783						
11A HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	WASTE ASBESTOS, ORM-E, RA91B9		11	T	170750	
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above			K. Handling Codes for Wastes Listed Above			
UNLESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF PCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE THE AMOUNT OF WASTE GENERATED TO THE EXTENT I HAVE DETERMINED TO BE TECHNICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE OR DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE HARM TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name CARMENITA RODRIGUEZ			Signature Carmenita Rodriguez		Date 7/16/86	
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature E. Williams		Date 7/16/86	
Printed/Typed Name E. WILLIAMS			Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date	
Printed/Typed Name			Signature		Date	
19. Discrepancy Indication Space UCTC 01305						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name			Signature W. J. Williams		Date 7/16/86	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



37.1 C3 11460
Pg 629 of 10403
1268 1060

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 3708	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address HIGH CARRIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00165578		
4. Generator's Phone (09) 945-7411				B. State Generator's ID 30689		
5. Transporter 1 Company Name HIGH CARRIDE CORPORATION				C. State Transporter's ID 30689		
6. US EPA ID Number TXD 000 461 533				D. Transporter's Phone 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568				G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 835 249				H. Facility's Phone (409) 935-4783		
11A HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	WASTE ASBESTOS, CRM-E, RA9189	50	BA	61 T		170790
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above		
UNLESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE TO A TECHNICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE OR DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE HAZARD TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name QUINCY RODRIGUEZ				Signature <i>Quincy Rodriguez</i>		Date 7/29/86
17. Transporter 1 Acknowledgement of Receipt of Materials				Date		
Printed/Typed Name B. J. LLOYD				Signature <i>B. J. Lloyd</i>		Month Day Year 7/29/86
18. Transporter 2 Acknowledgement of Receipt of Materials				Date		
Printed/Typed Name				Signature		Month Day Year
19. Discrepancy Indication Space UCTC 01306						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name				Signature <i>W. J. ...</i>		Date 7/29/86

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



51

C3
UPg 630
#126
11760
10460
1588

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404 Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD-000 461 533	Manifest Document No. 12107	2. Page 1 of 1	Information in the shaded areas is not required by Federal law	
3. Generator's Name and Mailing Address HIGH CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590		4. Generator's Phone (09) 945-7411		A. State Manifest Document Number 00165577		
5. Transporter 1 Company Name HIGH CARBIDE CORPORATION		6. US EPA ID Number TXD-000 461 533		B. State Generator's ID 30582		
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID 30589		
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 PO BOX 107 SOUTH, TEXAS CITY, TX		10. US EPA ID Number TXD-000 825 210		D. Transporter's Phone 945-7411		
				E. State Transporter's ID		
				F. Transporter's Phone		
				G. State Facility's ID 39036		
				H. Facility's Phone (409) 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. WASTE ASBESTOS, ORM-E, NA9189	123	RA	87	T	170756
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above						
K. Handling Codes for Wastes Listed Above						
LESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE TO THE DEGREE I HAVE DETERMINED TO BE ECONOMICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE RISK TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name CYNTHIA RODRIGUEZ		Signature <i>[Signature]</i>			Date 11/19/84	
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature <i>[Signature]</i>			Date 11/20/84	
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature <i>[Signature]</i>			Date 11/20/84	
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 18.						
Printed/Typed Name		Signature <i>[Signature]</i>			Date 11/20/84	

UCTC 01307

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



11620
106-0 Pg 63
1570 of 1268

Please print or type. (Form designed for use on site (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 13109 B57	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address MCM CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00165579		
4. Generator's Phone (409) 945-7411				B. State Generator's ID 30689		
5. Transporter 1 Company Name MCM CARBIDE CORPORATION #1021				C. State Transporter's ID 30689		
6. US EPA ID Number TXD 000 461 533				D. Transporter's Phone (409) 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address ULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77558 BOX 107 SOUTH, TEXAS CITY, TX				G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 835 249				H. Facility's Phone (409) 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	WASTE ASBESTOS, ORM-E, NA9189	7	EA	.78	T	170750
J. Additional Descriptions for Materials Listed Above CLASS INH WASTE SHIPPING IN NO USEPA Hazardous Waste Present				K. Handling Codes for Wastes Listed Above		
UNLESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE TO THE DEGREE I HAVE DETERMINED TO BE ECONOMICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE RISK TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name Gloria Matloge				Signature Gloria Matloge		Date 11/11/86
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature B J LLOYD		Date 11/12/86
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date
19. Discrepancy Indication Space				UCTC 01308		
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name				Signature [Signature]		Date 1/13/87

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



C3
Pg 632
of 1268
11560
10340
1220

Please print or type (Form designed for use on elite (12-pitch) typewriter)

Form approved. OMB No. 2000-0404 Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533		Manifest Document No. 3105		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address MICH CAPEIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590						A. State Manifest Document Number 00165572			
4. Generator's Phone (409) 945-7411						B. State Generator's ID 30689			
5. Transporter 1 Company Name MICH CAPEIDE CORPORATION #102						6. US EPA ID Number TXD 000 461 533		C. State Transporter's ID 30689	
7. Transporter 2 Company Name						8. US EPA ID Number		D. Transporter's Phone (409) 945-7411	
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 1007 SOUTH, TEXAS CITY, TX						10. US EPA ID Number TXD 000 825 240		E. State Transporter's ID	
								F. Transporter's Phone	
								G. State Facility's ID 39036	
								H. Facility's Phone (409) 935-4783	
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)					12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. ASBESTOS, GRN-E, PA9189					50	45	T	170750
	b.								
	c.								
	d.								
J. Additional Description for Materials Listed Above						K. Handling Codes for Wastes Listed Above			
UNLESS I AM A SMALL QUANTITY HAZARDOUS WASTE GENERATOR, I HAVE BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA. I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE THE AMOUNT OF WASTE GENERATED TO THE DEGREE I HAVE DETERMINED TO BE TECHNICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE OR DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE RISK TO HUMAN HEALTH AND THE ENVIRONMENT. 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.									
Printed/Typed Name Gloria Matlage								Date Month Day Year 01/27/86	
Signature Gloria Matlage									
17. Transporter 1 Acknowledgement of Receipt of Materials								Date Month Day Year 10/28/86	
Printed/Typed Name B. J. L. V. D.								Signature B. J. L. V. D.	
18. Transporter 2 Acknowledgement of Receipt of Materials								Date Month Day Year	
Printed/Typed Name								Signature	
19. Discrepancy Indication Space								Date	
								Month Day Year	
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 18.								Date	
Printed/Typed Name								Signature	
								Month Day Year 1/27/86	

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



C3 11440
P6320f 10280
1265 1100

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 3110	2. Page 1 of 1	Information in the shaded areas is not required by Federal law	
3. Generator's Name and Mailing Address HIGH CAREIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00105500		
4. Generator's Phone (09) 945-7411				B. State Generator's ID 30689		
5. Transporter 1 Company Name HIGH CAREIDE CORPORATION				C. State Transporter's ID 30689		
6. US EPA ID Number TXD 000 461 533				D. Transporter's Phone (09) 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568				G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 835 340				H. Facility's Phone (409) 935-4783		
11A HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. ASBESTOS, ORM-E, PA9189	50	PA	.63T		170750
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above						
K. Handling Codes for Wastes Listed Above						
UNLESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(D) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE TO THE DEGREE I HAVE DETERMINED TO BE TECHNICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, TREATMENT, OR DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE HAZARD TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name VINCENTA RODRIGUEZ				Signature <i>[Signature]</i>		Date 11/2/86
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>[Signature]</i>		Date 11/2/86
Printed/Typed Name B. J. L. C. V. D.				Signature <i>[Signature]</i>		Date 11/2/86
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date
Printed/Typed Name				Signature		Date
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name				Signature <i>[Signature]</i>		Date 11/2/86

UCTC 01310



Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 533	Manifest Document No. 3111	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address HIGH CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00165581		
4. Generator's Phone (00) 945-7411				B. State Generator's ID 30689		
5. Transporter 1 Company Name HIGH CARBIDE CORPORATION				C. State Transporter's ID 30589		
6. US EPA ID Number TXD 000 461 533				D. Transporter's Phone 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address GULF COAST WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568 102 SOUTH, TEXAS CITY, TX				G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 225 240				H. Facility's Phone (409) 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste Name
	a. WASTE ASBESTOS, ORN-E, NA9189	70	EA	1.06	T	170750
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above		
UNLESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE TO ECONOMICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE HAZARD TO HUMAN HEALTH AND THE ENVIRONMENT. 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name WILLIAM H. HODGINS				Signature <i>W. Hodgins</i>		Date Month Day Year 7/15/85
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>B. Lloyd</i>		Date Month Day Year 7/15/85
Printed/Typed Name B. LLOYD				Signature		Date
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date
Printed/Typed Name				Signature		Date
19. Discrepancy Indication Space						
UCTC 01311						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name				Signature <i>W. Lloyd</i>		Date Month Day Year 7/15/85

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711 1314



10720 C3 10152
1500 R 630 F 10321
420 1268 30

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 461 523	Manifest Document No. 1312	2. Page 1 of 1	Information in the shaded areas is not required by Federal law	
3. Generator's Name and Mailing Address ION CARBIDE CORPORATION P.O. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00165502		
4. Generator's Phone 909 945-7411				B. State Generator's ID 20680		
5. Transporter 1 Company Name ION CARBIDE CORPORATION #102				C. State Transporter's ID 00689		
6. US EPA ID Number TXD 000 461 523				D. Transporter's Phone 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address LA MAR WASTE DISPOSAL AUTHORITY P.O. BOX 1026, LA MARQUE, TX 77568				G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 835 249				H. Facility's Phone (409) 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
	a. CIL ARSENITE, BRN-E, RA9189	14	.21	T	170750	
	b.					
	c.					
	d.					
J. Additional Descriptions for Materials Listed Above						
K. Handling Codes for Wastes Listed Above						
LESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO OBTAIN A HAZARDOUS WASTE PRESENT MINIMIZATION CERTIFICATION UNDER SECTION 3002(B) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE THE AMOUNT OF HAZARDOUS WASTE GENERATED TO THE DEGREE I HAVE DETERMINED TO BE TECHNICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE RISK TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name Gloria Matlage				Signature Gloria Matlage		
Date 01/28/86				Month Day Year		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name B. J. L. L. L.				Signature B. J. L. L. L.		
Date 01/28/86				Month Day Year		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name				Signature		
Date				Month Day Year		
19. Discrepancy Indication Space						
UCTC 01312						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 18.						
Printed/Typed Name				Signature		
Date				Month Day Year		

TEXAS DEPARTMENT OF WATER RESOURCES
P.O. Box 13087, Capitol Station
Austin, Texas 78711



32

C3 11420
Pg 6350 of 10383
1065/1047

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMS No. 2000-0404. Expires 7-31-86

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. TXD 000 AC1 533	Manifest Document No. 13113	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address ION CARRIDE CORPORATION C. BOX 471, TEXAS CITY, TX 77590				A. State Manifest Document Number 00165593		
4. Generator's Phone No. 945-7411				B. State Generator's ID 30689		
5. Transporter 1 Company Name ION CARRIDE CORPORATION				C. State Transporter's ID 30689		
6. US EPA ID Number TXD 000 AC1 533				D. Transporter's Phone 945-7411		
7. Transporter 2 Company Name				E. State Transporter's ID		
8. US EPA ID Number				F. Transporter's Phone		
9. Designated Facility Name and Site Address LE COAST WASTE DISPOSAL AUTHORITY C. BOX 1026, LA MARQUE, TX 77558 107 SOUTH TEXAS CITY, TX				G. State Facility's ID 39036		
10. US EPA ID Number TXD 000 835 048				H. Facility's Phone (409) 935-4783		
11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	WASTE ASBESTOS, ORM-E, NA9189	50	BA	.6	T	900590 170750
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above		
LESS I AM A SMALL QUANTITY GENERATOR WHO HAS BEEN EXEMPTED BY STATUTE OR REGULATION FROM THE DUTY TO MAKE A WASTE MINIMIZATION CERTIFICATION UNDER SECTION 3002(D) OF RCRA, I ALSO CERTIFY THAT I HAVE A PROGRAM IN PLACE TO REDUCE THE AMOUNT OF WASTE GENERATED TO THE DEGREE I HAVE DETERMINED TO BE ECONOMICALLY PRACTICABLE AND I HAVE SELECTED THE METHOD OF PROCESSING, STORAGE, DISPOSAL CURRENTLY AVAILABLE TO ME WHICH MINIMIZES THE PRESENT AND FUTURE HAZARD TO HUMAN HEALTH AND THE ENVIRONMENT.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.						
Printed/Typed Name JOHN J. BOEDIGHEE				Signature [Signature]		Date 1/13/86
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name B. J. LLOYD				Signature [Signature]		Date 1/13/86
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name				Signature		Date
19. Discrepancy Indication Space UCTC 01313						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						
Printed/Typed Name				Signature [Signature]		Date 1/13/86