


PERMIT NO. NPDES - LA-0000761 (NON-COMPLIANCE REPORT)

Reporting Period: 8/1-7/82

Date: August 11, 1982

Event com No.	Effluent Characteristic	Lbs./Day Discharge Limitation	Lbs./Day Effluent Deviation	Date of Deviation	Time of Deviation	Reason or Explanation
001	pH (units)	6-9	-2.4	8/3	4:03 p.m.	(12 min.) Low pH material entered the pH control system from an undetermined source in the Plant temporarily exceeding the neutralization capacity of the pH control system.
1/017/ 019	TSS	2236	+417	8/5		Excursion due to a combination of: (1) a chlorine circuit outage resulting from power supply problems caused an increased flow to the Lead Treatment ponds, thereby reducing settling time for suspended solids. Flow curtailment measures were taken until the circuit was placed back in service; (2) abnormally high solids (apparently sand) in discharge of brine solids treatment system. Investigation of cause is underway.
						 I certify under penalty of law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the information is true, accurate, and complete and I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

SL 045660