

ABD00338187

CONOCO CHEMICALS — ABERDEEN PVC PLANT

DOSIMETRY CARD (A)

SAMPLE NO 1648

A

Hazard: VCM (✓) Lead () Noise () () Date 1/23/81
 Name Doug Spann S.S. # 418/66/3073 Shift A (F)
 Department Wing Job Class 84C

Instrument No. <u>74R</u>	Start Time <u>6:40</u> AM () PM (X)	Stop Time <u>7:04</u> AM (X) PM ()
Noise Cell No. _____	Airflow _____	_____

Analyst: J. K. Hall Analysis Date: 1-29-81

Hazard		TWA Exposure	
VCM	PEL: 1 PPM	<u>0.3</u>	PPM
Noise	Over () Under () 115 dBA	% of PEL	
Lead (Micrograms)	TOT: PEL: Per M ³	Per M ³	

ABD00338188
CONOCO CHEMICALS — ABERDEEN PVC PLANT
DOSIMETRY DATA CARD (B)

SAMPLE NO 1648
A

Hazard: VCM (☒) Lead () Noise () _____ () Date 1/23/81

Time Clock (Lead Sampling Only) : IN: 1900 AM () PM (☒) OUT: 0700 AM (☒) PM ()

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

Area	Time	Area	Time
<u>Vinyl Rx's</u>	<u>3 hrs</u>		
<u>Vinyl Decks</u>	<u>6 hrs</u>		

List most likely causes of possible overexposure to the hazard.

- Recovery Systems
- ~~Recovery~~
- Emission Rec. System — SIO leaky to TK1

Check respiratory protection you used:

(☒) None () Dust Mask () Air-line Respirator () Scott Air-pak

Signature Douglas Sparr

Please complete and return to guard