

5-A-3

5-A-3



O'BRIEN'S

FF



THERMOLYZED
TUNG OIL



MILDEW
RESISTANT
TO
FADING
AND
DISCOLORING
BY
EXPOSURE
TO
SUNLIGHT

PAINT

ONE COAT SUPER WHITE



MANUFACTURED IN U.S.A. BY THE O'BRIEN CORPORATION SOUTH BEND INDIANA

THERMOLYZED OIL PAINT

Made with special Thermolyzed Pre-Shrunk Oils—T. T. O. Paint may be used on any exterior surface—wood, metal, brick, concrete, etc. T. T. O. Paint works easily under the brush, covers exceptionally well and provides a high lustre, porcelain-like finish that looks like enamel, washes like glass and wears like iron.

T. T. O. WHITE PRIMER

A specially designed primer for use on all exterior surfaces under O'Brien's T.T.O. Paint and other house paints. Made with Pre-Shrunk Oils, T.T.O. Primer controls the penetration of the oils in the paints put over it and thus assures a well balanced, long-wearing paint film. Dries to a dull finish permitting fast and sure application of the finish coat. Comes in White only but may be tinted with O'Brien's Tone-All or Oil Colors.

DO NOT TAKE INTERNALLY

DANGER!

HAZARDOUS OR FATAL IF

SWALLOWED

CONTAINS LEAD. DO NOT INDUCE VOMITING. Do not apply on window sills, toys, furniture, or interior surfaces of rooms which may be used by children. USE WITH ADEQUATE VENTILATION. Avoid prolonged contact with skin and breathing of vapor or spray mist. Wash thoroughly after handling and before eating or smoking. Keep away from heat and open flame. Close container after each use. KEEP OUT OF THE REACH OF CHILDREN.

T.T.O. SUPER WHITE	
Pigment	42.31%
35% Lead Zinc Oxide	47.36%
Slitters	100.00%
Vehicle	100.00%
Heat Treated Linseed Oil	11.57%
Almond Sprites & Oils	24.31%
Preparation Ingredients	32.27%
Raw Linseed Oil	11.85%
	100.00%
*Active Phenyl Mercaptan	99.18%
Leads	100.00%

THE O'BRIEN CORPORATION
SOUTH BEND, IND. OKLAHOMA CITY, OKLA.
BALTIMORE, MD. SAN FRANCISCO, CAL.
LOS ANGELES, CAL.

DIRECTIONS FOR USE

FOR NEW UNPAINTED SURFACES

1st Coat—O'Brien's T.T.O. White Primer thinned with two or three pints of raw linseed oil.

2nd Coat—O'Brien's T.T.O. Paint.

FOR OLD PAINTED SURFACES

T.T.O. Super White should be applied only on surfaces that have weathered thoroughly or have been primed with T.T.O. Primer. If the surface has not completely weathered, it should be sanded or wire brushed before applying the T.T.O. Super White.

For light colors tint T.T.O. Primer with O'Brien's Tone-All or Oil Colors.

GENERAL RECOMMENDATIONS

WEATHER—Outside painting should never be done when the weather is damp or the temperature below 60° F.

SURFACES—Surfaces to be painted should be perfectly dry and free of grease, oil, dust and loose dirt.

SPRAYING—T.T.O. Paints may be sprayed by an experienced operator. Thin as necessary with turpentine.

DRYING—Allow at least 48 hours good drying weather between coats. When temperature is low, add two fluid ounces of O'Brien's No. 1188 Drier to each gallon.

Stir Paint Well Before and During Use
When Necessary—Thin with Turpentine