

TABLE 8. PROPERTIES OF SATURATED STEAM: PRESSURE TABLE—(Concluded)

Abs. Press. Lb./Sq. In. p	Temp. Deg. F. t	Specific Volume			Total Heat			Entropy			Abs. Press. Lb./Sq. In. p
		Sat. Liquid v _l	Evap. v _{fg}	Sat. Vapor v _g	Sat. Liquid h _f	Evap. h _{fg}	Sat. Vapor h _g	Sat. Liquid s _f	Evap. s _{fg}	Sat. Vapor s _g	
250.0	400.97	0.01867	1.8223	1.8410	376.02	824.5	1200.5	0.5680	0.9581	1.5261	250.0
260.0	404.43	0.01872	1.7536	1.7723	379.78	821.2	1201.0	0.5723	0.9504	1.5227	260.0
270.0	407.79	0.01877	1.6895	1.7083	383.44	818.0	1201.4	0.5765	0.9430	1.5194	270.0
280.0	411.06	0.01882	1.6302	1.6490	387.02	814.7	1201.8	0.5805	0.9357	1.5163	280.0
290.0	414.24	0.01887	1.5745	1.5934	390.50	811.6	1202.1	0.5845	0.9287	1.5132	290.0
300.0	417.33	0.01892	1.5225	1.5414	393.90	808.5	1202.4	0.5883	0.9220	1.5102	300.0
320.0	423.29	0.01901	1.4279	1.4469	400.47	802.5	1203.0	0.5957	0.9089	1.5046	320.0
340.0	428.96	0.01910	1.3439	1.3630	406.75	796.6	1203.4	0.6027	0.8965	1.4992	340.0
360.0	434.39	0.01918	1.2689	1.2881	412.80	790.9	1203.7	0.6094	0.8846	1.4940	360.0
380.0	439.59	0.01927	1.2015	1.2208	418.61	785.3	1203.9	0.6157	0.8733	1.4891	380.0
400.0	444.58	0.0194	1.1407	1.1601	424.2	779.8	1204.1	0.6218	0.8625	1.4843	400.0
420.0	449.38	0.0194	1.0853	1.1047	429.6	774.5	1204.1	0.6277	0.8520	1.4798	420.0
440.0	454.01	0.0195	1.0345	1.0540	434.8	769.3	1204.1	0.6334	0.8420	1.4753	440.0
460.0	458.48	0.0196	0.9881	1.0077	439.9	764.1	1204.0	0.6388	0.8322	1.4711	460.0
480.0	462.80	0.0197	0.9456	0.9653	444.9	759.0	1203.9	0.6441	0.8228	1.4670	480.0
500.0	466.99	0.0198	0.9063	0.9261	449.7	754.0	1203.7	0.6493	0.8137	1.4630	500.0
520.0	471.05	0.0198	0.8701	0.8899	454.4	749.0	1203.5	0.6543	0.8048	1.4591	520.0
540.0	474.99	0.0199	0.8363	0.8562	459.0	744.1	1203.2	0.6592	0.7962	1.4554	540.0
560.0	478.82	0.0200	0.8047	0.8247	463.6	739.3	1202.9	0.6639	0.7878	1.4517	560.0
580.0	482.55	0.0201	0.7751	0.7952	468.0	734.5	1202.5	0.6686	0.7796	1.4482	580.0
600.0	486.17	0.0202	0.7475	0.7677	472.3	729.8	1202.1	0.6731	0.7716	1.4447	600.0
620.0	489.71	0.0202	0.7217	0.7419	476.6	725.1	1201.7	0.6775	0.7638	1.4413	620.0
640.0	493.16	0.0203	0.6972	0.7175	480.8	720.5	1201.2	0.6818	0.7562	1.4380	640.0
660.0	496.53	0.0204	0.6744	0.6948	484.9	715.9	1200.8	0.6861	0.7487	1.4348	660.0
680.0	499.82	0.0205	0.6527	0.6732	488.9	711.3	1200.2	0.6902	0.7414	1.4316	680.0
700.0	503.04	0.0206	0.6321	0.6527	492.9	706.8	1199.7	0.6943	0.7342	1.4285	700.0
720.0	506.19	0.0206	0.6128	0.6334	496.8	702.4	1199.2	0.6983	0.7272	1.4255	720.0
740.0	509.28	0.0207	0.5944	0.6151	500.6	697.9	1198.6	0.7022	0.7203	1.4225	740.0
760.0	512.30	0.0208	0.5769	0.5977	504.4	693.5	1198.0	0.7060	0.7136	1.4196	760.0
780.0	515.27	0.0209	0.5602	0.5811	508.2	689.2	1197.4	0.7098	0.7069	1.4167	780.0
800.0	518.18	0.0209	0.5444	0.5653	511.8	684.9	1196.7	0.7135	0.7004	1.4139	800.0
820.0	521.03	0.0210	0.5293	0.5503	515.5	680.6	1196.0	0.7171	0.6940	1.4111	820.0
840.0	523.83	0.0211	0.5149	0.5360	519.0	676.4	1195.4	0.7207	0.6877	1.4084	840.0
860.0	526.58	0.0212	0.5013	0.5225	522.6	672.1	1194.7	0.7242	0.6815	1.4057	860.0
880.0	529.29	0.0213	0.4881	0.5094	526.0	667.9	1194.0	0.7277	0.6754	1.4031	880.0
900.0	531.95	0.0213	0.4756	0.4969	529.5	663.8	1193.3	0.7311	0.6694	1.4005	900.0
920.0	534.56	0.0214	0.4635	0.4849	532.9	659.7	1192.6	0.7344	0.6635	1.3980	920.0
940.0	537.13	0.0215	0.4520	0.4735	536.2	655.6	1191.8	0.7377	0.6577	1.3954	940.0
960.0	539.66	0.0216	0.4409	0.4625	539.6	651.5	1191.1	0.7410	0.6520	1.3930	960.0
980.0	542.14	0.0217	0.4303	0.4520	542.8	647.5	1190.3	0.7442	0.6464	1.3905	980.0
1000.0	544.58	0.0217	0.4202	0.4419	546.0	643.5	1189.6	0.7473	0.6408	1.3881	1000.0
1050.0	550.53	0.0219	0.3960	0.4179	554.0	633.6	1187.6	0.7550	0.6273	1.3822	1050.0
1100.0	556.28	0.0222	0.3738	0.3960	561.7	623.9	1185.6	0.7624	0.6141	1.3765	1100.0
1150.0	561.81	0.0224	0.3540	0.3764	569.2	614.3	1183.5	0.7695	0.6014	1.3709	1150.0
1200.0	567.14	0.0226	0.3356	0.3582	576.5	604.9	1181.4	0.7764	0.5891	1.3656	1200.0
1250.0	572.30	0.0228	0.3187	0.3415	583.6	595.6	1179.2	0.7831	0.5772	1.3603	1250.0
1300.0	577.32	0.0230	0.3029	0.3259	590.6	586.3	1177.0	0.7897	0.5654	1.3552	1300.0
1350.0	582.21	0.0232	0.2884	0.3116	597.5	577.2	1174.7	0.7962	0.5540	1.3501	1350.0
1400.0	586.96	0.0235	0.2748	0.2983	604.3	568.1	1172.4	0.8024	0.5428	1.3452	1400.0
1450.0	591.58	0.0237	0.2621	0.2858	611.0	559.1	1170.0	0.8086	0.5318	1.3404	1450.0
1500.0	596.08	0.0239	0.2502	0.2741	617.5	550.2	1167.6	0.8146	0.5212	1.3357	1500.0
1600.0	604.74	0.0244	0.2284	0.2528	630.2	532.6	1162.7	0.8262	0.5003	1.3265	1600.0
1700.0	612.98	0.0249	0.2089	0.2338	642.5	515.0	1157.5	0.8373	0.4801	1.3174	1700.0
1800.0	620.86	0.0254	0.1913	0.2167	654.7	497.2	1151.8	0.8482	0.4601	1.3083	1800.0
1900.0	628.39	0.0260	0.1754	0.2014	666.8	478.9	1145.7	0.8589	0.4402	1.2990	1900.0
2000.0	635.6	0.0265	0.1610	0.1875	679.0	460.0	1139.0	0.8696	0.4200	1.2896	2000.0
2200.0	649.2	0.0277	0.1346	0.1623	703.7	420.0	1123.8	0.8912	0.3788	1.2700	2200.0
2400.0	661.9	0.0292	0.1112	0.1404	729.4	376.4	1105.8	0.9133	0.3356	1.2488	2400.0
2600.0	673.8	0.0310	0.0895	0.1205	756.7	327.8	1084.5	0.9364	0.2892	1.2257	2600.0
2800.0	684.9	0.0333	0.0688	0.1021	786.7	272.3	1058.9	0.9618	0.2379	1.1996	2800.0
3000.0	695.2	0.0367	0.0477	0.0844	823.1	202.5	1025.6	0.9922	0.1754	1.1676	3000.0
3200.0	704.9	0.0459	0.0142	0.0601	887.0	75.9	962.9	1.0461	0.0651	1.1112	3200.0
3226.0	706.1	0.0522	0	0.0522	925.0	0	925.0	1.0785	0	1.0785	3226.0

responding change in the latent heat of evaporation. These values are given in Table 8.

Specific Heat. The specific heat of water, or the amount of heat (Btu) required to raise the temperature of one pound of water one degree Fahrenheit, varies with the temperature, but it is commonly assumed to be unity at all temperatures. Steam tables are based on exact values, however. The specific heat of ice at 32 F is 0.492 Btu per pound. The amount of heat required to raise one pound of water at 32 F through a known temperature interval depends on the average specific heat for the temperature range.

Sensible and Latent Heat. The heat necessary to raise the temperature of one pound of water from 32 F to the boiling point is known as the *heat of the liquid* or *sensible heat*. When more heat is added, the water begins to evaporate and expand at constant temperature until the water is entirely changed into steam. The heat thus added is known as the *latent heat of evaporation*.

PROPERTIES OF STEAM

Steam is water vapor which exists in the vaporous condition because sufficient heat has been added to the water to supply the latent heat of evaporation and change the liquid into vapor. This change in state takes place at a definite and constant temperature which is determined solely by the pressure of the steam. The volume of a pound of steam is the *specific volume* which decreases as the pressure increases. The reciprocal of this, or the weight of steam per cubic foot, is the *density*. (See Table 8.)

Steam which is in contact with the water from which it was generated is known as *saturated steam*. If it contains no actual water in the form of mist or priming, it is called *dry saturated steam*. If this be heated and the pressure maintained the same as when it was vaporized, its temperature will increase and it will become *superheated*, that is, its temperature will be higher than that of saturated steam at the same pressure.

REFERENCES

- Rational Psychrometric Formulae, by W. H. Carrier (*A.S.M.E. Transactions*, Vol. 33, 1911).
- Temperature of Evaporation, by W. H. Carrier (*A.S.H.V.E. TRANSACTIONS*, Vol. 24, 1918).
- The Evaporation of a Liquid into a Gas, by W. K. Lewis (*A.S.M.E. Transactions*, Vol. 44, 1922).
- The Evaporation of a Liquid into a Gas—a Correction, by W. K. Lewis (*Mechanical Engineering*, September, 1933).
- Temperature of Evaporation of Water into Air, by W. H. Carrier and D. C. Lindsay (*A.S.M.E. Transactions*, Vol. 46, 1924).
- A New Psychrometric Chart, by C. A. Bulkeley (*A.S.H.V.E. TRANSACTIONS*, Vol. 32, 1926).
- A Review of Psychrometric Charts, by C. O. Mackey (*Heating and Ventilating*, June, July, 1931).
- Air Conditioning Applied to Cold Storage and a New-Psychrometric Chart, by C. A. Bulkeley (*Refrigerating Engineering*, February, 1932).
- The Psychrometric Chart, by E. V. Hill (*Aerologist*, April, May, June, 1932).
- Air Conditioning Theory, by John A. Goff (*Refrigerating Engineering*, January, 1933).