

EPA/STATE NOTIFICATION ON FC-143 RESULTS ON LOCAL LANDFILL

(Letter, Stewart to Robert L. Allen, Chief dated 08/31/93)

BCC: J. B. Allen, Legal
Dr. J. L. Riddle, B12220
L. Diaz Riegel, DERS
T. D. Vandell, DERS

In Turn:

M. S. Eaton, Jr.
H. D. Ramsey
T. L. Eichstadt
D. R. Johnson
J. R. Gregory
W. M. Stewart

C. F. Muska/L. K. Ireland/R. A. Kirschner/P&S File

In Turn:

C. T. Alt
E. G. Ramos
G. Woytowich
D. J. Harbison
D. A. Weber

/vlw
5495-3

RJZ016303

EID939381



WASHINGTON WORKS
P.O. Box 1217
PARKERSBURG, WV 26102-1217

DU PONT POLYMERS

CC: Mr. John J. Humphries, III, Chief
General States Permit Section
U. S. EPA, Region III
841 Chestnut Building
Philadelphia, PA 19107

Mr. G. Max Robertson, Chief
Office of Waste Management
Division of Environmental Protection
1356 Hansford Street
Charleston, WV 25301

August 31, 1993

CERTIFIED MAIL -
RETURN RECEIPT REQUESTED

Mr. Robert L. Allen, Chief (3)
RCRA Programs Branch, 3HW50
U. S. Environmental Protection Agency, Region III
841 Chestnut Building
Philadelphia, Pa 19107

RE: Permit WVD045875291
Letter, Stewart to Allen, dated 6/28/93.

Dear Mr. Allen:

The ammonium perfluoro-octanoate (FC-143) and Triton(TM) X-100 results from the Local Landfill Verification Investigation (VI) sample locations are summarized in the attached table. Copies of the laboratory reports are also attached.

All samples were collected and analyzed using the VI protocols. FC-143 water analyses were performed by CH2M Hill in Montgomery, AL. Triton(TM) water and FC-143 soil analyses were performed at Washington Works.

A Triton(TM) sample has not yet been obtained from Local Landfill sample location LLL-2 because the stream bed has been dry. This location will be sampled for Triton(TM) at the next opportunity. However, a non-detectable result is expected since Triton(TM) biodegrades and all other Triton(TM) sample results were non-detectable.

Please contact me at (304) 863-4271 if you have any questions or need additional information.

Very truly yours,

W. M. Stewart
Sr. Environmental Control Consultant
Washington Works

Attachments

/v/w
5495

RJZ016304