

Year Model Part No.

G.M.C. (Cont.)

SERIES 350 AND 370 (Cont.)

46-49	ECS-375, 6 and 7; FCS-375, 6 and 7 School Bus (Transmission to First Midship Bearing)	3707830
	(First Midship Bearing to Second Midship Bearing and Second Midship Bearing to Rear Axle).....	3707830
1946	EC-352, 3, 4 and 5; EF-351, 2, 3, 4 and 5; ECS-354 and 5	3708961

SERIES 400 AND 410

60-65	4000, B4000, L4000, S4000 (Ex. S4011 w/H130 Axle).....	3707830
55-56	All 400 and 410 Series w/Spicer 1410 Series Joints	3707830
1955	All 400 and 410 Series with 4 or 5 Speed Transmission (Front or Center)	3707830
1955	All 400 and 410 Series with Hydramatic (All Locations Except Auxiliary Transmission to Rear Axle—Rear)	3707830
1954	401-27, 402-27, 403-27, 404-27, 405-27; S406-24, S407-24, S406-27, S407-27 School Bus	3707830
1954	M401-27, M402-27, M403-27, M404-27, M405-27	3707830
52-53	S405-24, S406-24, S407-24 School Bus (Transmission to Midship Bearing or Transmission to First Midship Bearing)	3707830
	(First Midship Bearing to Second Midship Bearing, Midship Bearing to Rear Axle or Second Midship Bearing to Rear Axle).....	3708961
50-51	HCW-402, HCW-404, HCW-405 (6x4)	3708961
50-51	HCS-405, HCS-406, HCS-407 School Bus (Transmission to First Midship Bearing)	3707830
	(First Midship Bearing to Second Midship Bearing and Second Midship Bearing to Rear Axle).....	3708961
1946	EC-402, 3, 4 and 5; EF-401, 2, 3, 4 and 5	3707830
41-45	CC-402, 3, 4 and 5; CF-401, 2, 3, 4 and 5; CCT-402, 3 and 4; CFT402 and 3	3707830

SERIES 450

55-56	M450, FM450, SM450 w/Spicer 1410 Series Joints.....	3707830
1955	M451, M452, M453, M454, M455; SM456, SM457, SM458 School Bus: FM451, FM452, FM453, FM454, FM455, FM456	3707830
	With Hydramatic Transmission (Transmission to Auxiliary Transmission)	3707830
1954	M451-30, M452-30, M453-30, M454-30, M455-30	3707830
52-54	W452-30, W453-30, W454-30, W455-30 (6x4)	3707830
52-53	DW-452-37, DW-453-37, DW-454-37, DW-455-37 (6x4)	3707830
	With Eaton 22M Axle (First Rear Axle to Second Rear Axle)	3707830
50-51	HC-451, 2, 3, 4 and 5; HFR-451, HF-451, 2, 3, 4 and 5	3707830
47-49	FC-451, 2, 3, 4 and 5; FFR-451, 2, 3, 4 and 5	3707830
47-51	FCS-456, 7 and 8; HCS-456, 7 and 8 School Bus	3707830

SERIES 470

1954	M471-30, M472-30, M473-30, M474-30, M475-30	3707830
1950	HC-471, 2, 3, 4 and 5; HF-471, 2, 3, 4 and 5	3707830

SERIES 500

64-65	B5000, 5000, L5000, S5000	3707830
57-59	MW500 (6x4) With Eaton 28M Axle (Transmission to Auxiliary Transmission)	3707830
57-59	With Eaton 22M Axle (First Rear Axle to Second Rear Axle)	3707830
1956	W502 (6x4) (First Rear Axle to Second Rear Axle)	3707830
1956	W503, W504, W505 (6x4) (First Rear Axle to Second Rear Axle)	3707830
55-56	MW502, MW503, MW504, MW505 (6x4) With Eaton 22M Axle (All Except Auxiliary Transmission to First Rear Axle)	3707830
1955	W502, W503, W504, W505 (6x4) With Eaton 22M Axle (First Rear Axle to Second Rear Axle)	3707830
1956	M500, FM500 Using 1410 Series Joints	3707830
1955	M501, M502, M503, M504, M505; FM502, FM503, FM504, FM505, FM506	3707830
	With Hydramatic Transmission (Transmission to Auxiliary Transmission)	3707830
39-45	AC-502, 3, 4 and 5; ACT-502, 3, 4 and 5; ACS-507, ACS-508; AF-501, 2, 3, 4 and 5; AFT-502 and 3	3707830
55-56	FM550, FMW550 (Transmission to Auxiliary Transmission)	3707830
55-56	M551, M552, M553, M554, M555	3707830
55-56	MW552, MW553, MW554, MW555 (6x4) With Eaton 32M Axle (First Rear Axle to Second Rear Axle)	3707830

SERIES 650

55-56	M651 to M655 (Transmission to Auxiliary Transmission)	3707830
-------	---	---------

COACHES—TRANSIT TYPE—TD

49-56	TD51 Models: TDH5102, TDH5103, TDM5103, TDH5104, TDM5104, TDH5105, TDM5105, TDH5106, TDM5106, TDH5107, TDM5107, TDH5108, TDM5108—Steering Gear Drive	B7A-7039A
-------	--	-----------