

ETHYL CORPORATION

100 PARK AVENUE BUILDING AT 41st STREET

NEW YORK 17, N. Y.


February 28, 1956

Dr. Robert A. Kehoe
Kettering Laboratory
University of Cincinnati
Cincinnati 19, Ohio

Dear Dr. Bob:

Attached is a copy of a Competitive Activity Report discussing the suspected case of lead poisoning previously reported to you by phone. We will keep you posted of any additional information we develop.

Sincerely yours,



L. R. Fleck

LRF:ems
Attach.

N13179

KE 0012565

ETHYL CORPORATION

100 PARK AVENUE BUILDING AT 41ST STREET

NEW YORK 17, N. Y.

February 28, 1956

Dr. Robert A. Kehoe
Kettering Laboratory
University of Cincinnati
Cincinnati 19, Ohio

Dear Dr. Bob:

Attached is a copy of a Competitive Activity Report discussing the suspected case of lead poisoning previously reported to you by phone. We will keep you posted of any additional information we develop.

Sincerely yours,

L. R. Fleck
L. R. Fleck

LRF:ems
Attach.

KE 0012566

RECEIVED
 FEB 23 1956
 T.E.R.
 H.W.R.
 C.E.S.

Mr. M. A. Taylor

Date 2-18-56

COMPETITIVE ACTIVITY REPORT

RUSH — Don't Type — If It's Worth Reporting, Jot It Down and Mail It In NOW

Your source of information: Sun Oil Co. Customer: Yes

Do you think this information is reliable? Yes Address: Marcus Hook, Pa.

The following competitive activity is herewith reported: Ableader, [REDACTED], unloaded a TEL coc Sunday Jan. 22. On Monday 23 he reported sick, Sun's doctor examined him after he said he thought he had lead poison. C. Atkinson was put in the Chester Hospital and Dupont's doctor was called in. However it was decided the man did not have lead poisoning, but a virus cold.

On February 4, Sun discovered the discharge line educator was leaking, after discovering TEL in the weigh tank pit.

Dupont was called in and men in uniform wearing canister masks started removing the old line, installing a new line, and removing the contaminated area.

The new line has been installed, but they still are working on de-contamination. When the area is safe they will back fill and have the suction and discharge lines put in a grated trench instead of being buried under the concrete floor.

CUSTOMER'S REACTION TO THIS ACTIVITY:

Sun feels Dupont is taken too long on de-contamination.

SUGGESTED REBUTTAL TO THIS ACTIVITY: I offered, ^{Sun}our help, as an industry problem, but was refused.

COPY OF ANY MATERIAL

REFERRED TO ABOVE

() IS ATTACHED

() IS NOT ATTACHED

M. I. McCoolley
(Signed)

En.
(Region)

Proxel Hill, Pa.
(Headquarters)