

Characteristics and Method of Using		Cost Data			Customers
Type of Goods					
Color					
Luster					
Match for			100	100	
Kind of Reducer			100	100	
Amount of Reduction for					
Brushing					
Spraying	Pressure				
Dipping	Drip Time	Analysis			
Floccing	Drip Time	Pigment	64		
Tumbling		Vehicle	36		
Air dry to recoat			100		
To Sand or Rub		Pigment			
Bake Time	Temp.	350°	Leaded Zinc	51.6	
Rub with		Petroleum		27.2	
Polish with		Barium Sulfate		10.8	
Schedule		Magnesium Sulfate		10.4	
		Vehicle			
		Raw Linseed Oil		33.4	
		Bodied Linseed Oil		33.7	
		Leaded Primer		6.1	
		Mineral Spirits		25.8	
				100.0	

GLD059036