

Monsanto

FROM (NAME & LOCATION) E.P. Bailey - Texas City 3R-16

DATE April 9, 1984 cc. R. T. Harmann - 0-22
M. A. Riddle - 0-22
SUBJECT Hourly Safety Committee Meeting G. L. Tromblee - 0-10
REFERENCE File

TO : ✓James Baker - 56D ✓Beverly Dodson - 16D
✓Lloyd Caldwell - SS-22 ✓Donald Jordan - SS-13
✓Larry Bond - AB-1 ✓James Platt - SS-8
sick Charles Davis - SS-10 ✓Casey Yauger - 51D

Frank Corsaro was substituting for Don Jordan at the March Hourly Safety Committee meeting. Charles Davis and Beverly Dodson were absent.

R.L. Hammond was the guest speaker. He related the safety organization of the other plants he had worked to our safety organization at Texas City. R.L. was very commendable of the outstanding safety record we had last year and this year.

The SHAC chairman explained the enhancement to STOP where we all can see a summary of all the observations for identifying trends. This will be accomplished by simply filling out both the front and back side of the existing STOP card. A plea was made for everyone to participate in STOP by turning in cards. This is a sure way to keep our great safety trend going.

The Quarterly Safety Housekeeping Inspection will be coming up between April 2nd to April 13th. Several members of the HSC will be asked to help conduct the inspections.

Plans are being made to have articles in the plant newspaper about the different safety organizations in our plant. The Hourly Safety Committee will be coming up in one of the articles within the coming months.

Special emphasis was made to have all Hourly Safety Committee members at the next meeting for a picture of this committee for the plant newspaper article.

Old Business

People not leaving keys in cars parked in the plant was discussed. The PMSB has come up with the answer to the problem by allowing keys to be removed from vehicles in the plant only where they are parked in designated parking spaces. The key point to remember is whether or not the vehicle might need to be moved if an emergency occurs.

When barge M25 has to have the relief valve changed, pipefitters must stand on valve handle to change out. Could a better solution be found? This will be referred to Materials Handling and Maintenance for an answer. Follow-up is required to make sure a solution is found.

A hose on the docks was tested 1/17/84. It was understood that a 30 minute test was adequate. The next day the hose was used and it leaked. How long must a test be held to get an accurate test? Plant Engineering Technical Services investigated this problem and agrees that a thirty minute test is enough for any hose forty feet or less. More follow-up is required for finding out the details on the case in question.

New Business

Several places in the plant were observed by members of the Hourly Safety Committee that an emergency alarm cannot be heard. The Hourly Safety Committee Representatives need to meet with the Unit/Craft Safety Representatives and have them check for these areas in their work areas.

It was stated by the chairman of the Hourly Safety Committee that all of the Hourly Safety Committee Representatives should contact the safety representatives of the areas that they represent after our monthly meeting. This should be the minimum amount of contact. Feedback from the minutes of the Hourly Safety Committee should be discussed with them and any safety problems in their workplace also discussed.

Some bicycle repair problems with Hourly Safety Committee member's bicycles was discussed. Mark Riddle will follow up.

Our next meeting is scheduled at 1:30 PM on April 24th in the Personnel Conference Room.



Paul Bailey

Phenol tanks needed scaffold removed last Friday and carpenters went down to do it. The job went back with 5 men. Needed four men in the tank leaving 1 man for hold man. Contractors built the scaffold with eight people. We need to have an answer.

Welders were working during spill alarm in the plant because they couldn't hear the alarm. A new alarm will be added.

Disaster planning where do we stand? Hurricane season is coming and we need to be updating the disaster plan. Answer: The disaster plan is being updated. We will be having an emergency plant drill in April.

Paul Bailey

SC

12250

LAM013447

3/27/84

R.L. Hammond

- Dock 1 incident
- Past history - 4 plants
 - Unit/Craft Safety Reps.
 - SHAC
 - Contractor Safety - Good Safety Performance
 - STOP Program
- Plant Safety Performance

Alarm not heard at 44 - East side

Bikes
- Grips on handle bars - Baker
- Wheels - Platt

Attendance
- Dodson not attending

SC

12251

LAM013448