

INSPECTION REPORT

Inspection Date(s):	April 6, 2015		
Media:	UIC		
Regulatory Program(s)	Underground Injection Control		
Company Name:	Benson-Montin & Greer		
Facility Name:	NW/4 Section 19-T27N-R1E		
Facility Physical Location:	NW/4 Section 19-T27N-R1E		
(city, state, zip code)	Cuba, NM		
Mailing Address:	4900 College Blvd		
(city, state, zip code)	Farmington, NM 87402		
County/Parish:	Rio Arriba County		
Facility Contact	James Hornbeck	5053259974	
	N/A		
FRS Number:	N/A		
Identification/Permit Number:	NM9102		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Personnel participating in the inspection:			
Rick Davis	6EN-WR	EPA Inspector	918-605-1643
Ben Gonzales	Benson-Montin & Greer	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A
EPA Lead Inspector	Rickey Davis Digitally signed by Rickey Davis DN: cn=Rickey Davis, o=EPA, ou=6EN, email=davis.rickey@epa.gov, c=US Date: 2015.05.13 12:35:40 -05'00'		
Signature/Date			Rickey Davis
Supervisor Signature/Date	WILLIE LANE Digitally signed by WILLIE LANE DN: c=US, o=U.S. Government, ou=USEPA, ou=Staff, cn=WILLIE LANE, dnQualifier=0000007235 Date: 2015.05.13 13:07:16 -05'00'		
			Willie Lane Jr., Chief, Water Resources Section(6EN-WR)

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector Rick Davis visited the Benson-Montin & Greer oil production facility located in the NW/4 Section 19-T27N-R1E near Cuba, New Mexico on April 6, 2015. Ben Gonzales represented Benson-Montin & Greer during the inspection. The inspection was conducted by authority of the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

Well location

Section II - OBSERVATIONS

Active lease with well not injecting. Tubing at -5psi and annulus at 40psi positive pressure. Bled off and pressured annulus to 550psi with water. Increased to 565psi in 30 minutes.

Section III - AREAS OF CONCERN

There were no areas of concern noted.

Section IV - FOLLOW UP

No follow-up actions are required.

Section V - LIST OF APPENDICES

There are no attachments to this report.