

MD-3-A

PACKAGE TICKET

CODE K+618-12LOT 121133

PQ	NET WT/PKG.	NO. PKG.	PACK WT.	LOCATION
		<u>18</u>	<u>2464</u>	<u>39</u>

STUMP

TOTAL NET WT. 2464LUMP WT. 2440

PKG. N-CODE

PROD. SUBV. 11

DATE

11 124183

OPERATOR

389

1.55 +
1.34 +
1.60 +
1.29 +
1.42 +
1.40 +
1.45 +
1.53 +
1.33 +
1.41 +
1.46 +
1.46 +
1.57 +
1.43 +
1.38 +
1.39 +
1.50 +
0.13 +

018

24.64 ±

PRODUCT NAME: WATCHUNG RED Y

CG 32 CODE RT-618-D PKG

LOT L2K33

EST. WT. ~~2370~~ LBS.

NON-BLEEDING

DATE PRINTED: 11/04/82

PROCESSES

APPROVED BY:

RT-618-D (T)

EWK 12/08/81

COMTYP JOB NAME: 32RT618DPT

MAKING NOTES:

INSTRUCTIONS

= PRESSING =

RECORD

VAT	DATE	TIME	RELEASED BY	PRESS	NO. OF CAKES	PRESS WITHOUT	AGITATION	WASH TO 330 M MHOS	TEST AFTER 2 HOURS	LOAD ON 8 CARS	USE MN FREE EQUIPMENT. INSTRUCT MAKING AREA TO ADD 10% N-588-A HALF-WAY THRU PRESSING. CLEAN MAGNETIC SEPARATOR AFTER PRESSING	CLEANED BY	TIME CLEANED	SAMPLES	JAR	DELIVER TO	PRESSLOAD	STARTED	CAKES USED	WATER ON	HRS. WASHED	M MHOS	HRS. WASHED	M MHOS	HRS. WASHED	M MHOS	CAKE CONDITION	NO CARS LOADED	EXPLAIN LOSSES

= DRYING =

DRY 24 HOURS AT 180 F
USE MN FREE EQUIPMENT. USE PAPER LINERS IN L/P. HOLD ON TRACK 30 MIN BEFORE DUMPING PANS.

LUMP: - OK - WET - SALTS - CONTAMINATED

ADDITIONAL DRYING HOURS REQUIRED

SAMPLES
DELIVER TO

NO CARS PULLED
SAMPLED BY
RELEASED BY

NO DRUMS
LUMP WGT

= GRINDING =

MILL 2 LSP 1/8" RP SCREEN 1800 RPM
MAX. TEMP. 140 F
DO NOT GRIND OTHER ORGANICS IN IMMEDIATE AREA. USE MN FREE EQUIPMENT.
INERT MILL WITH CO2 WHEN GRINDING PER O.P.# O.F.0043

SCREEN RPM
MAX. TEMP. F

EXPLAIN LOSSES

DATE MIXED
SAMPLED BY
RELEASED BY

SAMPLE WITHOUT MIXING
SAMPLES 2 ENV.
DELIVER TO CTL

33
124
51

1.48 +
0.14 -
1.58 +
0.14 -
1.58 +
0.14 -
1.26 +
0.14 -
1.57 +
0.14 -
1.29 +
0.14 -
24.40 +
32.32 *

33
427
51

1.63 +
0.14 -
1.67 +
0.14 -
1.62 +
0.14 -
1.68 +
0.14 -
1.65 +
0.14 -
1.58 +
0.14 -
1.77 +
0.14 -
1.65 +
0.14 -
1.77 +
0.14 -
1.67 +
0.14 -
1.41 +
0.14 -
7.92 +
24.40 *