

SPECIAL FIRE SCIENCE TASK FORCE

VI Offices
65 Madison Avenue
Morristown, NJ

Tuesday
September 20, 1994
4:00 p.m.

I. REVIEW OF CODES AND STANDARDS ISSUES

- | | | |
|----|------------------------|--------------|
| A. | Toxicity | |
| | 1. ASTM | Bob Strength |
| | 2. NIST | Bob Strength |
| | 3. NFPA | Bob Strength |
| | 4. International | Bob Strength |
| B. | Corrosion | |
| | 1. ASTM | Bob Strength |
| | 2. International | Bob Strength |
| | 3. UL Task Force | Group |
| C. | Fire Modeling | |
| | 1. ASTM | Bob Strength |
| | 2. International | Bob Strength |
| D. | National Electric Code | Bob Strength |

II. CRITIQUE OF PERFORMANCE

- | | | |
|----|---|----------|
| A. | Past and Future Efforts | Bud Hall |
| B. | Budgetary Restraints | Bud Hall |
| C. | Future Direction/Decision On
UL Task Force Funding | Group |

R&S 144069