

MAY -U-81-21320

() YE-735-D (K)

FWP 04/08/81

DATE: _____ LOT _____

ESTIMATED WEIGHT: 4021#

COMTYP JOB NAME: 01YE735DMK

EQUIP MENT	NAME: MOLYBDATE ORANGE	WE LBS	N-CODE	ACCT LBS
PREP				
1	1 OBTAIN FOR S-34	315	4-A	315
	2 OBTAIN FOR S-24	42	108-A	42
	3 OBTAIN FOR S-38	105	3-A	105
	4 OBTAIN FOR S-40	58	32-D	58
	5 OBTAIN FOR S-42	168	15-A	168
	6 OBTAIN FOR S-44	47	3-A	47
	7 DISSOLVE IN 30 G WATER AT 100-120°F IN DRUM FOR S-48	17	765-A	17
	8 DISSOLVE IN 30 G WATER AT 100-120°F IN DRUM FOR S-52	60	994-A	60
355 2	9 WEIGH IN OPTR _____, MK <u>2</u> , <u>32.00%</u> OPTR _____, MK _____, _____%	<u>78</u>	28-D	<u>2520</u>
351 3	10 WEIGH IN OPTR _____, MK <u>24</u> , <u>38.18%</u> OPTR _____, MK _____, _____%	<u>3735</u>	10-D	<u>1407</u> <u>1426</u>
359 4	11 WEIGH IN OPTR _____, MK <u>48</u> , <u>38.15%</u> OPTR _____, MK _____, _____%	<u>592</u>	423-D	<u>252</u> <u>226</u>
SV 5	12 FLUSH DISTRIBUTOR LINES UNTIL WATER COMES OUT ALL JETS RECORD: _____ (OK)			
	13 RUN IN 40" (1992 G) WATER			
	14 RUN IN FROM V-354. REC: OPTR: <u>34</u> , MK <u>473</u> , <u>13250</u> <u>28.68%</u> , PH <u>2.7</u> (2.8-3.7), G/ML _____ (1.270-1.328). SEE SUPV IF NOT IN RANGE.		41-D	3800
	15 ADJ TO 3350 GAL AT 67-69°F. RECORD: <u>6.7</u> °F (67° IN V-240 & 246; 69° IN V-241, 242, 245)		57-A	
	16 STIR 5MIN. & RECORD: PH <u>3.6</u> (2.8-3.6)			
	17 IF NECESSARY, ADJ TO PH 3.8-3.9 ASSUME 32% & RECORD: PH <u>3.9</u> (3.8-3.9) ASSUME 50%		28-D 7-D	<u>1</u>
	NOTE: DILUTE N-7-D 10:1 WITH WATER BEFORE ADDING			
	18 RECORD: <u>1.118</u> G/ML (1.116-1.118)			
	NOTE: IF G/ML OUT OF LIMITS, FILL OUT CHECK LIST & ATTACH			
	19 STIR AT 67-69°F FOR S-30. TAKE 1 QT SAMPLE.			
358 6	20 RUN 2" (110 G) WATER INTO V-358			
	21 RUN V-359 INTO V-351			
	22 PUMP V-351 INTO V-358			
	23 TURN ON AGITATOR			
	24 SIFT IN N-108-A FROM S-2			
	25 ADJUST TO 68" (3216 G) AT 67-69°F RECORD: <u>6.9</u> °F			
	26 STIR 3 MIN. & RECORD: PH <u>9.5</u> (9.0-9.5)			
	27 IF NECESSARY, ADJ. TO PH 9.0-9.5 ASSUME 32% & RECORD: PH _____ ASSUME 50%		28-D 7-D	
	28 RECORD: G/ML <u>1.060</u> (1.059-1.060)			
	NOTE: G/ML OUT OF LIMITS FILL OUT CHECK LIST & ATTACH			
	29 STIR AT 67-69°F FOR S-30. TAKE 1 QT SAMPLE.			

USE
LBS