



RW
file: Asbestos

PLAINTIFF'S EXHIBIT

FD-1443

Inter Office

Personnel and
Organization Staff

September 6, 1978

E. Duda
Engine Materials

Subject: Gasket, Asbestos & Synthetic Rubber - Bonded One Side to
Steel Sheet, #ESE-M8G149-A, Steelpak I, VICTOCOR 170
(Dana Corporation, Victor Products Division)

Pursuant to your request for toxicological information relative to the safe use and handling of the subject material, we offer the following information based, in part, on information supplied to us by the vendor of the subject material.

This material contains bound asbestos fibers. Although normal use of the product should not present a problem of airborne asbestos, specific handling of the product at any given job site may vary and could cause small amounts of asbestos fiber to become airborne. If such a possibility exists with the handling and use of this material, Industrial Hygiene and Toxicology should be contacted to monitor such operations.

In addition, it is our opinion that this material requires no special labeling to comply with the Hazardous Materials Transportation Act.

L. M. Roslinski, Ph.D.
Industrial Toxicologist
Industrial Hygiene and
Toxicology Department

LMR/kb

cc: G. F. Bush
R. L. Wabeke ✓

8005 0725

SCF-FORD-1597

PRODUCED BY FORD