

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH ANNUAL 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	64	32		32		32		32			
LAB O.T.	16	8		8		8		8			
LAB S.O.T.	10	5		5		5		5			
LAB OTHER	16	8		8		8		8			
SHIFT SUPERVISOR	60	30		30		30		30			
O.S. VINYL BOARD	28	14		14		14		14			
O.S. EDC BOARD	26	13		13		13		13			
S.O.T. B-TRI BRD	30	15		15		15		15			
S.O.T. MAINT.											
O.T. TANKS	40	20		20		20		19	1 Denova	43.87	
O.T. SAMPLES	38	19		19		19		19			
DAY OPERATIONS	168	84		84		84		84			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100 PPM	G 100 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G 1.3 PPM		
OFFICE	64	32		32		26	6	25	7		
LAB O.T.	16	8		8		7	1	6	2		
LAB S.O.T.	10	5		5		4	1	5			
LAB OTHER	16	8		8		8		8			
SHIFT SUPERVISOR	60	30		30		29	1	28	2		
O.S. VINYL BOARD	28	14		14		12	2	12	2		
O.S. EDC BOARD	26	13		13		11	2	7	6		
S.O.T. B-TRI BRD	30	15		15		12	3	13	2		
S.O.T. MAINT.											
O.T. TANKS	40	20		20		17	3	15	5		
O.T. SAMPLES	38	19		19		16	3	18	1		
DAY OPERATIONS	168	84		84		78	6	73	11		

DO 135747
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH FIRST QUARTER 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	16	8		8		8		8			
LAB O.T.											
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	4	2		2		2		2			
SHIFT SUPERVISOR	14	7		7		7		7			
O.S. VINYL BOARD	4	2		2		2		2			
O.S. EDC BOARD	8	4		4		4		4			
S.O.T. B-TRI BRD	6	3		3		3		3			
S.O.T. MAINT.											
O.T. TANKS	10	5		5		5		4	1 Denova	43.87	
O.T. SAMPLES	12	6		6		6		6			
DAY OPERATIONS	48	24		24		24		24			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100 PPM	G 100 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-.3 PPM	G .3 PPM		
OFFICE	16	8		8		7	1 Rantz	2	8		
LAB O.T.											
LAB S.O.T.	2	1		1			1 Vallet	18	1		
LAB OTHER	4	2		2		2		2			
SHIFT SUPERVISOR	14	7		7		7		7			
O.S. VINYL BOARD	4	2		2		1	1 Dayries	22	1	1 Dayries .42	
O.S. EDC BOARD	8	4		4		2	Karriss .7 2 James .2			Karriss 1.03 James 1.28 4 Martinez .66 Phillips 1.78	
S.O.T. B-TRI BRD	6	3		3		2	1 Bolfer	27	2	1 J. Templett 3.66	
S.O.T. MAINT.											
O.T. TANKS	10	5		5		4	1 Miller	26	5		
O.T. SAMPLES	12	6		6		5	1 McCall	51	6		
DAY OPERATIONS	48	24		24		23	1 Dean .4	22	2 Hope	1.44 Albarado .88	

DO NOT WRITE
ON THESE
COMPUTER
TAPES

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH SECOND QTR. 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	18	9		9		9		9			
LAB O.T.	6	3		3		3		3			
LAB S.O.T.	4	2		2		2		2			
LAB OTHER	4	2		2		2		2			
SHIFT SUPERVISOR	12	6		6		6		6			
O.S. VINYL BOARD	8	4		4		4		4			
O.S. EDC BOARD	4	2		2		2		2			
S.O.T. B-TRI BRD	14	7		7		7		7			
S.O.T. MAINT.											
O.T. TANKS	14	7		7		7		7			
O.T. SAMPLES	10	5		5		5		5			
DAY OPERATIONS	32	16		16		16		16			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-10 PPM	G 10 PPM	0-15 PPM	G 15 PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G 1.3 PPM		
OFFICE	18	9		9		7	2 Junkin .42 2 Bourg .70	6	3 Junkin	.74; Bourg .73; Joseph 1.50	
LAB O.T.	6	3		3		3		3			
LAB S.O.T.	4	2		2		2		2			
LAB OTHER	4	2		2		2		2			
SHIFT SUPERVISOR	12	6		6		6		6			
O.S. VINYL BOARD	8	4		4		4		4			
O.S. EDC BOARD	4	2		2		2		1	1 Davis .56		
S.O.T. B-TRI BRD	14	7		7		5	2 Booth .76 2 Bailey .30	6	1 Vallet	1.50	
S.O.T. MAINT.											
O.T. TANKS	14	7		7		5	2 Lemoine .28 2 Albo .66	4	3 Lemoine	2.25; Albarado 2.66 Thomas 2.30	
O.T. SAMPLES	10	5		5		3	2 McCall .42 2 Bynum .39	4	1 McCall	1.03	
DAY OPERATIONS	32	16		16		14	2 McKines 2 Clyde .29	12	4 Bellel	2.26; McKines 3.02 Stafford 2.50; Stain 1.42	

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH THIRD QUARTER 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	14	7		7		7		7			
LAB O.T.	6	3		3		3		3			
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	4	2		2		2		2			
SHIFT SUPERVISOR	18	9		9		9		9			
O.S. VINYL BOARD	12	6		6		6		6			
O.S. EDC BOARD	10	5		5		5		5			
S.O.T. B-TRI BRD	6	3		3		3		3			
S.O.T. MAINT.											
O.T. TANKS	6	3		3		3		3			
O.T. SAMPLES	6	3		3		3		3			
DAY OPERATIONS	36	18		18		18		18			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100PPM	G 100 PPM	0-150PPM	G 150PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G 1.3 PPM		
OFFICE	14	7		7		7		7			
LAB O.T.	6	3		3		3		2	1 Denova	.36	
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	4	2		2		2		2			
SHIFT SUPERVISOR	18	9		9		9		9			
O.S. VINYL BOARD	12	6		6		6		6			
O.S. EDC BOARD	10	5		5		5		5			
S.O.T. B-TRI BRD	6	3		3		3		3			
S.O.T. MAINT.											
O.T. TANKS	6	3		3		3		2	1 McKinnis	.99	
O.T. SAMPLES	6	3		3		3		3			
DAY OPERATIONS	36	18		18		17	1 Hebert	16 15	3 Hebert	1.07, Wesley	.35
									St. Julien	.73	

DC 138750
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH FOURTH QUARTER 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	16	8		8		8		8			
LAB O.T.	4	2		2		2		2			
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	4	2		2		2		2			
SHIFT SUPERVISOR	16	8		8		8		8			
O.S. VINYL BOARD	4	2		2		2		2			
O.S. EDC BOARD	4	2		2		2		2			
S.O.T. B-TRI BRD	4	2		2		2		2			
S.O.T. MAINT.											
O.T. TANKS	10	5		5		5		5			
O.T. SAMPLES	10	5		5		5		5			
DAY OPERATIONS	52	26		26		26		26			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-10 PPM	G 10 PPM	0-15 PPM	G 15 PPM	0-1 PPM	G 1 PPM	0-.3 PPM	G .3 PPM		
OFFICE	16	8		8		5 Baker 3.60 Bentz 1.18 Bourg 3.67		4	4 Bourg	1.11, Junkin 4.24 1.01, Baker 3.55	
LAB O.T.	4	2		2		1 Denova .22		1	1 Denova	.87	
LAB S.O.T.	2	1		1				1			
LAB OTHER	4	2		2				2			
SHIFT SUPERVISOR	16	8		8		7 1 LeBlanc .56		2 2 LeBlanc		1.76, Carlin .70	
O.S. VINYL BOARD	4	2		2		1 1 Vallet .25		1	1 Vallet	.82	
O.S. EDC BOARD	4	2		2				1	1 Young	.31	
S.O.T. B-TRI BRD	4	2		2				2			
S.O.T. MAINT.											
O.T. TANKS	10	5		5				4	1 Brown	.70	
O.T. SAMPLES	10	5		5				5			
DAY OPERATIONS	52	26		26		24 Lemoine .32 2 Cox .20		24	2 Cox 3.5	5. Montgomery 1.05	

DO NOT REPRODUCE
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH JANUARY 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	8	4		4		4		4			
LAB O.T.											
LAB S.O.T.											
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	4	2		2		2		2			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD											
S.O.T. MAINT.											
O.T. TANKS	2	1		1		1		1			
O.T. SAMPLES	4	2		2		2		2			
DAY OPERATIONS	14	7		7		7		7			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100 PPM	G 100 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G 1.3 PPM		
OFFICE	8	4		4		4		4			
LAB O.T.											
LAB S.O.T.											
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	4	2		2		2		2			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD	2	1		1		1		1 Phillips	1.78		
S.O.T. B-TRI BRD											
S.O.T. MAINT.											
O.T. TANKS	2	1		1		1		1			
O.T. SAMPLES	4	2		2		2		2			
DAY OPERATIONS	14	7		7		7		6	1 Albarado	.88	

DO 136752
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH FEBRUARY 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	2	1		1		1		1			
LAB O.T.											
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	4	2		2		2		2			
O.S. VINYL BOARD											
O.S. EDC BOARD											
S.O.T. B-TRI BRD	2	1		1		1		1			
S.O.T. MAINT.											
O.T. TANKS	4	2		2		2		1	1 Denova	43.87	
O.T. SAMPLES	4	2		2		2		2			
DAY OPERATIONS	18	9		9		9		9			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100 PPM	G 100 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G 1.3 PPM		
OFFICE	2	1		1		1		1			
LAB O.T.											
LAB S.O.T.	2	1		1			1 Valley	1			
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	4	2		2		2		2			
O.S. VINYL BOARD											
O.S. EDC BOARD											
S.O.T. B-TRI BRD	2	1		1		1			1 J. Temple	3.66	
S.O.T. MAINT.											
O.T. TANKS	4	2		2		2		2			
O.T. SAMPLES	4	2		2		2		2			
DAY OPERATIONS	18	9		9		8	1 Dean	8	1 Hope	1.44	

DC 136750
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH MARCH 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	6	3		3		3		3			
LAB O.T.											
LAB S.O.T.											
LAB OTHER											
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD	6	3		3		3		3			
S.O.T. B-TRI BRD	4	2		2		2		2			
S.O.T. MAINT.											
O.T. TANKS	4	2		2		2		2			
O.T. SAMPLES	4	2		2		2		2			
DAY OPERATIONS	16	8		8		8		8			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100 PPM	G 100 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G .1 PPM	0-.3 PPM	G .3 PPM		
OFFICE	6	3		3		2	1 Rentz .32	3			
LAB O.T.											
LAB S.O.T.											
LAB OTHER											
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	2	1		1			1 Dayries .22		1 Dayries .42		
O.S. EDC BOARD	6	3		3		1	2 James .44 Karras .27		3 Karras .05, James 11.25, Martinez .66,		
S.O.T. B-TRI BRD	4	2		2		1	1 Bolfer .27	2			
S.O.T. MAINT.											
O.T. TANKS	4	2		2		1	1 Miller .20	2			
O.T. SAMPLES	4	2		2		1	1 McCall .51	2			
DAY OPERATIONS	16	8		8		8		8			
						70.8%	29.2%	83.3%	16.7%		

DO 138751
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH APRIL 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	6	3		3		3		3			
LAB O.T.	2	1		1		1		1			
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	4	2		2		2		2			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD											
S.O.T. B-TRI BRD	4	2		2		2		2			
S.O.T. MAINT.											
O.T. TANKS	6	3		3		3		3			
O.T. SAMPLES	2	1		1		1		1			
DAY OPERATIONS	8	4		4		4		4			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100 PPM	G 100 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-3 PPM	G 3 PPM		
OFFICE	6	3		3		3		3			
LAB O.T.	2	1		1		1		1			
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	4	2		2		2		2			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD											
S.O.T. B-TRI BRD	4	2		2		1	1 Booth .76	2			
S.O.T. MAINT.											
O.T. TANKS	6	3		3		1	2 Monica .21 2 Rusty .66	1	2 Monica .25 Albarado 2.66		
O.T. SAMPLES	2	1		1			1 McCall .20		1 McCall .03		
DAY OPERATIONS	8	4		4		3	1 McKines .4	12	2 Bellelo 2.26 McKines 3.02		
						73.7%	26.3%	73.7%	26.3%		

DO 138755
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH MAY 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	4	2		2		2		2			
LAB O.T.	2	1		1		1		1			
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD	6	3		3		3		3			
S.O.T. MAINT.											
O.T. TANKS	2	1		1		1		1			
O.T. SAMPLES	6	3		3		3		3			
DAY OPERATIONS	4	2		2		2		2			
JOB	NO.	TETRAS (1,1,1,2) 0-100 PPM G 100 PPM		EXCURSION 0-150 PPM G 150 PPM		TETRAS (1,1,2,2) 0-1 PPM G .1 PPM		EXCURSION 0-.3 PPM G .3 PPM			
OFFICE	4	2		2		2 Junkin .43		Bourg .70 2 Junkin		74; Bourg .73	
LAB O.T.	2	1		1		1		1			
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD	2	1		1		1		1 Davis .66			
S.O.T. B-TRI BRD	6	3		3		3		2	1 Vallet	7.50	
S.O.T. MAINT.											
O.T. TANKS	2	1		1		1		1			
O.T. SAMPLES	6	3		3		2	1 Bynum .39	3			
DAY OPERATIONS	4	2		2		2		2			

DO 138756
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH JUNE 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	8	4		4		4		4			
LAB O.T.	2	1		1		1		1			
LAB S.O.T.											
LAB OTHER											
SHIFT SUPERVISOR	2	1		1		1		1			
O.S. VINYL BOARD	4	2		2		2		2			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD	4	2		2		2		2			
S.O.T. MAINT.											
O.T. TANKS	6	3		3		3		3			
O.T. SAMPLES	2	1		1		1		1			
DAY OPERATIONS	20	10		10		10		10			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100 PPM	G 100 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G 1.3 PPM		
OFFICE	8	4		4		4		3	1 Joseph 1	50	
LAB O.T.	2	1		1		1		1			
LAB S.O.T.											
LAB OTHER											
SHIFT SUPERVISOR	2	1		1		1		1			
O.S. VINYL BOARD	4	2		2		2		2			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD	4	2		2		1	1 Bailey .30	2			
S.O.T. MAINT.											
O.T. TANKS	6	3		3		3		2	1 Thomas 2	30	
O.T. SAMPLES	2	1		1		1		1			
DAY OPERATIONS	20	10		10		9	1 Stafford .29 ppm	8	2 Stafford	2.50; Stain 1.42	

DO 138757
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH JULY 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	4	2		2		2		2			
LAB O.T.	2	1		1		1		1			
LAB S.O.T.											
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	6	3		3		3		3			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD	2	1		1		1		1			
S.O.T. MAINT.											
O.T. TANKS	4	2		2		2		2			
O.T. SAMPLES	2	1		1		1		1			
DAY OPERATIONS	10	5		5		5		5			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100 PPM	G 100 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G 1.3 PPM		
OFFICE	4	2		2		2		2			
LAB O.T.	2	1		1		1		1			
LAB S.O.T.											
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	6	3		3		3		3			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD	2	1		1		1		1			
S.O.T. MAINT.											
O.T. TANKS	4	2		2		2		1	1 McKine	.99	
O.T. SAMPLES	2	1		1		1		1			
DAY OPERATIONS	10	5		5		4	1 Hebert	4	1 Hebert	1.07	

DO NOT REPRODUCE
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH AUGUST 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	2	1		1		1		1			
LAB O.T.	2	1		1		1		1			
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD	2	1		1		1		1			
S.O.T. MAINT.											
O.T. TANKS											
O.T. SAMPLES											
DAY OPERATIONS	6	3		3		3		3			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-10 PPM	G 10 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G 1.3 PPM		
OFFICE	2	1		1		1		1			
LAB O.T.	2	1		1		1		1			
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD	2	1		1		1		1			
S.O.T. MAINT.											
O.T. TANKS											
O.T. SAMPLES											
DAY OPERATIONS	6	3		3		3		3			

DO 106756
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH SEPTEMBER 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	8	4		4		4		4			
LAB O.T.	2	1		1		1		1			
LAB S.O.T.											
LAB OTHER											
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	4	2		2		2		2			
O.S. EDC BOARD	6	3		3		3		3			
S.O.T. B-TRI BRD	2	1		1		1		1			
S.O.T. MAINT.											
O.T. TANKS	2	1		1		1		1			
O.T. SAMPLES	4	2		2		2		2			
DAY OPERATIONS	20	10		10		10		10			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100 PPM	G 100 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G .3 PPM		
OFFICE	8	4		4		4		4			
LAB O.T.	2	1		1		1		1	.36	Denova	
LAB S.O.T.											
LAB OTHER											
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	4	2		2		2		2			
O.S. EDC BOARD	6	3		3		3		3			
S.O.T. B-TRI BRD	2	1		1		1		1			
S.O.T. MAINT.											
O.T. TANKS	2	1		1		1		1			
O.T. SAMPLES	4	2		2		2		2			
DAY OPERATIONS	20	10		10		10		8	2 St.	Julien .73; Wesley .35	

DO NOT WRITE
ON THESE CARDS

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH OCTOBER 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	10	5		5		5		5			
LAB O.T.	4	2		2		2		2			
LAB S.O.T.											
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD											
O.S. EDC BOARD											
S.O.T. B-TRI BRD	4	2		2		2		2			
S.O.T. MAINT.											
O.T. TANKS	4	2		2		2		2			
O.T. SAMPLES	6	3		3		3		3			
DAY OPERATIONS	18	9		9		9		9			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-150 PPM	G 150 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G 1.3 PPM		
OFFICE	10	5		5		3	2 Bourg .67 Baker .60	3	2 Bourg 1.01; Baker 3.55		
LAB O.T.	4	2		2		1	1 Denova .2	1	1 Denova .87		
LAB S.O.T.											
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD											
O.S. EDC BOARD											
S.O.T. B-TRI BRD	4	2		2		2		2			
S.O.T. MAINT.											
O.T. TANKS	4	2		2		2		1	1 Brown 70		
O.T. SAMPLES	6	3		3		3		3			
DAY OPERATIONS	18	9		9		7	2 Cox .20 Lemoine	8	1 Cox 3.75		

DO NOT
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH NOVEMBER 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	2	1		1		1		1			
LAB O.T.											
LAB S.O.T.	2	k		k		k		k			
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	6	3		3		3		3			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD											
S.O.T. MAINT.											
O.T. TANKS	4	2		2		2		2			
O.T. SAMPLES	2	1		1		1		1			
DAY OPERATIONS	8	4		4		4		4			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100PPM	G 100PPM	0-150PPM	G 150PPM	0-1PPM	G 1PPM	0-1.3PPM	G 1.3 PPM		
OFFICE	2	1		1		1		1 Junkin	.24		
LAB O.T.											
LAB S.O.T.	2	1		1		1		1			
LAB OTHER	2	1		1		1		1			
SHIFT SUPERVISOR	6	3		3		2	1 LeBlanc	5 1	2 LeBlanc	1.76; Carlin	.70
O.S. VINYL BOARD	2	1		1			1 Vallet .25		1 Vallet	.82	
O.S. EDC BOARD	2	1		1		1			1 Young	1	.51
S.O.T. B-TRI BRD											
S.O.T. MAINT.											
O.T. TANKS	4	2		2		2		2			
O.T. SAMPLES	2	1		1		1		1			
DAY OPERATIONS	8	4		4		4		4			

DO 138762
CONFIDENTIAL

VINYL CHLORIDE PLANT PERSONNEL EXPOSURE STATUS REPORT
EDC - BETA-TRI - TETRAS - NOISE

MONTH DECEMBER 1979

JOB	NO.	EDC 8 HOUR TWA		EXCURSION		B-TRI 8 HOUR TWA		EXCURSION		NOISE EXPOSURE	
		0-50 PPM	G 50 PPM	0-75 PPM	G 75 PPM	0-10 PPM	G 10 PPM	0-20 PPM	G 20 PPM	LOW	HIGH
OFFICE	4	2		2		2		2			
LAB O.T.											
LAB S.O.T.											
LAB OTHER											
SHIFT SUPERVISOR	4	2		2		2		2			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD											
S.O.T. MAINT.											
O.T. TANKS	2	1		1		1		1			
O.T. SAMPLES	2	1		1		1		1			
DAY OPERATIONS	26	13		13		13		13			
JOB	NO.	TETRAS (1,1,1,2)		EXCURSION		TETRAS (1,1,2,2)		EXCURSION			
		0-100 PPM	G 100 PPM	0-150 PPM	G 150 PPM	0-1 PPM	G 1 PPM	0-1.3 PPM	G 1.3 PPM		
OFFICE	4	2		2		1	1 Rentz .18	1	1 Rentz 1	11	
LAB O.T.											
LAB S.O.T.											
LAB OTHER											
SHIFT SUPERVISOR	4	2		2		2		2			
O.S. VINYL BOARD	2	1		1		1		1			
O.S. EDC BOARD	2	1		1		1		1			
S.O.T. B-TRI BRD											
S.O.T. MAINT.											
O.T. TANKS	2	1		1		1		1			
O.T. SAMPLES	2	1		1		1		1			
DAY OPERATIONS	26	13		13		13		12	1 Montgomery	1.05	

DC 138763
CONFIDENTIAL