

(Drislane - Purcell)

1 that's the way it was. Most of them served two years. It
2 may be some of these earlier didn't serve the full two years,
3 I don't know, '51, '52, '53, '49 through '51, that was the
4 general pattern. You would get reelected at that next June
5 meeting.

6 Q What were the qualifications to serve as president
7 of the FMSI?

8 A Had to be a delegate or alternate I believe from
9 one of the member companies.

10 Q Any other criteria?

11 A No, not that I know of.

12 Q You indicate that in 1955, you're referencing this
13 Bendix type servo brake was redesigned to using a fixed
14 anchor from the former adjustable anchor type. Do you see
15 that information?

16 A Yes, yes.

17 Q You mentioned then about manufacturing tolerances
18 with the fixed anchor brake, problems associated with that
19 caused many manufacturers to move to an eccentric or tapered
20 grind on the drum brake linings. Do you see that?

21 A Yes.

22 Q Do you know whether or not an eccentric grind on
23 the drum brake linings requires more arcing and grinding to