

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date:	01/12/2026	
Media Program:	Water (CWA)	
Regulatory Program:	Water (CWA) Brine Program (Oil & Gas Inspection)	
Company Name:	Pharr, Billy W (dba B Pharr Operating, LLC)	
Facility Name:	Kress City Warnock SWD #1 SWD	
Facility Physical Location:	Off Arkansas Highway 29 at 33.3331, -93.575468	
(city, state, zip code)	Lewisville, AR 71845	
Mailing address:	P.O. Box 130	
(city, state, zip code)	Emerson, AR, 71740	
County/Parish:	Lafayette County	
Facility Phone Number:	870-904-5573	
Facility Contact:	Billy Pharr	Owner/Operator
	bp@hydrooil.net	
FRS Number:	N/A	
Identification/Permit Number:	ARU002347	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Uma Lad (Lead)	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Kerri McCabe	EPA / Region 6 ECDW	Inspector / Enforcement Officer
EPA Lead Inspector Signature/Date		
	Uma Lad	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Uma Lad and Kerri McCabe arrived at the Pharr, Billy W (dba B Pharr Operating, LLC) / Kress City Warnock SWD #1 SWD, located off Arkansas Highway 29 at 33.3331, -93.575468, at 2:44 PM on 01/12/2026 for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection at the Pharr, Billy W (dba B Pharr Operating, LLC) / Kress City Warnock SWD #1 SWD, which consists of two (2) storage tanks, one (1) separator, and one (1) saltwater disposal (SWD) injection well. An additional two (2) storage tanks at the facility appeared to be “out of service” or “not in use.”

Section II – OBSERVATIONS

I observed the facility, associated signage, the SWD injection well, separator, storage tanks and secondary containment; see Appendix 1 (Photograph Log), Photo No. 1 through No. 5. For additional GPS location and photo metadata, see Appendix 1.

I observed two (2) storage tanks that appeared to be “out of service” or “not in use,” see Photo No. 5.

I observed a secondary containment discharge valve that was capped, see Photo No. 6. I observed another secondary containment discharge valve that was in the closed position but not capped, see Photo No. 7. I observed a flow path from the discharge valve that indicates that the operator discharges fluids from secondary containment, see Photo No. 8.

Section III – AREAS OF CONCERN

No closing conference was held due to no Pharr, Billy W / B Pharr Operating, LLC staff present during the inspection. Areas of concern at the time of the inspection are:

- Tanks that appeared “out of service” or “not in use.”
- The uncapped secondary containment discharge valve.

If the operator is attempting to permanently close the tanks, then 40 CFR §112.2 of the Spill Prevention Control and Countermeasure (SPCC) rule requires that:

- “(1) all liquid and sludge have been removed from each container and connecting line; and
- (2) all connecting lines and piping have been disconnected from the container and blanked off, all valves (except ventilation valves) have been closed and locked, and
- (3) conspicuous signs have been posted on each container stating that it is a permanently closed container and noting the date of closure.”

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure areas of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log – 8 photos taken 01/12/2026.

Appendix 1

Photograph Log

8 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Facility/Location:		Pharr, Billy W (dba B Pharr Operating, LLC) / Kress City Warnock SWD #1 SWD off Arkansas Highway 29 at 33.3331, -93.575468					
City:	Lewisville	County:	Lafayette County	State:	AR	Direction:	NE
Filename:	R0011206.JPG	Photo Date:		01/12/2026		Time:	16:44:48
Photographer:	Uma Lad			Witness Name:		Kerri McCabe	



Description:	This photo was taken facing northeast and shows the facility sign.		
Latitude:	33°19'59.16" N	Longitude:	93°34'31.686" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Facility/Location:		Pharr, Billy W (dba B Pharr Operating, LLC) / Kress City Warnock SWD #1 SWD off Arkansas Highway 29 at 33.3331, -93.575468					
City:	Lewisville	County:	Lafayette County	State:	AR	Direction:	SE
Filename:	R0011207.JPG	Photo Date:		01/12/2026		Time:	16:50:19
Photographer:	Uma Lad			Witness Name:		Kerri McCabe	



Description:	This photo was taken facing southeast and shows the tank battery and injection well.		
Latitude:	33°19'58.95" N	Longitude:	93°34'31.428" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

PHOTO HERE

Facility/Location:		Pharr, Billy W (dba B Pharr Operating, LLC) / Kress City Warnock SWD #1 SWD off Arkansas Highway 29 at 33.3331, -93.575468					
City:	Lewisville	County:	Lafayette County	State:	AR	Direction:	WNW
Filename:	R0011214.JPG	Photo Date:		01/12/2026		Time:	16:52:36
Photographer:	Uma Lad			Witness Name:		Kerri McCabe	



Description:	This photo was taken facing west-northwest and shows another view of the tank battery and injection well.		
Latitude:	33°19'58.266" N	Longitude:	93°34'30.402" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Facility/Location:		Pharr, Billy W (dba B Pharr Operating, LLC) / Kress City Warnock SWD #1 SWD off Arkansas Highway 29 at 33.3331, -93.575468					
City:	Lewisville	County:	Lafayette County	State:	AR	Direction:	SSW
Filename:	R0011208.JPG	Photo Date:	01/12/2026		Time:	16:50:45	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe	



Description:	This photo was taken facing south-southwest and shows a separator at the facility.		
Latitude:	33°19'58.53" N	Longitude:	93°34'31.602" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Facility/Location:		Pharr, Billy W (dba B Pharr Operating, LLC) / Kress City Warnock SWD #1 SWD off Arkansas Highway 29 at 33.3331, -93.575468					
City:	Lewisville	County:	Lafayette County	State:	AR	Direction:	WSW
Filename:	R0011222.JPG	Photo Date:	01/12/2026		Time:	16:56:12	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe	



Description:	This photo was taken facing west-southwest and shows tanks that appear to be "out of service" or "not in use."		
Latitude:	33°19'58.338" N	Longitude:	93°34'32.286" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 6

Facility/Location:		Pharr, Billy W (dba B Pharr Operating, LLC) / Kress City Warnock SWD #1 SWD off Arkansas Highway 29 at 33.3331, -93.575468					
City:	Lewisville	County:	Lafayette County	State:	AR	Direction:	NE
Filename:	R0011211.JPG	Photo Date:	01/12/2026	Time:	16:53:41		
Photographer:	Uma Lad			Witness Name:	Kerri McCabe		



Description:	This photo was taken facing northeast and shows a capped secondary containment discharge valve.		
Latitude:	33°19'59.16" N	Longitude:	93°34'31.098" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 7

Facility/Location:		Pharr, Billy W (dba B Pharr Operating, LLC) / Kress City Warnock SWD #1 SWD off Arkansas Highway 29 at 33.3331, -93.575468					
City:	Lewisville	County:	Lafayette County	State:	AR	Direction:	WNW
Filename:	R0011212.JPG	Photo Date:	01/12/2026	Time:	16:51:24		
Photographer:	Uma Lad			Witness Name:			



Description:	This photo was taken facing west-northwest and shows a secondary containment drainage valve in the closed position but did not have a cap.		
Latitude:	33°19'57.948" N	Longitude:	93°34'31.284" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 8

Facility/Location:		Pharr, Billy W (dba B Pharr Operating, LLC) / Kress City Warnock SWD #1 SWD off Arkansas Highway 29 at 33.3331, -93.575468					
City:	Lewisville	County:	Lafayette County	State:	AR	Direction:	NE
Filename:	R0011213.JPG	Photo Date:	01/12/2026	Time:	16:51:33		
Photographer:	Uma Lad			Witness Name:	Kerri McCabe		



Description:	This photo was taken facing northeast and shows a flow path from the secondary containment discharge valve that was closed but did not have a cap.		
Latitude:	33°19'57.924" N	Longitude:	93°34'31.218" W