



INSPECTION REPORT

Facility Inspected Hensley CPA, LLC
98 River Street
Ellijay, Georgia 30540

Inspection Date: July 19, 2022

Facility Programmatic ID 3601452251

Inspection Type Clean Air Act (CAA)
National Emission Standards for Hazardous Air Pollutants (NESHAP) - Asbestos

Inspectors Tony Spann (Lead)
Pamela Storm

Introduction

An inspection pursuant to Section 114 of the CAA was conducted on July 19, 2022, at Hensley CPA, LLC located at 98 River Street in Ellijay, Georgia 30540 (the facility). The unannounced inspection was conducted by Tony Spann and Pamela Storm of EPA Region 4.

Building permit # 726 was issued on September 22, 2021, by the City of Ellijay for the demolition activity at the facility. The inspectors obtained information regarding this permit from the City of Ellijay on July 19, 2022, prior to this inspection. The purpose of the inspection was to determine compliance with the CAA NESHAP Asbestos Standard and the regulations promulgated at 40 C.F.R. Part 61, Subpart M, for the demolition activity conducted pursuant to this permit.

The EPA Region 4 CAA NESHAP asbestos program targets facilities for inspection located in the State of Georgia based on tips/complaints; permits issued on a local level; and demolition and/or renovation/abatement notices sent to the State. This inspection was conducted based on the previously mentioned permit.

Facility Information

The facility is Hensley CPA, LLC in which the demolition activity was performed.

Inspection

During the inspection, Mr. Joseph C. Hensley, the owner of the facility, explained to the inspectors that the wood deck located at the back of the facility was demolished and a new deck was rebuilt in its place. The demolition activity at the facility had been completed at the time of this inspection. No evidence of ongoing renovation or demolition activities were observed by the inspectors.

Conclusion

The inspectors will follow up with the contractor(s) and/or owner(s)/operator(s) listed on the building permit as deemed appropriate, to obtain information and necessary paperwork related to this demolition activity. This information will include, but not necessarily be limited to, copies of asbestos inspection reports and demolition notifications for the facility.

Report Approval

This inspection report was written by:

Spann, Tony Digitally signed by Spann, Tony
Date: 2022.09.14 13:05:02
-04'00'

Tony Spann, Inspector

This inspection report was approved by:

JASON DRESSLER Digitally signed by JASON
DRESSLER
Date: 2022.09.14 13:56:20 -04'00'

Jason Dressler, Chief
North Air Enforcement Section