

US POSTAL SERVICE CHELSEA VMF CLEAN WATER ACT PHOTOGRAPH LOG

*ALL PHOTOGRAPHS WERE TAKEN BY MICHAEL PRESCOTT USING A HEWLETT
PACKARD PHOTOSMART M547*

*PLEASE NOTE THAT DUE TO AN ERROR IN SETTING THE TIME ON THE
CAMERA, THE DATE AND TIME STAMPS ON THE PHOTOS ARE 36 HOURS
EARLIER THAN WHEN THE PHOTOS WERE TAKEN.*

DATE TAKEN: 11/15/22

PHOTO #: 1

COMMENTS: A 330-gallon
aboveground storage tank (AST) for
new oil next to a trench drain
connected to an oil water separator
and the sanitary sewer.

SITE LOCATION: Maintenance bay inside VMF Building




US POSTAL SERVICE CHELSEA VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/15/22

PHOTO #: 2

COMMENTS: Excavated area in floor exposing sanitary sewer pipes.

SITE LOCATION: Old car wash bay inside VMF Building



DATE TAKEN: 11/15/22

PHOTO #: 3

COMMENTS: Trench drain outside VMF building connected to storm sewer.

SITE LOCATION: Paved area in front of the VMF



US POSTAL SERVICE CHELSEA VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/15/22

PHOTO #: 4

COMMENTS: View of three ASTs and HAZMAT locker with peeling paint and rust due to the corrosive salt air.

SITE LOCATION: Paved area in back of the VMF



DATE TAKEN: 11/15/22

PHOTO #: 5

COMMENTS: View of HAZMAT locker and used antifreeze AST with peeling paint and rust looking towards the stormwater drain in the paved area.

SITE LOCATION: Paved area in back of the VMF



US POSTAL SERVICE CHELSEA VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/15/22

PHOTO #: 6

COMMENTS: View of heating oil AST with peeling paint and rust looking towards the stormwater drain in the paved area.

SITE LOCATION: Paved area in back of the VMF



DATE TAKEN: 11/15/22

PHOTO #: 7

COMMENTS: View of three ASTs with peeling paint and rust and the connecting piping into the building.

SITE LOCATION: Paved area in back of the VMF




US POSTAL SERVICE CHELSEA VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/15/22

PHOTO #: 8

COMMENTS: View of stormwater drain in back of the VMF near the ASTs with a slight oil sheen on the surface of the water.

SITE LOCATION: Paved area in back of the VMF



DATE TAKEN: 11/15/22

PHOTO #: 9

COMMENTS: View of stormwater drain in front of the VMF.

SITE LOCATION: Paved area in front of the VMF



US POSTAL SERVICE CHELSEA VMF CLEAN WATER ACT PHOTOGRAPH LOG

DATE TAKEN: 11/15/22

PHOTO #: 10

COMMENTS: Stormwater drain in paved area near the adjacent USPS mailing facility with rubber bands all around the drain.

SITE LOCATION: Paved area near adjacent USPS mailing facility

